

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED
MAY 08 2014
NMOCD ARTESIA

Release Notification and Corrective Action

nHMP1413429654
OPERATOR Initial Report Final Report
 Name of Company **Devon Energy** *6137* Contact **Tracy Kidd**
 Address **PO Box 250 Artesia, NM 88211** Telephone No. **575.513.0628**
 Facility Name **Cotton Draw Unit 65 SWD** Facility Type **Salt Water Disposal**

Surface Owner **Federal** Mineral Owner **State** API No. **30-015-10843**

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	2	25S	31E	1980	N	1980	E	Eddy

Latitude: 32.161085918 **Longitude:** -103.746039442

NATURE OF RELEASE

Type of Release Spill Produced Water	Volume of Release 255 BBLs	Volume Recovered 250 BBLs
Source of Release Produced water line	Date and Hour of Occurrence May 5, 2014 7:00 AM	Date and Hour of Discovery May 5, 2014 7:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Joah Weidemann; Devon Energy Assistant Production Foreman	
By Whom? David Medlock with RW Trucking	Date and Hour 7:00 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
The leak was in the produced water line coming from the Cotton Draw Unit 76 location to the Cotton Draw Unit 65 SWD. The check valve on the produced water header was bad. The line was isolated to determine the exact cause of the problem and the well was shut in. Once it was determined what the issue was the leaking area was dug up and repairs were made. The line had a hole in it as a result of corrosion.

Describe Area Affected and Cleanup Action Taken.*
The produced water leak was contained within the earthen berm surrounding the location. On May 5 a vacuum truck recovered 250 BBLs of the 255 BBLs spilled. The area where the spill occurred was back dragged. Soil samples will be taken to determine if remediation is needed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Sandra Farley</i>	OIL CONSERVATION DIVISION	
Printed Name: Sandra Farley	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: <i>5/14/14</i>	Expiration Date: <i>NA</i>
E-mail Address: Sandy.Farley@dvn.com	Conditions of Approval: Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION PROPOSAL NO LATER THAN:	Attached <input type="checkbox"/>
Date: May 6, 2014 Phone: 575.746.5587	<i>6/19/14</i>	

* Attach Additional Sheets If Necessary

2PP-2300

Bratcher, Mike, EMNRD

From: Farley, Sandy <Sandy.Farley@dvn.com>
Sent: Tuesday, May 06, 2014 1:45 PM
To: Bratcher, Mike, EMNRD; Jeff Robertson (jlr Robertson@blm.gov)
Cc: Kidd, Tracy; Weidemann, Joah
Subject: Cotton Draw Unit 65 SWD PW Spill 5.5.14
Attachments: CDU 65 SWD Initial C141.doc; CDU 65 255 BBLs Spill 5.5.14 2of3.PNG; CDU 65 255 BBLs Spill 5.5.14 3of3.PNG; CDU 65 255 BBLs Spill 5.5.14 1of3.PNG

Good afternoon,

Attached is the initial C141 and photos for the 255 BBLs PW Spill that occurred at the Cotton Draw Unit 65 SWD on May 5, 2014. Hard copies have been mailed to your office.

Please let me know if I can be of any further assistance.

Have a wonderful rest of your week

Sandy Farley

**Field Admin Support
Production**

Devon Energy Corporation


Artesia, New Mexico

6488 Seven Rivers Highway

Sandy.Farley@dvn.com

575 746 3587 (office)


devon



Devon Cotton Draw Ut 65 SWD
DOR 5/5/14


Devon Photo

Seven Giffordburn Ut 65 SW
DDE 5/5/14



Seven Photo

Dever Cotton Annex W 6 SWD
2012 5/31/14



Dever-Flt