

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

HOBBS OCD
State of New Mexico
Energy Minerals and Natural Resources
AUG 27 2014
Oil Conservation Division
1220 South St. Francis Dr.
RECEIVED Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company: Linn Operating	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Mescalero Ridge Unit 35 Battery (MRU #24)	Facility Type: Battery (Oil)

Surface Owner: Federal	Mineral Owner:	API No.: (closest well) 3002533661
------------------------	----------------	------------------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	35	19S	34E	2620	North	1300	East	Lea

Latitude: 32.6169119406597 Longitude: -103.526687241183

NATURE OF RELEASE

Type of Release: Oil / Produced Water	Volume of Release: 4 bbls / 1 bbl	Volume Recovered: 3 bbls / 0
Source of Release: Water Dump valve	Date and Hour of Occurrence: 12/11/13	Date and Hour of Discovery: 12/11/2013 0900
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM Geoffrey Leking-NM OCD	
By Whom? Brian Wall	Date and Hour 12/12/2013 0837	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: Water Dump on heater treater didn't dump water because the diafram had hole in it and filled the dump up with water and then heater filled up with water and dumped water and oil into oil production tank and over flowed the tank and did not equalize into other tank because other oil tank was full waiting for loads to be hauled.

Describe Area Affected and Cleanup Action Taken.* : Picked up fluid with vacuum truck. Will have ETech give an assessment. Just oil on surface. May try and wash area.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Approved by District Supervisor: 	
Title: Construction Foreman II	Approval Date: 8-27-14	Expiration Date: 10-28-14
E-mail Address: bwall@linenergy.com Date: 12/12/13 Phone: 806-367-0645	Conditions of Approval: Site Specific Request	Attached <input type="checkbox"/> IRP- 3276

* Attach Additional Sheets If Necessary

Delimited remediate area on
an NMOCD guide. Submit
Final C-141 by 10-28-14
Ogrod 269324
W1019 23 935780
P 7019 23 935911