

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**HOBSOCD**

Form C-141  
Revised August 8, 2011

Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

**RECEIVED**

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company	Oxy Permian Ltd.	Contact	Chancey Summers
Address	1017 W. Stanolind Rd, Hobbs, NM 88240	Telephone No.	(575) 397-8216
Facility Name	MLMU #71 CTB	Facility Type	Battery

Surface Owner	Kelly Myers	Mineral Owner		API No.	30-025-10901 (nearest well)
---------------	-------------	---------------	--	---------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	31	23S	37E					Lea

Latitude N 32.26219° Longitude W 103.2074°

**NATURE OF RELEASE**


Type of Release	Produced water	Volume of Release	100 bbls	Volume Recovered	50 bbls
Source of Release	1" stainless steel injection line caused by stress/fatigue at remote header	Date and Hour of Occurrence	04/08/2014	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking-NMOCD, Jennifer Van Curen-BLM		
By Whom?	Jennifer Gilkey	Date and Hour	04/09/2014 @ 5:24 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
Stress on a 1" stainless steel injection line at a remote header caused a leak of 100 bbls of produced water to spill onto the ground. A vacuum truck recovered 50 bbls of produced water and the line was repaired or replaced.

Describe Area Affected and Cleanup Action Taken.\*  
The affected area is approximately 8' x 650' on and off location. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Chancey Summers	Approved by Environmental Specialist:	
Title:	HES Coordinator	Approval Date:	9-22-14
E-mail Address:	Chancey_Summers@oxy.com	Expiration Date:	11-22-14
Date:	4-15-14	Conditions of Approval:	Site Sample report
Phone:	(575) 397-8216	Attached	<input type="checkbox"/>

\* Attach Additional Sheets If Necessary

*Delivered & returned over as per NMOCD guidelines. Submit final C-141 by 11-22-14.*

1AP-3336  
ogrid 192463  
n701426 537125  
p701426 537286

SEP 22 2014