

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NOV 11 2014

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB14310492LPL

OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company <i>LRE Operating, LLC</i>		Contact <i>Michael Barrett</i>	
Address <i>1111 Bagby St. Ste. 4600, Houston, TX 77002</i>		Telephone No. <i>575-623-8424</i>	
Facility Name <i>Kersey St. # 8</i>		Facility Type <i>Flowline</i>	
Surface Owner <i>Concho</i>		Mineral Owner <i>State</i>	API No. <i>30-015-42163</i>

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	32	17S	28E	1650	FSL	330	FEL	Eddy

Latitude 32.786646 Longitude -104.190679

NATURE OF RELEASE

Type of Release <i>Produced Water</i>	Volume of Release <i>32bbls</i>	Volume Recovered <i>15bbls</i>
Source of Release <i>3" Polyline Split</i>	Date and Hour of Occurrence <i>A/M 11-9-14</i>	Date and Hour of Discovery <i>11/9/2014 8:00 A/M</i>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, To Whom? <i>NMOCD - Mike Bratcher / Heather P.</i>	
By Whom? <i>Sheldon Hitchcock / Talon/LPE</i>	Date and Hour <i>11/11/14 @ 9:44am</i>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A flowline leak caused the release of 32bbls of produced water. The flowline was repaired and put back into service. Talon/LPE mobilized personnel to conduct an initial site assessment and to perform soil sampling within the impacted area. Upon receipt of laboratory results from the soil sampling activities a remediation work plan will be generated and submitted to the OCD

Describe Area Affected and Cleanup Action Taken.*

A flowline leak caused the release of 32bbls of produced water. A vacuum truck was immediately dispatched to begin recovering fluid. 15bbls of fluid were recovered. The fluid flowed from the release point south across the pasture for approximately 339'. Remedial activities will commence upon regulatory approval of a work plan.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Michael Barrett</i>	OIL CONSERVATION DIVISION	
Printed Name: Michael Barrett	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Production Supervisor	Approval Date: <i>11/12/14</i>	Expiration Date: <i>NA</i>
E-mail Address: mbarrett@timerockresources.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11-10-14	Phone: 575-628-424	

* Attach Additional Sheets If Necessary

2BP-2594

Patterson, Heather, EMNRD

From: Sheldon Hitchcock <slhitchcock@talonlpe.com>
Sent: Tuesday, November 11, 2014 9:44 AM
To: Bratcher, Mike, EMNRD
Cc: Patterson, Heather, EMNRD
Subject: LRE Operating, LLC (Lime Rock): Kersey St. #8 30-015-42163
Attachments: 20141111093543068.pdf

Mike,

Lime Rock had a flowline leak at the Kersey St. #8 (C-141 attached). They lost 32bbls of PW in the pasture (recovered 15bbls). I took samples yesterday, we will follow up with a work plan when we get lab data back. Please let me know if you have any questions or concerns. Thank you.

Respectfully,

Sheldon L. Hitchcock
Project Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
Phone: (575) 746-8768
Cell: (575) 689-5198
Fax: (575) 746-8905
Email: slhitchcock@talonlpe.com
Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist
Staples Foundation for Learning Hall of Fame Recipient: 2010
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the system manager. This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited.