

FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, B. Biehl, RL Gawlik, JR Smitherman, SF Johnson, FD Schoch, G Fletcher, J Fuqua, A Ruth, A Thompson, B Blevins, K Bright

DATE: February 2, 2015

LOCATION OF SPILL SITE: PLU PB 1 Federal 1 #1H (API 30-015-37030)

UL O-1-26S-30E Eddy co.

GPS COORDINATES (Lat & Long): 32.065962 -103.832944

ESTIMATED VOLUMES (Oil & Water Separately):

*If BBLs Recovered are not available at time of Initial Report: Send in Follow-up report when numbers are known

Volume spilled:		BBLs Spilled	*BBLs Recovered	Net Spilled		BBLs Spilled	*BBLs Recovered	Net Spilled
On ground /or earth berm -	Oil:			0	Water:	6	0	6
Contained in impervious liner -	Oil:	5	5	0	Water:	20	20	0
	Total:	5	5	0	Water:	26	20	6

DESCRIPTION (What happened?):

Water leg on heater treater failed releasing fluid into containment and heater treater

SPILL RESPONSE (How was the spill cleaned up?):

Vacuum truck recovered fluid in containment

PICTURE ATTACHMENT:

