

NM OIL CONSERVATION
ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

MAR 17 2015

Form C-141
Revised August 8, 2011

RECEIVED to appropriate District Office in accordance with 19.15.29 NMAC.

14B1507654570 Release Notification and Corrective Action

14B1507654823

OPERATOR

Initial Report Final Report

Name of Company	DCP Midstream, LP	Contact	Jon Bebbington
Address	10 Desta Drive, Suite 400 West	Telephone No.	432-620-4207; 432-413-3601
Facility Name	W-1-3-1-1 & W-1-3-1 Gas Gathering Pipeline	Facility Type	Natural Gas Gathering Pipeline
Surface Owner	BLM	Mineral Owner	
		API No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	14	19S	31E					EDDY

Latitude N32.67 Longitude W-103.

NATURE OF RELEASE

Type of Release: Raw Natural Gas, Condensate	Volume of Release 8 bbl	Volume Recovered 0 bbl
Source of Release W-1-3-1-1 & W-1-3-1 Gas Pipeline	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 1500 3-13-2015
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N / A		
Describe Cause of Problem and Remedial Action Taken.* This 6 inch steel line ruptured in several locations within a 100 yard by 100 yard area with two locations being the largest with a combined area of 2000 SF. Approx 8 bbls of condensate spilled from these areas combined. Latitude: 32.661104 Latitude: 32.661975 Longitude: -103.841880 Longitude: -103.841166 DCP will excavate and repair the damaged sections and the excavations left open until remedial action can occur.		
Describe Area Affected and Cleanup Action Taken.* Five locations of rupture were identified, two of which are much larger than the others all totaling about 2000 SF of surface area impacted by spilled condensate. A cleanup plan will be submitted for BLM and OCD Approval. The excavation from the repairs will be left open until remediation can be completed.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>Jon D. Bebbington</i>		OIL CONSERVATION DIVISION
Printed Name: Jon D. Bebbington	Approved by Environmental Specialist: Signed By: <i>[Signature]</i>	
Title: Princ. Environmental Engineer	Approval Date: 3/17/15	Expiration Date: N/A
E-mail Address: jdbebbington@dcpmidstream.com	Conditions of Approval:	Attached <input type="checkbox"/>

Remediation per O.C.D. Rules & Guidelines

Date: 3-17-2015	Phone: 432-620-4207	SUBMIT REMEDIATION PROPOSAL NO	2RP-2890
		LATER THAN: 4/17/15	

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Bebbington, Jon D <JDBebbington@dcpmidstream.com>
Sent: Tuesday, March 17, 2015 11:44 AM
To: Randal Pair; Bratcher, Mike, EMNRD
Cc: Michael, Kelley R; Owens, Mark R; Brister, Shane W; Ortega, Russell G
Subject: DCP W-1-3-1-1 Line Release
Attachments: DCP W-1-3-1-1 & W-1-3-1 Line 3-13-2015 C141.pdf

DCP's 6 inch steel line ruptured in several locations within a 100 yard by 100 yard area with two locations being the largest with a combined area of 2000 SF. Approx 8 bbls of condensate spilled from these areas combined. The two largest areas are located as follows:

Latitude: 32.661104 Latitude: 32.661975
Longitude: -103.841880 Longitude: -103.841166

DCP will excavate and repair the damaged sections and the excavations left open until remedial action can occur.