

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

nJMW1307241610


OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company: Devon Energy Production LP <i>6137</i>		Contact: Roy White	
Address: P.O. Box 250 Artesia, N.M. 88211		Telephone No. (575) 513-1741	
Facility Name: Turkey Town # 1		Facility Type: Gas Well # 30-015-24228	
Surface Owner	Mineral Owner	Lease No.	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	23	18S	28E	660	South	1980	West	Eddy

NATURE OF RELEASE

Type of Release: Oil/Produced Water	Volume of Release: 94 bbls oil/12 bbls produced water	Volume Recovered: 0 bbls recovered
Source of Release: Broken load line valve	Date and Hour of Occurrence: 1/17/13, 5:00 PM	Date and Hour of Discovery: 1/17/13, 5:00 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Rudy Zuniga, Assistant Foremen, Devon Energy	
By Whom? Brooke Owens, Lease Operator	Date and Hour: 1/17/13, 5:00 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.*
At the Turkey Town # 1 location a load line valve broke causing 94 bbls of oil and 12 bbls of produced water to release onto the ground. The Lease Operator who discovered the spill contacted an environmental cleanup company to remediate soil.

Describe Area Affected and Cleanup Action Taken.*
The spill occurred at the Turkey Town #1 location. The Lease Operator who discovered the broken load line valve contacted an environmental cleanup company to remediate soil. 0 bbls. were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Raga</i>	OIL CONSERVATION DIVISION	
Printed Name: Rebecca Raga	Approved by District Supervisor: Signed By <i>Mike Benavidez</i>	
Title: Field Admin Tech	Approval Date: MAR 13 2013	Expiration Date:
E-mail Address: Rebecca.raga@dvn.com	Conditions of Approval: Remediation per OCD Rule & Guidelines. SUBMIT REMEDIATION	Attached <input type="checkbox"/>
Date: 1/21/13 Phone: 575-746-5564		

* Attach Additional Sheets If Necessary

PROPOSAL NO LATER THAN:
April 13, 2013

2RP-1584