

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT Form C-141  
Revised August 8, 2011

MAY 13 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**NAB1513452903**

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P. <b>210737</b>	Contact: Tony Savoie
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: BEU Hackberry 34 Fed. #1	Facility Type: Tank Battery and SWD
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-40288	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	34	19S	31E	800	North	825	East	Eddy

Latitude N 32.621733° Longitude W 103.851513°

**NATURE OF RELEASE**

Type of Release: Crude oil	Volume of Release: 12 Bbls.	Volume Recovered: 4 bbls.
Source of Release: Heater-treater sight glass	Date and Hour of Occurrence: 5/4/15 time unknown,	Date and Hour of Discovery: 5/4/15 at approximately 7:30 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

The sight glass on the heater-treater broke, unknown reason. The sight glass valve was closed until the sight glass could be replaced.

Describe Area Affected and Cleanup Action Taken.\*

The spill impacted approximately 2,100 sq.ft. of caliche pad area around the process equipment with standing fluid, and approximately 2200 sq.ft. of pad area was lightly misted. The free standing fluid was recovered with a vacuum truck. EPI environmental crew worked on 5/7/15 and 5/8/15 removing the saturated soil with a hydro-vac; 28 cubic yards of material was hauled to R-360 for disposal. Soil samples were collected and delivered to the lab for confirmation analysis.  
The final closure report is pending.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: <b>5/14/15</b>	Expiration Date: <b>N/A</b>
E-mail Address: <a href="mailto:tasavoie@basspet.com">tasavoie@basspet.com</a>	Conditions of Approval: <b>Remediation per O.C.D. Rules &amp; Guidelines</b> Attached <input type="checkbox"/>	
Date: <b>5/13/15</b> Phone: 432-556-8730	<b>SUBMIT REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

LATER THAN: **6/15/15**

2RP-3001

## FIELD SPILL REPORT

Distribution List: CJ Barry, TA Savoie, B. Biehl, JR Smitherman, SF Johnson, W Hanna  
G Fletcher, J Fuqua, C Giese, J Brooks, M Titsworth, A Ruth, A Thompson, B Blevins, K Bright

DATE: May 4, 2015

LOCATION OF SPILL SITE: BEU Hackberry 34 Fed. #1 Battery (API 30-015-40288)

UL A, 34-19S-31E Eddy Co. N.M.

GPS COORDINATES (Lat & Long): 32.621994 -103.851153

**ESTIMATED VOLUMES (Oil & Water Separately):**

\*If BBLs Recovered are not available at time of Initial Report: Send in Follow-up report when numbers are known

Volume spilled:		BBLs Spilled	*BBLs Recovered	Net Spilled		BBLs Spilled	*BBLs Recovered	Net Spilled
On ground /or earth berm -	Oil:	12	4	8	Water:	0		0
Contained in impervious liner -	Oil:			0	Water:			0
<b>Total:</b>	<b>Oil:</b>	<b>12</b>	<b>4</b>	<b>8</b>	<b>Water:</b>	<b>0</b>	<b>0</b>	<b>0</b>





**DESCRIPTION (What happened?):**

EHS was notified of a release that occurred at the Hackberry battery. A sight glass broke and released 12 bbls. of oil to the ground surface.

**SPILL RESPONSE (How was the spill cleaned up?):**

A vacuum truck was called out and recovered 4 bbls of oil. Future remediation to be planned.

**PICTURE ATTACHMENT:**





2/13/2014

Oil Battery

SWD

BEU Hackberry 34 Fed #1 SWD

Spill area

© 2015 Google

Google earth

1996

Imagery Date: 2/13/2014 lat: 32.621079 lon: -103.851164 dev: 3.74 ft. eye alt: 4323 ft.