

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1514651908*

Name of Company: COG Operating LLC <i>229137</i>		Contact: Robert McNeill	<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Address: 600 West Illinois Avenue, Midland TX 79701		Telephone No. 432-230-0077		
Facility Name: West Brushy 8 Federal SWD #1		Facility Type: SWD		
Surface Owner: Federal		Mineral Owner: Federal	API No. 30-015-31675	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	8	26S	29E	660	North	330	East	Eddy

Latitude 32.0625249053514 Longitude -103.99867482237

**NATURE OF RELEASE**

Type of Release: Oil	Volume of Release: 10 bbls Oil	Volume Recovered: 9 bbls Oil
Source of Release: Water tank overflow	Date and Hour of Occurrence: 5/9/2015 12:00 pm	Date and Hour of Discovery: 5/9/2015 12:00 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <b>NM OIL CONSERVATION</b> ARTESIA DISTRICT	
If a Watercourse was Impacted, Describe Fully.*	MAY 21 2015	
<b>RECEIVED</b>		
Describe Cause of Problem and Remedial Action Taken.* This release was caused because the transducers on the alarms were not calibrated correctly. Vacuum trucks were dispatched to recover all the standing fluid.		
Describe Area Affected and Cleanup Action Taken.* This released remained with the lined bermed area of the facility. The facility able to be cleaned and put back into service.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: <i>Huber</i>	
Title: Senior Environmental Coordinator	Approval Date: <i>5/26/15</i>	Expiration Date:
E-mail Address: atrujillo@concho.com	Conditions of Approval: <b>FINAL</b>	Attached <input type="checkbox"/>
Date: May 21, 2015 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

*2RP-3016*

## **Patterson, Heather, EMNRD**

---

**From:** Amanda Trujillo <ATrujillo@concho.com>  
**Sent:** Thursday, May 21, 2015 4:55 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; James Amos; Jeff Robertson  
**Subject:** (Notification/C-141 Initial-Final) West Brushy 8 Federal #1 (30-015-31678)  
**Attachments:** 5-9-2015 West Brushy 8 Federal SWD #1 (TB) Initial-Final.pdf

Mr. Bratcher/Mr. Amos,

COG Operating LLC is reporting a release on the West Brushy 8 Federal #1 (30-015-31678)  
Unit A Section 8 Township 26S Range 29E  
The release occurred at 12:00 pm on 5/9/2015  
Released: 10 bbls Oil  
Recovered: 9 bbls Oil

This release was caused because the transducers on the alarms were not calibrated correctly. This release remained within the lined facility and was able to be recovered and the facility put back into service. If you have any additional questions please feel free to contact me.

Thank you,

### **Amanda Trujillo**

Senior Environmental Coordinator  
COG Operating LLC  
Cell: 505.350.1336  
Office: 575.748.6930  
[atrujillo@concho.com](mailto:atrujillo@concho.com)

2407 Pecos Ave.  
Artesia, NM 88210



**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information herein, is prohibited. If you received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.

**CONFIDENTIALITY NOTICE:** The information in this email may be confidential and/or privileged. If you are not the intended recipient or an authorized representative of the intended recipient, you are hereby notified that any review, dissemination or copying of this email and its attachments, if any, or the information contained herein, is prohibited. If you have received this email in error, please immediately notify the sender by return email and delete this email from your system. Thank you.