

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

SEP 04 2015

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1524749389

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>260737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: JRU 19 Battery	Facility Type: Exploration and Production

Surface Owner: State	Mineral Owner:	API No. 3001527357
----------------------	----------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	36	22S	30E	1980		1980		Eddy

Latitude: 32.346455 Longitude: 103.832237

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 1530 barrels	Volume Recovered: 1360 barrels
Source of Release: 4x2 Swedge on water transfer pump	Date and Hour of Occurrence: 9-3-15 @ 12:00am	Date and Hour of Discovery: 9-3-15 @ 5:45am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher via email	
By Whom? Bradley Blevins	Date and Hour: 9-3-15 @ 9:03am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

A 4x2 swedge failed on the water transfer pump causing fluid to be released to the lined containment (1100 barrels of produced water was recovered from inside the containment). The containment failed releasing 430 barrels of the fluid to the ground surface, 260 barrels of produced water was recovered from surrounding pasture area.

Describe Area Affected and Cleanup Action Taken.*

Vacuum trucks were able to recover a total of 1360 barrels of the produced water from the containment and ground surface.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	OIL CONSERVATION DIVISION	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: <i>9/4/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <i>9-4-15</i> Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/4/15

2RP-3240

Bratcher, Mike, EMNRD

From: Blevins, Bradley <BBlevins@BassPet.Com>
Sent: Thursday, September 03, 2015 9:03 AM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Blevins, Bradley; Savoie, Tony A.; Ruth, Amy C.
Subject: JRU 19 Battery

Mike, Heather

Bopco EHS was notified of a release that occurred at the JRU 19 battery. A connection on the top of water pump failed releasing PW to the containment. The containment failed releasing PW to the ground surface, vacuum trucks are in the process of recovering the fluid. I will follow up once all fluid has been recovered and more details are collected.
Thanks

Sent from my iPhone