

NM OIL CONSERVATION

ARTESIA DISTRICT

SEP 18 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company: Devon Energy Production Co LP (6137)	Contact: Brian Kuh, Foreman
Address: PO Box 250 Artesia, NM 88211	Telephone No. 575- 616-1540
Facility Name: Terrapin Treatment Facility "Terrapin Containment and Recycling Facility"	Facility Type: Water Treatment Facility
Surface Owner: State	Mineral Owner: State API No. NA

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	2	26S	31E	660	South	1155	West	Eddy

Latitude: ___ Longitude: 32.066441

NATURE OF RELEASE 103.753382

Type of Release: Produced Water	Volume of Release: 75 bbls	Volume Recovered: 75 bbl
Source of Release: Frac tank loading line valve connected to tank	Date and Hour of Occurrence: 8/24/2015, 3:30 PM	Date and Hour of Discovery: 8/24/2015, 3:30 PM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher	
By Whom? Brian Kuh	Date and Hour: 8/21/15, 9:19 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. NA	
If a Watercourse was Impacted, Describe Fully.* NA		
Describe Cause of Problem and Remedial Action Taken.* When tanks were being filled with produced water for treatment, it was found that the valves were not retightened after new gaskets were installed, causing a 75 barrel spill inside of containment. Immediately retightened all valves and gaskets on the frac tanks to stop further leaking.		
Describe Area Affected and Cleanup Action Taken.* The entire spill occurred within containment. The liner was checked for holes and none were found. A vacuum truck was used to recover the entire spill and place back into another frac tank. No further action required.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		

Signature: <i>D. Menoud</i>	OIL CONSERVATION DIVISION	
Printed Name: Denise Menoud	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Field Admin Support	Approval Date: 9/24/15	Expiration Date: N/A
E-mail Address: Denise.Menoud@dvn.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: 9/9/2015 Phone: 575-746-5544		

* Attach Additional Sheets If Necessary

2RP-3301

Bratcher, Mike, EMNRD


From: Menoud, Denise <Denise.Menoud@dvn.com>
Sent: Wednesday, September 09, 2015 9:11 AM
To: Bratcher, Mike, EMNRD
Cc: Menoud, Denise
Subject: FW: C141- Terrapin Treatment Facility
Attachments: Scanned C141 with map - Terrapin.PDF

Please see attached C141 on the Terrapin Treatment Facility. Thank you.

Denise Menoud

Admin Field Support 4 / Completions
Devon Energy Production Co. LP/Artesia NM
Denise.Menoud@dvn.com
575-746-5544

Confidentiality Warning: This message and any attachments are intended only for the use of the intended recipient(s), are confidential, and may be privileged. If you are not the intended recipient, you are hereby notified that any review, retransmission, conversion to hard copy, copying, circulation or other use of all or any portion of this message and any attachments is strictly prohibited. If you are not the intended recipient, please notify the sender immediately by return e-mail, and delete this message and any attachments from your system.



75 BPW Spilled & Recovered

Lat: 32.066441
Lon: -103.753382

SWSW-2-26S-31E

Terrapin treatment facility

Terrapin Facility
75 bbls Treated Wtr Spill




This map is for illustrative purposes only and is neither a legally recorded map nor survey and is not intended to be used as one. Devon makes no warranty, representation, or guarantee of any kind regarding this map.

WGS_1984_Web_Mercator_Auxiliary_Sphere
Prepared by: D Menoud
Map is current as of: 25-Aug-2015



Miles
0 0.02 0.04 0.07 1:3,557



Layers: Outline

