

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised October 10, 2003

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report  Final Report

Name of Company	Doyle Hartman	Contact	Don Mashburn
Address	500 N. Main St., Midland, TX 79701	Telephone No.	(432) 684-4011
Facility Name	State "LMT" No. 11.	Facility Type	Produced Water Tank

Surface Owner	State of New Mexico	Mineral Owner	State of New Mexico	Lease No.	[REDACTED]
---------------	---------------------	---------------	---------------------	-----------	------------

LOCATION OF RELEASE

API# 30025 35346 0000


Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	36	23S	36E	1150'	North	1750'	East	Lea

125'

Latitude [REDACTED] Longitude [REDACTED]

NATURE OF RELEASE

Type of Release	Produced Water Spill	Volume of Release	150 BBL	Volume Recovered	300 BBL (260 BBL)
Source of Release	150 BBL Fiberglass Tank	Date and Hour of Occurrence	[REDACTED]	Date and Hour of Discovery	10/3/04
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? [REDACTED]			
By Whom?	[REDACTED]	Date and Hour [REDACTED]			
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			



If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
During a severe thunderstorm on 10/03/2004, lightning struck and damaged a 150 BBL fiberglass water tank at our State "LMT" No. 11 facility. The lightning strike resulted in the unintentional and accidental release of 40 BBL of produced water from the damaged water tank. We cleaned up 300 BBL of water (40 BBL produced water + 260 BBL rain water). We installed a new 310 BBL fiberglass water tank, and we are in the process of installing a 24" (approximate height) berm around the new water tank.

Describe Area Affected and Cleanup Action Taken.\*  
We cleaned up 300 BBL of water (40 BBL produced water + 260 BBL rain water).

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Don Mashburn</i>	<b>OIL CONSERVATION DIVISION</b>		
Printed Name: Don Mashburn	Approved by District Supervisor:		
Title: Engineer	Approval Date:	Expiration Date:	
E-mail Address: [REDACTED]	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 10/19/2004	Phone: (432) 684-4011		

\* Attach Additional Sheets If Necessary

incident - n LWH 0428 162327  
application - p PAC 0607437965