

OCT 22 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1520542546

OPERATOR

Initial Report Final Report

Name of Company: Gibson Energy, LLC 229137	Contact: Bridget Sedlack
Address: 3819 Towne Crossing, Ste. 100 Mesquite, TX 75150	Telephone No. 214-461-5563
Facility Name: COG-SRO St. Com #043H	Facility Type: Truck Release

Surface Owner: State	Mineral Owner: State	API No. 30-015-41141
----------------------	----------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	17	26S	28E	190	N	990	W	Bddy

Latitude 32.0492096 Longitude -104.1149597

NATURE OF RELEASE

Type of Release: Crude Oil	Volume of Release: 9bbls	Volume Recovered: 5bbls
Source of Release: Truck Overfill	Date and Hour of Occurrence: 10/19/15 @ 5:30 am	Date and Hour of Discovery: 10/19/15 @ 5:30 am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
Human error caused a truck to overfill onto COG's SRO St. Com #043H location. Approximately 9bbls of oil were released. Gibson Energy contacted Talon/LPE to conduct an emergency response and to recover the standing fluids. A vacuum truck was utilized to recover the standing fluids. Approximately 5bbls of oil were recovered.

Describe Area Affected and Cleanup Action Taken.*
The impacted area was near the LACT unit at the tank battery. All of the fluid was contained to the location. After recovering the standing fluids Talon/LPE covered the impacted area with an organic sorbent to further stabilize the surface of the impacted area should a precipitation event occur before remediation activities are complete. The impacted area will be excavated, confirmation soil samples will be obtained, analyzed for TPH, BTEX, and Chloride, and the analytical results will be submitted to NMOCD for review prior to backfill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Bridget Sedlack	Signed By:	
Title: Environmental Manager	Approved by Environmental Specialist:	Approval Date: 10/22/15 Expiration Date: N/A
E-mail Address: bridget.sedlack@gibsons.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 10/20/15 Phone: 214-461-5563	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 11/23/15 **2RD-3350**

Bratcher, Mike, EMNRD

From: Sheldon Hitchcock <slhitchcock@talonlpe.com>
Sent: Thursday, October 22, 2015 10:02 AM
To: Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD
Cc: bridget.sedlack@gibsons.com; lwalp@gibsons.com
Subject: Gibson Energy/COG: SRO St. Com 43H 30-015-41141 Initial C-141
Attachments: Signed C-141.pdf

Heather,

Please see the attached C-141 for the SRO St. Com 43H. Gibson Energy overfilled a truck resulting in a release of 9bbls of oil. We used a vac truck and were able to recover 5bbls. Being that the release was on a COG pad we are going to move forward with the remediation. I will take confirmation samples and send you the analytical results prior to backfill. Please let me know if you have any questions or concerns.

Respectfully,

Sheldon L. Hitchcock
Project Manager
Talon/LPE
408 West Texas Avenue
Artesia, New Mexico 88210
Office: (575) 746-8768
Direct: (575) 616-4021
Cell: (575) 689-5198
Fax: (575) 746-8905
Email: slhitchcock@talonlpe.com
Web: www.talonlpe.com



Better Business Bureau Torch Award for Marketplace Ethics: 2010 Winner, 2009 Finalist
Staples Foundation for Learning Hall of Fame Recipient: 2010
ICIC and Business Week- Top 100: 2010, 2009, 2008, 2007, 2006
Inc. 500/5000: 2012, 2011, 2010, 2009, 2008, 2007

This email and any files transmitted with it are confidential and intended solely for the use of the individual or entity to whom they are addressed. If you have received this email in error please notify the system manager. This message contains confidential information and is intended only for the individual named. If you are not the named addressee you should not disseminate, distribute or copy this e-mail. Please notify the sender immediately by e-mail if you have received this e-mail by mistake and delete this e-mail from your system. If you are not the intended recipient you are notified that disclosing, copying, distributing or taking any action in reliance on the contents of this information is strictly prohibited.