

DEC 22 2015

Form C-141
Revised August 8, 2011

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1535154357

OPERATOR

Initial Report Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: James Ranch Unit #10 Battery	Facility Type: Exploration and Production

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-23075
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	1	23S	30E	1980	North	660	East	Eddy

Latitude 32.335560° Longitude -103.827584°

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 81 bbls	Volume Recovered: 40 bbls
Source of Release: Tank Overflow	Date and Hour of Occurrence: 12/14/2015 time unknown	Date and Hour of Discovery: 12/14/2015 11:15 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Heather Patterson (NMOCD), Jim Amos (BLM)	
By Whom? Amy Ruth	Date and Hour: 12/14/2015 4:52 pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Coupling on water transfer pump failed and pump shut down. Produced water tank filled and overflowed into the battery earthen containment. The pump was repaired.

Describe Area Affected and Cleanup Action Taken.*
The leak affected 1550 ft² of well pad within the tank containment and standing fluids were recovered.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION	
Printed Name: Amy C. Ruth	Approved by Environmental Specialist:	
Title: Remediation Specialist	Approval Date: 12/23/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input checked="" type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO	
Date: 12/22/2015 Phone: 432-661-0571	LATER THAN: 1/24/16	

* Attach Additional Sheets If Necessary

2RP-3164

Patterson, Heather, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Tuesday, December 22, 2015 1:38 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Jim Amos
Subject: RE: james ranch unit 010 bopco l.p.
Attachments: Initial C-141 JRU 10 Battery 12-14-15.pdf

Hello All,
Here is the initial C-141 for the spill with details.
Thank you!
-Amy

From: Ruth, Amy C.
Sent: Monday, December 14, 2015 4:52 PM
To: Mike Bratcher; EMNRD Patterson Heather
Cc: Jim Amos
Subject: james ranch unit 010 bopco l.p.

BOPCO had an accidental release of produced water at the JRU 10 tank battery. The water transfer pump failed and the tank overflowed into the earthen containment. Fluids remained within the containment with exception of the sw corner, though what little escaped remained on the well pad, and 40 bbls pw was recovered. An estimate of fluid remaining in soil will be made and submitted on a form C-141 along with a summary of any repair activities. Below is the location API and well GPS coordinates. Thanks

Description: API: **3001523075**
Coords: 32.335841,-103.827771

Patterson, Heather, EMNRD

From: Ruth, Amy C. <ACRuth@BassPet.Com>
Sent: Monday, December 14, 2015 4:52 PM
To: Bratcher, Mike, EMNRD; Patterson, Heather, EMNRD
Cc: Jim Amos
Subject: james ranch unit 010 bopco l.p.
Attachments: image.jpeg

BOPCO had an accidental release of produced water at the JRU 10 tank battery. The water transfer pump failed and the tank overflowed into the earthen containment. Fluids remained within the containment with exception of the sw corner, though what little escaped remained on the well pad, and 40 bbls pw was recovered. An estimate of fluid remaining in soil will be made and submitted on a form C-141 along with a summary of any repair activities. Below is the location API and well GPS coordinates. Thanks

Description: API: 3001523075<tel:3001523075>
Coords: 32.335841,-103.827771
[image.jpeg]

Sent from my iPhone