

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

NOV 29 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

*NAB1633639499*

Name of Company	WPX Energy Inc/RKI <i>241289</i>	Contact	Karolina Blaney
Address	5315 Buena Vista Dr.	Telephone No.	970 589 0743
Facility Name:	Brushy Draw Booster Station/Fed UCBHWW 1	Facility Type:	Tank Farm
Surface Owner:	Federal	Mineral Owner:	Federal
		API No.	30-015-24034

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	25	26S	29E	660	FSL	660	FWL	Eddy

Latitude: 32.005742 N Longitude: -103.944433 W

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 120 Bbls	Volume Recovered: 200 Bbls
Source of Release Produced water tank	Date and Hour of Occurrence 11/13/2016	Date and Hour of Discovery 11/13/2016 - 1420 hrs MT
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? NMOCD Heather Patterson & Michael Bratcher, BLM Shelly Tucker	
By Whom? Karolina Blaney	Date and Hour: 11/14/16- 1302 hrs MT	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.\* N/A

**Describe Cause of Problem and Remedial Action Taken.\***

The cause of this spill is equipment failure; a cross arm on an electric post failed which cut off power supply to the water transfer pump. Additionally, the ESD float got stuck, didn't trigger the high water alarm notification and didn't shut in the system.

**Describe Area Affected and Cleanup Action Taken.\***

The spill was contained inside dirt SPCC containment berm. 200 bbls of produced water and stormwater were recovered from the secondary containment (estimated at least 80 bbls of stormwater). The impacted area was sampled for chlorides, BTEX and TPH in accordance with NM OCD Guidelines for Remediation of Leaks, Spills, and Releases. WPX will submit a workplan to OCD and BLM for the remediation of this spill.

The total ranking score for this site is 0 and the site will be remediated to levels specified in 0-9 column of the Guidelines document.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Karolina Blaney</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Karolina Blaney	Approved by Environmental Specialist <i>[Signature]</i>	
Title: Environmental Specialist	Approval Date: <i>11/30/16</i>	Expiration Date: <i>N/A</i>
E-mail Address: Karolina.blaney@wpxenergy.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 11/28/2016	Phone: 970-589-0743	

\* Attach Additional Sheets If Necessary

2RP-4011

## **Patterson, Heather, EMNRD**

---

**From:** Blaney, Karolina <Karolina.Blaney@wpxenergy.com>  
**Sent:** Monday, November 28, 2016 2:09 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'  
**Subject:** RE: WPX Brushy Draw Booster Station - initial C-141  
**Attachments:** Brushy Draw Booster Station - Initial C-141.doc

Attached is the initial C-141 for this spill.  
Please let me know if you have any questions or suggestions.  
Thank you,

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Office: (575) 885-7514  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

---

**From:** Blaney, Karolina  
**Sent:** Monday, November 14, 2016 1:02 PM  
**To:** 'Patterson, Heather, EMNRD' <Heather.Patterson@state.nm.us>; 'Bratcher, Mike, EMNRD' <mike.bratcher@state.nm.us>; 'stucker@blm.gov' <stucker@blm.gov>  
**Subject:** WPX Brushy Draw Booster Station - spill notification

Good afternoon,

Yesterday, 11/13/16, WPX had a produced water spill at the Brushy Booster Station location. The cause of this spill is equipment failure; a cross arm on an electric failed which cut off power supply to the water transfer pump. Additionally, the ESC float got stuck and didn't trigger the high water alarm notification and didn't shut in the system. Approximately 200 bbls of produced water and stormwater were recovered from the secondary containment (estimated at least 80 bbls of stormwater).

The Brushy Booster Station is located south of the Fed UCBHWW 1, API # 30- 015-24034, qtr/qtr M, S25, T26S, R29E.

The C-141 report will be submitted within 15 days from the incident.

Please let me know if you have any questions or concerns.

Thank you and have a great day,

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)

## **Patterson, Heather, EMNRD**

---

**From:** Blaney, Karoljna <Karoljna.Blaney@wpxenergy.com>  
**Sent:** Monday, November 14, 2016 1:02 PM  
**To:** Patterson, Heather, EMNRD; Bratcher, Mike, EMNRD; 'stucker@blm.gov'  
**Subject:** WPX Brushy Draw Booster Station - spill notification

Good afternoon,

Yesterday, 11/13/16, WPX had a produced water spill at the Brushy Booster Station location. The cause of this spill is equipment failure; a cross arm on an electric failed which cut off power supply to the water transfer pump. Additionally, the ESC float got stuck and didn't trigger the high water alarm notification and didn't shut in the system. Approximately 200 bbls of produced water and stormwater were recovered from the secondary containment (estimated at least 80 bbls of stormwater).

The Brushy Booster Station is located south of the Fed UC BHW 1, API # 30-015-24034, qtr/qtr M, S25, T26S, R29E.

The C-141 report will be submitted within 15 days from the incident.

Please let me know if you have any questions or concerns.

Thank you and have a great day,

*Karolina Blaney*  
Environmental Specialist  
WPX Energy  
Cell: (970) 589-0743  
[karolina.blaney@wpxenergy.com](mailto:karolina.blaney@wpxenergy.com)