

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

MAY 29 2018

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office
District II - ARTESIA, OGD
In accordance with 19.15.29 NMAC.

FAB1815958809
NAB1815959068

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company DCP Midstream LP <i>36785</i>	Contact Yvonne Blair
Address 5301 Sierra Vista, Carlsbad NM 88220	Telephone No. cell 575-361-2406
Facility Name 10500 Pipeline	Facility Type Natural Gas Gathering Pipeline

Surface Owner: BLM	Mineral Owner: unknown	API No. N/A
--------------------	------------------------	-------------

LOCATION OF RELEASE

Unit Letter	Section 1	Township 21S	Range 31E	Feet from the	North/South Line	Feet from the	East/West Line	County <i>tea Eddy</i>
-------------	-----------	--------------	-----------	---------------	------------------	---------------	----------------	------------------------

Latitude _ 32.519703 _ Longitude -103.829627

NATURE OF RELEASE

Type of Release: Natural Gas	Volume of Release 465 MCF	Volume Recovered 0
Source of Release Pipeline	Date and Hour of Occurrence 05-09-18 11:30 AM	Date and Hour of Discovery 05-09-18 11:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* N / A

Describe Cause of Problem and Remedial Action Taken.*

DCPM was notified of a possible line leak on 05/09/18 by landowner to DCP Midstream. Natural Gas release into atmosphere. Minimal condensate were present and lines were shut in by operators.

Describe Area Affected and Cleanup Action Taken.*

DCPM construction crew repaired the line with 8" steel 2 joints to be on 05/15/18 by replacing 1 joint of 40' steel pipe. The line was put back in service on 4/24/18. No field remediation was required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health, or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Yvonne Blair</i>	OIL CONSERVATION DIVISION	
Printed Name: Yvonne Blair	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Compliance Coordinator	Approval Date: <i>6/7/18</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>yblair@dcpmidstream.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/> <i>2RD-4792</i>
Date: 05/21/18 Phone: 575-361-2406		

* Attach Additional Sheets If Necessary

Bratcher, Mike, EMNRD

From: Blair, Yvonne B <YBBlair@dcpmidstream.com>
Sent: Tuesday, May 29, 2018 10:53 AM
To: Weaver, Crystal, EMNRD; Bratcher, Mike, EMNRD
Subject: 10500 line leak C141 initial and closure.docx
Attachments: 10500 Line Leak - Site Overview Map.pdf; 10500 Soil Sample Table.pdf; H801373 DCP.pdf; 10500 Line Leak C141.doc

Crystal and Mike

Please see attached C-141 initial and closure request. All results are below standards.

DCPM construction crew repaired the line with 8" steel 2 joints to be on 05/15/18 by replacing 1 joint of 40' steel pipe. The line was put back in service on 5/16/18. No remediation was required due to atmosphere release only.

Yvonne Blair
Compliance Coordinator
DCP Midstream
5301 Sierra Vista Dr
Carlsbad, NM 88220
575-361-2406

From: Blair, Yvonne B
Sent: Wednesday, May 16, 2018 6:15 PM
To: Jordan, Yolanda (yjordan@blm.gov)
Subject: FW: 5-9-18 10500 leak report.docx

Yolanda

This line leak is a discharge line for DCP. It is high pressure line. 465 MCF emissions release that will be reported to NMOCD with request for immediate closure. Please see attached lease.

Thanks

Yvonne Blair
Compliance Coordinator
DCP Midstream
5301 Sierra Vista Dr
Carlsbad, NM 88220
575-361-2406



