

3RF - 28

**Leak Detection
Inspection Logs**

**Enduring
NEU 16B Facility**

10/22/18 - 12/26/18

Date: 2018

Leak Detection Water Removal Report - December
NEU 2207 16B

PLS 18 26341898

Total Depth of Leak Detection: 75'

Date	Leak Detection Water Level	Gallons Removed	Comments	Pond Water Level
11/9/2018	53'	0		17'
11/20/2018	53'	0		17'
11/21/2018	53' 6 1/4"	0		17'
11/22/2018	53.55'	0		17'
11/23/2018	53.5'	0		17'
11/24/2018	over 50'	0	unable to get WL meter past 50'	17'
11/25/2018	over 50'	0	unable to get WL meter past 50'	15.6'
11/26/2018	over 50'	0	unable to get WL meter past 50'	15.6'
11/27/2018	over 50'	0	unable to get WL meter past 50'	14.3'
11/28/2018	over 50'	0	unable to get WL meter past 50'	14.3'
11/30/2018	53.5'	63	using a hand pump	15.6'
12/3/2018	56.6'	2.5	hand pump broke	16.8'
12/10/2018	59.7'	0	Diaphragm pump did not work	11.6'
12/11/2018	59.5'	95	diaphragm pump used	10.3'
12/12/2018	61.25'	70	diaphragm pump used	11.6'
12/17/2018	69.8'	40	diaphragm pump used	8.6'
12/19/2018	64'	70	diaphragm pump used	9.2'
12/20/2018	68.5'	100	diaphragm pump used	9.3'
12/26/2018	66'	50	diaphragm pump used	8.2'
12/27/2018	67'	34	diaphragm pump used	7.6'

TOTAL GALONS REMOVED FROM LD 490.5





Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NBU 2207 168 Permit Number _____

Section 16 Township 22N Range 7W County SANDOVAL

Latitude _____ Longitude _____

Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Pond being filled

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Permant fence is still being install temp^{oo} fence in good condition

COMMENTS

Name (Print) SAM BARRETT

Date 10-22-18

Name (Signature) [Signature]

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NB4 2207-16B Permit Number _____
 Section 16 Township 22N Range 7W County SANDOVAL
 Latitude _____ Longitude _____
 Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

THERE IS SOME OIL IN POND, SPOKE WITH GEORGE Employee's and they will remove oil and replace oil absorbent booms.

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Bird deterrent system is working and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>

Leak detection still needs to be installed, two deputy owls have broken wings, 1 billion is in pond and another is off next to roll off.

COMMENTS

Name (Print) SAM BAILEY Date 10-28-14
 Name (Signature) [Signature] Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEA 2207-16B Permit Number _____
 Section 16 Township 22N Range 7W County SANDOVAL
 Latitude _____ Longitude _____
 Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

WATER LEVEL IN BETWEEN LINER AT 53 FT AND BOTTOM IS APPROX 75 FT
 APPROX 20 FT OF WATER. WATER IN LINER IS LOWER THAN POND

COMMENTS

Name (Print) SAM BARRON Date 11-9-12
 Name (Signature) [Signature] Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 16B Permit Number _____

Section 16 Township 22N Range 7W County SANDOVAL

Latitude _____ Longitude _____

Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

STILL OIL THAT NEEDS SKIMMED OFF THE TOP. Oil Absorbent Booms need replaced. Owls are in need of repair and scare eyes have 5 missing it was too windy to repair owls

COMMENTS

Name (Print) SAM BARRETT

Date 11-12-18

Name (Signature)

Company ENDURING RESOURCES



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 2207 16B Permit Number SJ4301P0D1
Section 16 Township 22N Range 7W County Sandovg 1
Latitude _____ Longitude _____
Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYCLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Sampled water in leak detection at 53 ft. oil booms being used in skimming of surface oil, being replaced. minimal signs of surface oil currently remain.

COMMENTS

Name (Print) John Docket Date 11/20/18

Name (Signature) John Docket Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 2207-16B Permit Number _____
 Section 16 Township 22N Range 7W County Sandoval
 Latitude _____ Longitude _____
 Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Water detected @ 53ft 6 1/4 inches in leak detection
OWB working, but may need replaced in near future.

COMMENTS

Name (Print) John Dackter Date 11/21/18
 Name (Signature) [Signature] Company Enduring Resources



Recycling Facility Inspection

Conducted on
11/22/18, 8:49 AM

Prepared by
James McDaniel

Score
14/15 - 93.33%

Completed on
11/22/18, 8:53 AM


Failed Responses

This section lists responses that were set as "failed responses" in the template used for this audit.


Question	Response	Details
Leak detection was checked, and does not show signs of a release	No	Water in leak detection at 53.55 feet.

Audit - 14/15 - 93.33%


Question	Response	Details
Location Name	NEU 2207 16B	
Permit Number	3RF-28	
Location	Cuba, NM 87018 United States (36.14477796483425, -107.5767284073937)	
Recycling Facility	<input checked="" type="checkbox"/>	
Recycling Containment	<input checked="" type="checkbox"/>	
Facility is free of evidence of leaks, spills or releases	Yes	
Facility is still being used for the recycling of produced water	Yes	
Facility sign is visible and in good condition	Yes	
Comments		
Recycling Containment		
1		
Containment has a minimum of three feet of freeboard	Yes	
Containment is free of evidence of surface water run-on	Yes	
Containment water surface is free of visible signs of oil	Yes	
Oil absorbent booms are on-site and in good condition	Yes	
Injection and withdrawal of water is done through a header	Yes	
There is no evidence of a leak in the liner above the waterline	Yes	
Leak detection was checked, and does not show signs of a release	No	Water in leak detection at 53.55 feet.

Question	Response	Details	
No migratory birds were discovered in the containment	Yes		
Bird deterrent system is working and in good condition	Yes		
Facility fencing is in good condition and is not in need of repairs	Yes		
Pictures of Recycling Facility			
<div style="display: flex; justify-content: space-around; align-items: center;"> <div style="text-align: center;">  <p>Appendix 1</p> </div> <div style="text-align: center;">  <p>Appendix 2</p> </div> </div>			
Comments	Additional bird balls need to be ordered and hung up. Water being pumped into facility at time of inspection.		
Date and Time	11/22/18, 8:52 AM		
Inspector	James McDaniel	11/22/18 8:52 AM	

Media



Appendix 1



Appendix 2



Recycling Facility Inspection

23 Nov 2018 / Chad Snell

Status

Complete

Conducted on

23rd Nov, 2018 10:01 AM MST

Prepared by

Chad Snell

2

Failed responses

86.67%

Audit score

2 Failed Responses

Audit

Recycling Containment / null 1

Containment water surface is free of visible signs of oil

No

Notes

Starting to get a light film on top

Attached Media



Leak detection was checked, and does not show signs of a release

No

Notes

Leak detection had water. Level was at 53.5. Level did not Increase

Location Name
NEU 2207 16B Pond

Permit Number
3RF-28

Location
Cuba, NM 87018
United States
(36.111707, -107.5368014)



Recycling Facility



Recycling Containment

Facility is free of evidence of leaks, spills or releases

Yes

Facility is still being used for the recycling of produced water

Yes

Facility sign is visible and in good condition

Yes

Comments
No response

Recycling Containment

80.00% 8/10

Element 1

80.00% 8/10

Containment has a minimum of three feet of freeboard

Yes

Containment is free of evidence of surface water run-on

Yes

Containment water surface is free of visible signs of oil

No

Notes

Starting to get a light film on top

Attached Media



Oil absorbent booms are on-site and in good condition

Yes

Notes

Might need booms by second water discharge into pond.

Attached Media



Injection and withdrawal of water is done through a header

Yes

There is no evidence of a leak in the liner above the waterline

Yes

Leak detection was checked, and does not show signs of a release

No

Notes

Leak detection had water. Level was at 53.5. Level did not Increase

No migratory birds were discovered in the containment

Yes

Bird deterrent system is working and in good condition

Yes

Facility fencing is in good condition and is not in need of repairs

Yes

Pictures of Recycling Facility

No media added

Comments

No response

Date and Time

23rd Nov, 2018 10:17 AM MST

Inspector



23rd Nov, 2018 10:06 AM MST

3 Photos




Photo 1




Photo 2




Photo 3



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 2207-16B Permit Number 3RF-28
 Section 16 Township 22N Range 7W County Sandevag
 Latitude _____ Longitude _____
 Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawl of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

water level was checked to soft and no water was detected.
 Ovals and balloons could use a little attention.

COMMENTS

Name (Print) John Dackter Date 11/24/18
 Name (Signature) *John Dackter* Company Enduring Resources



Recycling Facility Inspection

25 Nov 2018 / Chad Snell

Status

Complete

Conducted on

25th Nov, 2018 08:44 AM MST

Prepared by

Chad Snell

1

Failed response

93.33%

Audit score

1 Failed Response

Audit

Recycling Containment / null 1

Leak detection was checked, and does not show signs of a release

No

Notes

Water in leak detection. Could only check to 50ft and no water at 50ft. We know water level has been at 53.5ft

Location Name
NEU 2207 16B

Permit Number
3RF-28

Location
Cuba, NM 87018
United States
(36.111707, -107.5368014)



Recycling Facility



Recycling Containment

Facility is free of evidence of leaks, spills or releases

Yes

Facility is still being used for the recycling of produced water

Yes

Facility sign is visible and in good condition

Yes

Comments
No response

Recycling Containment

90.00% 9/10

Element 1

90.00% 9/10

Containment has a minimum of three feet of freeboard

Yes

Containment is free of evidence of surface water run-on

Yes

Containment water surface is free of visible signs of oil

Yes

Oil absorbent booms are on-site and in good condition

Yes

Injection and withdrawal of water is done through a header

Yes

There is no evidence of a leak in the liner above the waterline

Yes

Leak detection was checked, and does not show signs of a release

No

Notes

Water in leak detection. Could only check to 50ft and no water at 50ft. We know water level has been at 53.5ft

No migratory birds were discovered in the containment

Yes

Bird deterrent system is working and in good condition

Yes

Facility fencing is in good condition and is not in need of repairs

Yes

Pictures of Recycling Facility

No media added


Comments

Need more bird balls. Water being produced into pond from water well. Water level has gone down about 5ft due to using water for frac

Date and Time

25th Nov, 2018 08:48 AM MST

Inspector



25th Nov, 2018 08:48 AM MST



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 2207 16B Permit Number _____
 Section 16 Township 22N Range 7W County Sandoval
 Latitude _____ Longitude _____
 Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYCLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	* YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

or minimal traces of surface oil being skimmed off later today. water level in leak detection was measured down to 50 ft and the level has not risen. Water currently being ran into pond from tanks. Bird deterrant audio in good working condition. @wts wild need attention this week.

COMMENTS

Name (Print) John Dackter Date 11/26/18
 Name (Signature) *John Dackter* Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NE 2267 116B Permit Number 3RF-28
 Section 116 Township 22N Range 7W County Sandover
 Latitude 36.14395 Longitude -107.576203
 Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYCLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrent system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Water level in leak detection was measured to 50'. No detection indicates water level has not risen. Small accumulation of oil in SE corner. Pumper stated water cleared with chemical treatment but has returned to original coloration.

COMMENTS

Name (Print) John Dockter Date 11/27/18

Name (Signature) *John Dockter* Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 2207 16B Permit Number _____
Section 16 Township 22N Range 7W County Sandoval
Latitude _____ Longitude _____
Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Small amount of oil on water surface in Northeast corner.
There is no water in leak detection up to 50 ft. There was previously water in leak detection at 53 ft. Therefore water level has not risen.

COMMENTS

Name (Print) John Doelter Date 11/28/18
Name (Signature) *John Doelter* Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name New 2207 16B Permit Number 3RF-28
Section 16 Township 22N Range 7W County Sandwich
Latitude 36.14395 Longitude -107.576203
Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYCLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrent system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

603 gallons pumped from leak detection. water detector detects water at approx. 60'ft on mid setting. and nothing at 75'ft on lowest setting.

COMMENTS

Name (Print) John Dackter Date 11/30/18

Name (Signature) John Dackter Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 2207 110B Permit Number 3RF-28
Section 16 Township 22N Range 7W County Sandoval
Latitude 36.14395 Longitude -107.576203
Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYCLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Leak detection checked water at 56 1/2" Head pumped 2.5 gallons before pump went out
Several small patches of oil on water surface

COMMENTS

Name (Print) John Dackter Date 12/3/18

Name (Signature) Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 2207 16B Permit Number 3RF-28

Section 16 Township 22N Range 7W County Sandoval

Latitude 36.14395 Longitude -107.576203

Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Pictures sent to James of truck that has been leaking pond water since "last night"

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrent system is working and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

1) trace amounts of surface oil 2) leak detection had water at 59'7". Could not successfully pump. will return tomorrow to pump. 3) speaker system is working, owls are up, but balls have been taken down along with fence around containment, but facility outer fence still in good condition (curtis)

COMMENTS

Name (Print) John Dackter Date 12/10/18

Name (Signature) *John Dackter* Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NPU 2207 16B Permit Number 3RF-28
Section 16 Township 22N Range 7W County Sandoval
Latitude 36.14395 Longitude -107.576203
Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

Trace oil on water surface. Leak detection showed water at 59.5".
95 gallons pumped out. Leak detection checked again. water @
approx 70'. OWS are up. speaker running, no bird deterrant balls up.

Name (Print) John Dockter Date 12/11/18
Name (Signature) Company Enduring



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 2207 16B Permit Number 3RF-28
Section 16 Township 22N Range 7W County Sandoval
Latitude 36.14395 Longitude -107.576203
Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYCLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYCLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrent system is working and in good condition	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

-Water detected at 61' 2.5". 70 gallons pumped. Water level checked again. 65' 8".

COMMENTS

Name (Print) John Dockett Date 12/12/18
Name (Signature) [Signature] Company Enduring Resources



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 2207 168 Permit Number 3RF-28

Section 16 Township 22N Range 7W County Sandoval

Latitude 36.14395 Longitude -107.576203

Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawl of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Water level in leak detection 69'8" 40 gallons were pumped from leak detection. Final water level was 68'6"

COMMENTS

Name (Print) John Dochter Date 12/18/18

Name (Signature) John Dochter Company Enduring



Enduring Resources, LLC

Recycling Facility Inspection Sheet

SITE INFORMATION

Location Name NEU 22nd 16B Permit Number 3RF-28
 Section 16 Township 22N Range 7W County Sandoval
 Latitude 36.14395 Longitude -107.576203
 Recycling Facility Recycling Containment

INSPECTION INFORMATION FOR RECYLING FACILITY

Facility is free of evidence of leaks, spills or releases	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility is still being used for the recycling of produced water	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility sign is visible and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

COMMENTS

INSPECTION INFORMATION FOR RECYLING CONTAINMENT

Containment has a minimum of three feet of freeboard	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment is free of evidence of surface water run-on	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Containment water surface is free of visible signs of oil	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Oil absorbent booms are on-site and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Injection and withdrawal of water is done through a header	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
There is no evidence of a leak in the liner above the waterline	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Leak detection was checked and doesn't show signs of a leak	YES	<input type="checkbox"/>	NO	<input checked="" type="checkbox"/>
No migratory birds were discovered in the containment	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Bird deterrant system is working and in good condition	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>
Facility fencing is in good condition and is not in need of repairs	YES	<input checked="" type="checkbox"/>	NO	<input type="checkbox"/>

Water in leak detection at approx. 66"
 Ending water level in leak detection: 69"

COMMENTS

Name (Print) John Dicker Date 12/26/18
 Name (Signature) *John Dicker* Company Enduring/High Desert