

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised October 10, 2003

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company: <b>Occidental Permian Limited Partnership</b>	Contact: <b>Tony Summers</b>
Address: <b>1017 West Stanolind Road, Hobbs, N.M. 88240</b>	Telephone No: <b>505.397.8236 or 505.390.9228</b>
Facility Name <b>State D Battery</b>	Facility Type <b>Production</b>

Surface Owner	Mineral Owner <b>Oxy</b>	Lease No.
---------------	--------------------------	-----------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County Lea
G	32	21S	36E					

Latitude N32° 26.318' Longitude W 103° 17.249'

**NATURE OF RELEASE**

Type of Release <b>Crude oil</b>	Volume of Release <b>60 bbls crude oil</b>	Volume Recovered <b>50 bbls crude oil</b>
Source of Release <b>Whole in circulation line between heater and storage tanks.</b>	Date and Hour of Occurrence <b>03/04/07 approx. 6:00 am</b>	Date and Hour of Discovery <b>03/04/07 9:00am</b>
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? <b>Chris Williams</b>	
By Whom?	Date and Hour <b>03/05/07 10 am</b>	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\* At approximately 6 am on Sunday 03/04/07 a whole occurred in a circulation 3 inch steel buried pipe line between heater treater and storage tanks. Approx. 60 barrels of crude oil leaked out. Line was shut in and vacuum truck called which recovered 50 barrels of crude oil.

Describe Area Affected and Cleanup Action Taken.\* Spill site was contained to existing Oxy tank battery caliche pad. Picked up all free standing fluids with vacuum truck. Contaminated soil will be evacuated and hauled to JL Land Farm and replaced with new soil.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature:	Approved by District Supervisor: <i>Chris Williams</i>	
Printed Name: <b>Tony Summers</b>	Approval Date: <b>3/20/07</b>	Expiration Date: <b>3/20/08</b>
Title: <b>HES Technician</b>	Conditions of Approval: Attached <input type="checkbox"/>	
E-mail Address: <b>tony_summers@oxy.com</b>		

facility - FPAC 0708022805  
incident - NPAC 0708022976

application - PAC 0708023067 RP# 1247

Date:

Phone: **505.397.8236**

\* Attach Additional Sheets If Necessary



**Occidental Permian Limited Partnership**

---

March 19, 2007

New Mexico Oil Conservation Division  
District I  
1625 N. French Drive  
Hobbs, New Mexico 88240

Attn: Environmental Engineering

RE: Remediation Plan  
State D Tank Battery  
UL 'G, Sec. 32, T-21S, R-36E

At approximately 6 AM on 03/04/07 a hole occurred in a 3" buried steel circulation line between heater treater and storage tanks on existing Oxy tank battery. Lease was shut in while repairs were made and vacuum truck called. Approx. 60 barrels of crude oil were spilled and 50 were picked up by vacuum truck. All fluid spilled onto existing battery caliche pad, none got into pasture. The NMSEO data base has no info for this exact area. The closest is in section 25 which show average depth to water 148' giving a ranking of 0. Remediation of spill site will be as follows:

1. Line will be replaced with new.
2. Contaminated area will be excavated and disposed of to JL Land farm.
3. NMOCD guidelines will be used to insure entire site is in compliance with guidelines.

If you have any questions, or if I can be of further assistance, please contact me at (505) 397-8251.


Tony Summers  
HES Technician/Seminole RMT

Tony\_summers@oxy.com  
(505) 397-8236

Attachments: Initial C-141  
Hand drawn map of spill site.

# STD Battery

N/2 sec 32 T21S R36E 400.00



67 bls on ground  
30 bls picked up