

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED
DEC 14 2009
HOBBSD

Form C-141
Revised October 10, 2003
Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company	Purvis Operating Co.	Contact	Donnie E. Brown
Address	PO Box 51990, Midland, TX 79710	Telephone No.	432-682-7346
Facility Name	Gladiola SWD System	Facility Type	Saltwater Disposal System

Surface Owner	Dean Kinsolving	Mineral Owner	Unknown	Lease No.	NA
---------------	-----------------	---------------	---------	-----------	----

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	26	12S	37	1500' approx.	South	2200' approx.	East	Lea

30.025. 07141

(See Attached Map) Latitude _____ Longitude _____

NATURE OF RELEASE



Type of Release	Produced Saltwater	Volume of Release	Approx. 250-300 bbls.	Volume Recovered	None. Soaked away
Source of Release	6" PVC Pipe Line	Date & Hr of Occurrence:	p.m. of 12-9-09	Date and Hour of Discovery	11:25 a.m. of 12-10-2009
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Geoffrey Leking		
By Whom?	Donnie Brown	Date and Hour	3:30 p.m., 12-10-2009		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	None		

If a Watercourse was Impacted, Describe Fully.*
Not Impacted.

Describe Cause of Problem and Remedial Action Taken.*
 A collar on a 6" PVC saltwater disposal line failed that leaked saltwater. The pipe was dug up and repaired. The soil that was dug up will be hauled to a land farm and replaced with fresh soil. All standing produced water was picked up with a vacuum truck.

Describe Area Affected and Cleanup Action Taken.*
 The area affected is approximately the same area that was reported on Form C-141 dated August 21, 2009. Vertical and lateral characterization of the affected area will be done before remediation recommendations are made to the OCD

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<u>OIL CONSERVATION DIVISION</u>	
Printed Name:	Donnie E. Brown	Approved by District Supervisor:	
Title:	Petroleum Engineer	Approval Date:	12-16-09
E-mail Address:	eng@purvisop.com	Expiration Date:	2-16-10
Date:	December 10, 2009	Phone:	432-682-7346
		Conditions of Approval:	Attached <input type="checkbox"/> IRP# 09.16.2366

* Attach Additional Sheets If Necessary

FGRL 0935753973

Microsoft Access - [INCIDENTS]

File Edit RBDMS Reports View Records Admin Window Help

Incidents Date Mod: 12/16/2009

General Spill / Release Photos and Other Document Images

IncidentNo: nLW0935032781 Type: Produced Water Release Source of Referral: Land Owner API Well No: 30-025-07141-00-00 Date: 12/16/2009 UIC Related: Emergency:

Owner: PURVIS OPERATING CO. County: Lea View Incidents in GIS

Legal: H-5-12S 38E 660E - 19801

Well Name: GLADIOLA SWD H Well Type: Salt Water Dis St District: 01

Resp Co: Complainant: Complainant Confidential?

Date	Time
Notified: 12/14/2009	
Response:	
Resolved:	Final Report? <input type="checkbox"/>
Action: Referred to Environmental In	

N Leak on 6" transite trunkline from Aspen.
 o Purvis was directed by OCD to cease
 t useage of this line due to numerous.
 e repetitious leaks in area where ground water
 s depth is 20' bgs.

Record: 14 of 2 (Filtered)

Comments

Start | Inbox - Microsof... | Home - Energy, M... | RBDMS2003 : Dat... | Well Selection Crit... | INCIDENTS | 9:11 AM

Microsoft Access - [INCIDENTS]

File Edit RBDMS Reports View Records Admin Window Help

Inspections Incidents Date Modified: 12/16/2009

General Spill / Release Photos and Other Document Images

IncidentNo: nLWJ093503271 Type: Produced Water Release Source of Referr: Land Owner API Well No: 30-025-07141-00-01 Date: 12/16/2009

Material	Spilled	GAL/BBL	Recover	Lost	Source	Cause
Produced Water	300	BBL	0	300	Pipeline (Any)	Equipment Failure
*		BBL				

Record: 1 of 1

Area Affected

Agng Infrastructure. Area Affected

NOTES - Please include in the notes all information on Volume Reaching the Environment, Wildlife Affected, Contacts, Method of Cleanup, Evidence, and Volume

Dimensions		Areal Extents		Waterway	
Wide	Est	22,500	Sq Ft	<input type="checkbox"/>	Affected?
Long	Calc		Cu Ft	<input type="checkbox"/>	

Leak on 6" transite trunkline from Aspen. Purvis was directed by OCD to cease useage of this line due to numerous, repetitious leaks in area where ground water depth is 20' bgs.

Record: 1 of 2 (Filtered)

Form View NUM

Start Inbox - Micro... Home - Ener... RBDMS2003 ... Well Select... .INCIDENTS Document1 ... 9:16 AM