

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

**RECEIVED**

Form C-141  
Revised March 17, 1999

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

JUL 08 2010

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**HOBBSOCD**

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company Devon Energy	Contact <input type="checkbox"/> Roger Hernandez
Address P. O. Box 250 Artesia, NM 88211	Telephone No. <input type="checkbox"/> 575-748-5238
Facility Name Rio Blanco 33 Federal #1	Facility Type <input type="checkbox"/> Battery

Surface Owner	Mineral Owner	Lease No. <input type="checkbox"/>
---------------	---------------	------------------------------------

**LOCATION OF RELEASE API # 30-025-36359-00-00**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	33	22S	34E	1000	South	1620	West	Lea County NM

**NATURE OF RELEASE**



Type of Release Oil	Volume of Release 80 BO	Volume Recovered <input type="checkbox"/> 77 BO
Source of Release Leak in manway plate	Date and Hour of Occurrence 7-4-10 10:30 AM	Date and Hour of Discovery <input type="checkbox"/> 7-4-10 10:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos (BLM) 12:03 PM Jeff (OCD) 3:48 PM Trishia BadBear (BLM) 3:44 PM	
By Whom? <input type="checkbox"/> Tracy Kidd	Date and Hour <input type="checkbox"/> 7-04-10 3:44 & 3:48 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
N/A  
WATER @ 230'

Describe Cause of Problem and Remedial Action Taken.\*  
Internal corrosion caused a hole to develop in the manway plate resulting in this spill.

Describe Area Affected and Cleanup Action Taken.\*  
Oil was contained in the berm, but the overflow to our location was approximately 15'x40'. Oil was picked up and transferred to the other oil tank, we will rake, and blend new soil to clean up this spill.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Roger Hernandez	Approved by <input type="checkbox"/> District Supervisor: 	ENV. ENGINEER:
Title: Production Foreman	Approval Date: 07/08/10	Expiration Date: 09/08/10
Date: July 7, 2010 Phone: (575) 748-5238	Conditions of Approval: DELIVER TO CLEAN	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

+1. MULTIPLE SAMPLING OF BLENDED SOIL REQUIRED TO ACQUIRE GOOD COMPOSITE. SUBMIT FINAL C-141 BY 09/08/10  
IRP-11-10-2645