






Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18

5. 9. 2005

*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-A*


5.9.2005



A photograph of an industrial site. In the foreground, there is a large, blue, corrugated metal building. A metal walkway with railings extends from the building towards the background. The ground is a mix of dirt and gravel. In the background, there are some trees and a clear sky.


*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-B*

5.9.2005




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-C

5.9.2005




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-D

5-9-2005



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-E

5.9.2005




*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-F*

5.9.2005




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-G

5.9.2005



*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-H*

8.8.2005




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-1

8.8.2005



*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-J*

8.8.2005





*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-K*

8. 8. 2005

Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-L


8.8.2005






*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-M*

8.8.2005




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-N

8-29-2005



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-0

8.29.2005




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-P

8-29-2005


*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-Q*

8.29.2005



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-R

8.29.2005



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-S

8.29.2005

ECO Notification

Date: Friday, July 22, 2005
To: Environmental Compliance Officer, NMOCD District II
From: Chris Beadle
Subject: Levers A State 2 - 30-015-26895



Photo of Tank Battery, collapsed tank and liquids pooling & chloride buildup.



Photo of runoff from tank battery.



Photo of chloride pooling area.



Photo from well area looking back up road to runoff from tank battery.

**Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-T**



Photo of saturated soils at tank battery.



Photo of saturated soils at tank battery.



Photo of oil pooling at tank battery, chloride buildup on left hand tank.



Photo of tank battery runoff.

ECO Notification

Date: Thursday, October 20, 2005
To: Environmental Compliance Officer, NMOCD District II
Subject: Levers A State Tank Battery - Sandlott Energy



Photo of Tank Battery location looking northeast.




Photo of tank battery location looking northwest.



Photo of sample one location, orthwest of tanks.



Photo of sample two location, north of tanks.



Photo of sample three location, northeast of location.



Photo of collapsed tank from the battery-lying northwest of tanks.

Jackie Brewer D/B/A


Sandlott Energy

Case 14074

OCD Exhibit No. 18-V



*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-W*




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-X



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-Y




*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-Z*




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-AA



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-BB



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-CC




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-DD

Sandlott Energy
Levers A St 002
30-015-26895


Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-EE

7.20.2007




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-FF

7.20.2007

A photograph of an oil pumpjack in a desert landscape. The pumpjack is a large, dark metal structure with a long, thin arm extending from a base. The ground is dry, dusty, and covered with sparse, low-lying green and yellow vegetation. In the background, there are more desert plants and a clear sky. A small, dark, rounded object is visible on the ground near the base of the pumpjack. A white rectangular label with black and blue text is overlaid on the right side of the image. A large, orange, semi-transparent date stamp is in the bottom right corner.

*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-GG*

7.20.2007



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-HH

7.20.2007




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-II

7-20-2007



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-JJ

7.20.2007



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-KK

7.20.2007



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-LL

7.20.2007




A photograph showing a blue tarp on the left side, partially covering a light-colored gravel or dirt surface. A dark, irregular, and somewhat circular stain is visible on the gravel, extending from the edge of the tarp. The stain appears to be a spill or residue. The background is a mix of light and dark gravel.

Jackie Brewer D/B/A
Sandlott Energy
Case 14074

OCD Exhibit No. 18-MM


7-20-2007



Jackie Brewer D/B/A
Sandlott Energy

Case 14074
OCD Exhibit No. 18-NN


7.20.2007



Jackie Brewer D/B/A
Sandlott Energy
Case 14074

OCD Exhibit No. 18-00

7.20.2007



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-PP

7-20-2007



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-QQ

7.20.2007




Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-RR

7.20.2007



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-SS



*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-TT*

A photograph showing a trench or excavation site. On the left, a large blue tarp is partially visible, showing some brown stains. A metal pipe or rod runs vertically through the center of the trench. The ground is uneven and appears to be a mix of dirt and gravel. In the background, there are some green bushes and a fence line.


Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-UU




*Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-VV*



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-WW

A photograph showing a close-up of a wellhead or pumpjack assembly. The main vertical pipe is dark and appears to be made of metal. It is surrounded by a network of other pipes, some of which are wrapped in white insulation. The ground is dry, dusty, and uneven. In the background, a portion of a blue structure, possibly a tank or part of the machinery, is visible. The overall scene suggests an industrial or mining environment in an arid region.


Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-XX



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-YY



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-ZZ



Jackie Brewer D/B/A
Sandlott Energy
Case 14074
OCD Exhibit No. 18-AAA

Jackie Brewer D/B/A
Sandlott Energy
Case 14074

OCD Exhibit No. 18-BBB

