



Post Office Box 61229
Houston, Texas 77208-1229

1111 Travis Street
Houston, Texas 77002

Phone: (832) 839-4573
dduffy@hilcorp.com

836

March 1, 2018

Bureau of Land Management
Farmington Resource Area
6251 College Blvd., Suite A
Farmington, NM 87402

Commissioner of Public Lands
State of New Mexico
P. O. Box 1148
Santa Fe, NM 87501-1148

Oil Conservation Division
State of New Mexico
1220 S. Saint Francis Drive
Santa Fe, NM 87505

**2018 PLAN OF DEVELOPMENT
FOR THE HUERFANITO UNIT I SEC. NO. 943
SAN JUAN COUNTY, NEW MEXICO**

Prior to August 1, 2017, ConocoPhillips operated the Huerfanito Unit and submitted a 2017 Plan of Development and Operations ("2017 POD"). Hilcorp Energy Company ("Hilcorp") assumed the role of Unit Operator on August 1, 2017.

Pursuant to Section 10 of the Huerfanito Unit Agreement, Hilcorp, as Unit Operator, hereby submits the proposed 2018 Plan of Development and Operations ("2018 POD").

I. PERIOD

This plan will be effective from April 1, 2018 through March 31, 2019. The 2019 Plan will be submitted on or before March 1, 2019.

II. 2017 PLAN REVIEW OF OPERATIONS

A summary of key activities undertaken after August 1, 2017 include:

A. Production History: During 2017, approximate cumulative production from the Huerfanito Unit was 2.80 gas (BCF); 19.16 oil (MBO); produced water 45 (MBW). Refer to Exhibit "A" attached for a listing of all wells in the Huerfanito Unit.

B. Participating Areas: The Participating Areas currently established in the Huerfanito Unit are:

FORMATION	EXPANSION	EFFECTIVE DATE
DAKOTA	009	01-Nov-11
FRUITLAND COAL	011	01-Mar-07
MANCOS	INTIAL	06-Jun-12
MESAVERDE	006	01-Nov-66
PICTURED CLIFFS	043	01-Mar-06

MAR 01 2018 PM 04:32

C. Drilling Program: The 2017 POD filed by ConocoPhillips provided for no drilling activity. No additional drilling projects were undertaken by Hilcorp during the 2017 period.

D. Workovers/Recompletion Program: Key activities included one (1) workover project and zero (0) recompletes as outlined in the following table:

WELL NAME	API	SEC	TWP	RNG	FORMATION	TYPE
Huerfanito Unit 82	3004535329	25	27	9	DK/MN/MV	Lower Tubing

E. Facility Program: The 2017 POD filed by ConocoPhillips provided for no activity. No additional projects were undertaken by Hilcorp during the 2017 period.

F. Plugging & Abandonment Program: The 2017 POD filed by ConocoPhillips provided for no activity. No additional projects were undertaken by Hilcorp during the 2017 period.

III. 2018 PLAN OF DEVELOPMENT AND OPERATIONS

A summary of key activities planned for 2018 includes:

A. Drilling Program: Hilcorp does not anticipate drilling any new wells in the Huerfanito Unit. However, new drill opportunities will be evaluated and executed as they arise.

B. Workovers/Recompletion Program: Hilcorp is evaluating opportunities throughout the unit to maintain and increase production. At this time, no specific projects have been identified. However, new projects will be executed as they arise.

C. Facility Program: Throughout 2018, Hilcorp will conduct routine repairs and replacement of facilities required to maintain and increase field production, including construction of additional gas lift lines and/or gas flow lines, expansion of production facilities(including electrical and piping upgrades), and construction of additional water disposal, injection or processing equipment.

D. Plugging & Abandonment Program: Hilcorp does not anticipate plugging/abandoning any wells in the Huerfanito Unit at this time. Hilcorp will evaluate and implement additional P&A projects as they arise.

In accordance to Section 10 of the Unit Agreement, please provide your approvals by executing and returning a copy of this letter to the undersigned.

Please contact me at (832) 839-4573 if there are any questions regarding this letter.

Sincerely,
HILCORP ENERGY COMPANY



David W. Duffy
L48W Land Manager

cc: Working Interest Owners

BENSON-MONTIN-GREER DRILLING CORP
CHARLES W GAY
CLARIS SENTER
ELIZABETH TURNER CALLOWAY
HILCORP SAN JUAN, LP
J GLENN TURNER JR
J&M RAYMOND LTD
LA PLATA GATHERING SYSTEM INC
LILLY REVOC TRUST AGMT
LORRAYN GAY HACKER
MARY E GLENN
MARY F TURNER JR REV TRUST
MCCONNELL LTD CO
MICHAEL R DIMOND
STOABS OIL CORPORATION
T H MCELVAIN OIL & GAS LLLP
TAMACAM LLC

**HUERFANITO UNIT
2018 PLAN OF DEVELOPMENT APPROVALS**

Bureau of Land Management

Date

New Mexico Oil Conservation Division

Date

New Mexico Commissioner of Public Lands

Date



Huerfanito Unit Exhibit "A"

API #	WELL NAME	POOL/FORMATION	STATUS	ST	COUNTY	SEC	TWP	RGE	QTR	OPERATOR
3004505905	Huerfanito Unit 67	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	12	026N	09W		Hilcorp Energy Company
3004505906	Huerfanito Unit 065	Basin Fruitland Coal	Flowing	NM	San Juan	12	026N	009W	SWSW	Hilcorp Energy Company
3004505916	Huerfanito Unit 092	Basin Dakota	Flowing	NM	San Juan	12	026N	009W	NWSW	Hilcorp Energy Company
3004505944	Huerfanito Unit 066	Basin Fruitland Coal	Flowing	NM	San Juan	12	026N	009W	SENE	Hilcorp Energy Company
3004505962	Huerfanito Unit 064	Ballard Pictured Cliffs	Flowing	NM	San Juan	12	026N	009W	NWNW	Hilcorp Energy Company
3004505963	Huerfanito Unit 091	Basin Dakota	Flowing	NM	San Juan	12	026N	009W	NWNE	Hilcorp Energy Company
3004505965	Huerfanito Unit 062	Ballard Pictured Cliffs	Flowing	NM	San Juan	11	026N	009W	NWNW	Hilcorp Energy Company
3004505966	Huerfanito Unit 070	Basin Fruitland Coal	Flowing	NM	San Juan	10	026N	009W	NENE	Hilcorp Energy Company
3004505967	Huerfanito Unit 63	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	11	026N	09W		Hilcorp Energy Company
3004505968	Huerfanito Unit 069	Ballard Pictured Cliffs	Flowing	NM	San Juan	10	026N	009W	NWNW	Hilcorp Energy Company
3004505970	Huerfanito Unit 080	Basin Dakota	Flowing	NM	San Juan	10	026N	009W	NWNE	Hilcorp Energy Company
3004505972	Huerfanito Unit 081	Basin Dakota	Flowing	NM	San Juan	11	026N	009W	NENE	Hilcorp Energy Company
3004505998	Huerfanito Unit 025	Ballard Pictured Cliffs	Flowing	NM	San Juan	4	026N	009W	SESE	Hilcorp Energy Company
3004505999	Huerfanito Unit 014	Ballard Pictured Cliffs	Flowing	NM	San Juan	1	026N	009W	SWSE	Hilcorp Energy Company
3004506000	Huerfanito Unit 013	Ballard Pictured Cliffs	Flowing	NM	San Juan	1	026N	009W	SESW	Hilcorp Energy Company
3004506002	Huerfanito Unit 21	Ballard Pictured Cliffs	Shut-In	NM	San Juan	3	026N	09W		Hilcorp Energy Company
3004506003	Huerfanito Unit 018	Ballard Pictured Cliffs	Shut-In	NM	San Juan	2	026N	009W	SWSE	Hilcorp Energy Company
3004506004	Huerfanito Unit 17	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	2	026N	09W		Hilcorp Energy Company
3004506008	Huerfanito Unit Np 068	Basin Fruitland Coal	Flowing	NM	San Juan	3	026N	009W	SWSW	Hilcorp Energy Company
3004506015	Huerfanito Unit 060	Basin Dakota	Flowing	NM	San Juan	4	026N	009W	SWSW	Hilcorp Energy Company
3004506023	Huerfanito Unit 087	Basin Dakota	Flowing	NM	San Juan	1	026N	009W	NESW	Hilcorp Energy Company
3004506023	Huerfanito Unit 087	Blanco-Mesaverde	Flowing	NM	San Juan	1	026N	009W	NESW	Hilcorp Energy Company
3004506030	Huerfanito Unit 024	Ballard Pictured Cliffs	Flowing	NM	San Juan	4	026N	009W	NESW	Hilcorp Energy Company
3004506045	Huerfanito Unit 061	Basin Dakota	Flowing	NM	San Juan	4	026N	009W	SWNE	Hilcorp Energy Company
3004506050	Huerfanito Unit 020	Ballard Pictured Cliffs	Flowing	NM	San Juan	3	026N	009W	SWNW	Hilcorp Energy Company
3004506052	Huerfanito Unit 22	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	4	026N	09W		Hilcorp Energy Company
3004506053	Huerfanito Unit 076	Basin Dakota	Flowing	NM	San Juan	2	026N	009W	SWNE	Hilcorp Energy Company
3004506063	Huerfanito Unit 011	Ballard Pictured Cliffs	Flowing	NM	San Juan	1	026N	009W	NENE	Hilcorp Energy Company
3004506068	Huerfanito Unit 019	Basin Fruitland Coal	Flowing	NM	San Juan	3	026N	009W	SENE	Hilcorp Energy Company
3004506069	Huerfanito Unit 012	Ballard Pictured Cliffs	Flowing	NM	San Juan	1	026N	009W	NWNW	Hilcorp Energy Company
3004506070	Huerfanito Unit 015	Ballard Pictured Cliffs	Flowing	NM	San Juan	2	026N	009W	NENE	Hilcorp Energy Company
3004506071	Huerfanito Unit 016	Ballard Pictured Cliffs	Flowing	NM	San Juan	2	026N	009W	NWNW	Hilcorp Energy Company
3004506072	Huerfanito Unit 023	Ballard Pictured Cliffs	Flowing	NM	San Juan	4	026N	009W	NENW	Hilcorp Energy Company
3004506072	Huerfanito Unit 023	Basin Fruitland Coal	Flowing	NM	San Juan	4	026N	009W	NENW	Hilcorp Energy Company
3004506076	Huerfanito Unit 71	Basin Dakota	Perm Abandoned	NM	San Juan	3	026N	09W		Hilcorp Energy Company
3004506076	Huerfanito Unit 71	Blanco Mesaverde	Perm Abandoned	NM	San Juan	3	026N	09W		Hilcorp Energy Company
3004506076	Huerfanito Unit 71	Basin Dakota	Perm Abandoned	NM	San Juan	3	026N	09W		Hilcorp Energy Company
3004506092	Huerfanito Unit 051	Basin Fruitland Coal	Flowing	NM	San Juan	36	027N	009W	SESW	Hilcorp Energy Company
3004506094	Huerfanito Unit 52	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	36	027N	09W		Hilcorp Energy Company
3004506097	Huerfanito Unit 030	Ballard Pictured Cliffs	Flowing	NM	San Juan	35	027N	009W	SESE	Hilcorp Energy Company
3004506100	Huerfanito Unit 029	Basin Fruitland Coal	Flowing	NM	San Juan	35	027N	009W	SWSW	Hilcorp Energy Company
3004506102	Huerfanito Unit 28	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	34	027N	09W		Hilcorp Energy Company
3004506107	Huerfanito Unit 26	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	33	027N	09W		Hilcorp Energy Company
3004506111	Huerfanito Unit 027	Ballard Pictured Cliffs	Flowing	NM	San Juan	34	027N	009W	SWSW	Hilcorp Energy Company
3004506129	Huerfanito Unit 086	Basin Dakota	Flowing	NM	San Juan	36	027N	009W	NWSW	Hilcorp Energy Company
3004506129	Huerfanito Unit 086	Blanco-Mesaverde	Flowing	NM	San Juan	36	027N	009W	NWSW	Hilcorp Energy Company
3004506132	Huerfanito Unit 31	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	33	027N	09W		Hilcorp Energy Company
3004506147	Huerfanito Unit 34	Fulcher-Kutz Pictured Cliffs	Perm Abandoned	NM	San Juan	34	027N	09W		Hilcorp Energy Company
3004506148	Huerfanito Unit 74	Basin Dakota	Perm Abandoned	NM	San Juan	34	027N	09W		Hilcorp Energy Company
3004506153	Huerfanito Unit 33	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	33	027N	09W		Hilcorp Energy Company
3004506154	Huerfanito Unit 036	Ballard Pictured Cliffs	Flowing	NM	San Juan	35	027N	009W	SWNW	Hilcorp Energy Company
3004506155	Huerfanito Unit 049	Ballard Pictured Cliffs	Flowing	NM	San Juan	35	027N	009W	SWNE	Hilcorp Energy Company
3004506159	Huerfanito Unit 050	Basin Fruitland Coal	Flowing	NM	San Juan	36	027N	009W	SWNW	Hilcorp Energy Company
3004506163	Huerfanito Unit 073	Basin Dakota	Flowing	NM	San Juan	33	027N	009W	SENE	Hilcorp Energy Company

3004506177	Huerfanito Unit 078	Basin Dakota	Flowing	NM	San Juan	36	027N	009W	NWNE	Hilcorp Energy Company
3004506177	Huerfanito Unit 078	Blanco-Mesaverde	Flowing	NM	San Juan	36	027N	009W	NWNE	Hilcorp Energy Company
3004506179	Huerfanito Unit 010	Blanco P. C. South	Flowing	NM	San Juan	36	027N	009W	NENE	Hilcorp Energy Company
3004506181	Huerfanito Unit NP 32	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	33	027N	09W		Hilcorp Energy Company
3004506184	Huerfanito Unit 035	Ballard Pictured Cliffs	Flowing	NM	San Juan	34	027N	009W	NENE	Hilcorp Energy Company
3004506206	Huerfanito Unit 46	Blanco S Pictured Cliffs	Perm Abandoned	NM	San Juan	25	027N	09W		Hilcorp Energy Company
3004506209	Huerfanito Unit 85	Basin Dakota	Perm Shut-In	NM	San Juan	26	027N	09W		Hilcorp Energy Company
3004506209	Huerfanito Unit 85	Blanco Mesaverde	Perm Shut-In	NM	San Juan	26	027N	09W		Hilcorp Energy Company
3004506216	Huerfanito Unit 38	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	28	027N	09W		Hilcorp Energy Company
3004506226	Huerfanito Unit 072	Basin Fruitland Coal	Flowing	NM	San Juan	28	027N	009W	NESW	Hilcorp Energy Company
3004506228	Huerfanito Unit 40	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	27	027N	09W		Hilcorp Energy Company
3004506229	Huerfanito Unit 39	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	27	027N	09W		Hilcorp Energy Company
3004506251	Huerfanito Unit 42	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	27	027N	09W		Hilcorp Energy Company
3004506256	Huerfanito Unit 083	Basin Dakota	Flowing	NM	San Juan	28	027N	009W	SENE	Hilcorp Energy Company
3004506261	Huerfanito Unit 079	Basin Dakota	Flowing	NM	San Juan	26	027N	009W	SENE	Hilcorp Energy Company
3004506261	Huerfanito Unit 079	Blanco-Mesaverde	Flowing	NM	San Juan	26	027N	009W	SENE	Hilcorp Energy Company
3004506270	Huerfanito Unit 47	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	27	027N	09W		Hilcorp Energy Company
3004506283	Huerfanito Unit 94	Blanco S Pictured Cliffs	Perm Abandoned	NM	San Juan	26	027N	09W		Hilcorp Energy Company
3004506286	Huerfanito Unit 041	Fulcher Kutz Pictured Cliffs	Flowing	NM	San Juan	28	027N	009W	NWNE	Hilcorp Energy Company
3004506314	Huerfanito Unit 54	Blanco S Pictured Cliffs	Perm Abandoned	NM	San Juan	22	027N	09W		Hilcorp Energy Company
3004506320	Huerfanito Unit 45	Blanco S Pictured Cliffs	Perm Abandoned	NM	San Juan	24	027N	09W		Hilcorp Energy Company
3004506344	Huerfanito Unit 089	Basin Dakota	Flowing	NM	San Juan	23	027N	009W	NWSW	Hilcorp Energy Company
3004506351	Huerfanito Unit 55	Blanco S Pictured Cliffs	Perm Abandoned	NM	San Juan	23	027N	09W		Hilcorp Energy Company
3004506352	Huerfanito Unit 43	Fulcher-Kutz Pictured Cliffs	Perm Abandoned	NM	San Juan	22	027N	09W		Hilcorp Energy Company
3004506356	Huerfanito Unit 097	Basin Dakota	Flowing	NM	San Juan	24	027N	009W	NWSW	Hilcorp Energy Company
3004506358	Huerfanito Unit 077	Otero Chacra	Flowing	NM	San Juan	24	027N	009W	NESW	Hilcorp Energy Company
3004506358	Huerfanito Unit 077	Blanco P. C. South	Flowing	NM	San Juan	24	027N	009W	NESW	Hilcorp Energy Company
3004506377	Huerfanito Unit 075	Basin Dakota	Flowing	NM	San Juan	22	027N	009W	SWNW	Hilcorp Energy Company
3004506381	Huerfanito Unit 059	Blanco P. C. South	Flowing	NM	San Juan	23	027N	009W	SWNW	Hilcorp Energy Company
3004506383	Huerfanito Unit 44	Fulcher-Kutz Pictured Cliffs	Perm Abandoned	NM	San Juan	22	027N	09W		Hilcorp Energy Company
3004506399	Huerfanito Unit 095	Blanco P. C. South	Flowing	NM	San Juan	24	027N	009W	NWNW	Hilcorp Energy Company
3004506400	Huerfanito Unit 056	Blanco P. C. South	Flowing	NM	San Juan	23	027N	009W	NWNE	Hilcorp Energy Company
3004506410	Huerfanito Unit 88	Basin Dakota	Perm Abandoned	NM	San Juan	23	027N	09W		Hilcorp Energy Company
3004506410	Huerfanito Unit 88	Blanco Mesaverde	Perm Abandoned	NM	San Juan	23	027N	09W		Hilcorp Energy Company
3004511704	Huerfanito Unit 103	Basin Dakota	Flowing	NM	San Juan	3	026N	009W	SESW	Hilcorp Energy Company
3004511727	Huerfanito Unit 106	Ballard Pictured Cliffs	Flowing	NM	San Juan	2	026N	009W	SWSW	Hilcorp Energy Company
3004511766	Huerfanito Unit 101	Blanco-Mesaverde	Flowing	NM	San Juan	2	026N	009W	NENE	Hilcorp Energy Company
3004511783	Huerfanito Unit 100	Blanco Mesaverde	Perm Abandoned	NM	San Juan	34	027N	09W		Hilcorp Energy Company
3004511807	Huerfanito Unit 105	Basin Dakota	Flowing	NM	San Juan	27	027N	009W	NENE	Hilcorp Energy Company
3004511816	Huerfanito Unit 104	Basin Dakota	Flowing	NM	San Juan	27	027N	009W	SWSW	Hilcorp Energy Company
3004511824	Huerfanito Unit 99	Basin Dakota	Perm Abandoned	NM	San Juan	35	027N	09W		Hilcorp Energy Company
3004511824	Huerfanito Unit 99	Blanco Mesaverde	Perm Abandoned	NM	San Juan	35	027N	09W		Hilcorp Energy Company
3004511875	Huerfanito Unit 102	Basin Dakota	Flowing	NM	San Juan	34	027N	009W	SWSW	Hilcorp Energy Company
3004511903	Huerfanito Unit 084	Basin Dakota	Flowing	NM	San Juan	33	027N	009W	NESW	Hilcorp Energy Company
3004511904	Huerfanito Unit 098	Basin Dakota	Flowing	NM	San Juan	35	027N	009W	SWNE	Hilcorp Energy Company
3004511904	Huerfanito Unit 098	Blanco-Mesaverde	Flowing	NM	San Juan	35	027N	009W	SWNE	Hilcorp Energy Company
3004512051	Huerfanito Unit 96	Basin Dakota	Perm Abandoned	NM	San Juan	22	027N	09W		Hilcorp Energy Company
3004512051	Huerfanito Unit 96	Basin Dakota	Perm Abandoned	NM	San Juan	22	027N	09W		Hilcorp Energy Company
3004512189	Huerfanito Unit 082	Basin Dakota	Flowing	NM	San Juan	25	027N	009W	NWSW	Hilcorp Energy Company
3004512189	Huerfanito Unit 082	Blanco-Mesaverde	Flowing	NM	San Juan	25	027N	009W	NWSW	Hilcorp Energy Company
3004512189	Huerfanito Unit 082	Otero Chacra	Flowing	NM	San Juan	25	027N	009W	NWSW	Hilcorp Energy Company
3004513239	Huerfanito Unit 048	Ballard Pictured Cliffs	Flowing	NM	San Juan	26	027N	009W	NWSW	Hilcorp Energy Company
3004513365	Huerfanito Unit 093	Basin Fruitland Coal	Flowing	NM	San Juan	25	027N	009W	NWNW	Hilcorp Energy Company
3004513473	Huerfanito Unit 057	Blanco P. C. South	Flowing	NM	San Juan	23	027N	009W	NWSE	Hilcorp Energy Company
3004523444	Huerfanito Unit 087A	Blanco-Mesaverde	Flowing	NM	San Juan	1	026N	009W	SENE	Hilcorp Energy Company
3004523447	Huerfanito Unit 086A	Blanco-Mesaverde	Flowing	NM	San Juan	36	027N	009W	NENW	Hilcorp Energy Company
3004523912	Huerfanito Unit 063R	Ballard Pictured Cliffs	Flowing	NM	San Juan	11	026N	009W	SENE	Hilcorp Energy Company
3004525383	Huerfanito Unit 077A	Blanco-Mesaverde	Flowing	NM	San Juan	24	027N	009W	NENW	Hilcorp Energy Company
3004527161	Huerfanito Unit 167	Basin Fruitland Coal	Flowing	NM	San Juan	2	026N	009W	NENE	Hilcorp Energy Company

3004527162	Huerfanito Unit 151	Basin Fruitland Coal	Flowing	NM	San Juan	36	027N	009W	NENE	Hilcorp Energy Company
3004527187	Huerfanito Unit 150	Basin Fruitland Coal	Flowing	NM	San Juan	1	026N	009W	SENE	Hilcorp Energy Company
3004527202	Huerfanito Unit Np 154	Basin Fruitland Coal	Flowing	NM	San Juan	34	027N	009W	SENE	Hilcorp Energy Company
3004528946	Huerfanito Unit 098M	Basin Fruitland Coal	Flowing	NM	San Juan	35	027N	009W	SWSE	Hilcorp Energy Company
3004528948	Huerfanito Unit 79	Blanco Mesaverde	Perm Abandoned	NM	San Juan	26	027N	09W		Hilcorp Energy Company
3004528948	Huerfanito Unit 79M	Basin Dakota	Perm Abandoned	NM	San Juan	26	027N	09W		Hilcorp Energy Company
3004528948	Huerfanito Unit 79M	Blanco Mesaverde	Perm Abandoned	NM	San Juan	26	027N	09W		Hilcorp Energy Company
3004528948	Huerfanito Unit 79M	Basin Dakota	Perm Abandoned	NM	San Juan	26	027N	09W		Hilcorp Energy Company
3004528971	Huerfanito Unit 078M	Basin Dakota	Flowing	NM	San Juan	36	027N	009W	NESE	Hilcorp Energy Company
3004528971	Huerfanito Unit 078M	Basin Fruitland Coal	Flowing	NM	San Juan	36	027N	009W	NESE	Hilcorp Energy Company
3004528977	Huerfanito Unit 082M	Otero Chacra	Flowing	NM	San Juan	25	027N	009W	NWNW	Hilcorp Energy Company
3004529386	Huerfanito Unit 153	Basin Fruitland Coal	Flowing	NM	San Juan	2	026N	009W	NWSW	Hilcorp Energy Company
3004529409	Huerfanito Unit 152	Basin Fruitland Coal	Flowing	NM	San Juan	1	026N	009W	SWSW	Hilcorp Energy Company
3004529432	Huerfanito Unit 155	Basin Fruitland Coal	Flowing	NM	San Juan	11	026N	009W	NWNE	Hilcorp Energy Company
3004529436	Huerfanito Unit 070R	Ballard Pictured Cliffs	Flowing	NM	San Juan	10	026N	009W	SWNE	Hilcorp Energy Company
3004529691	Huerfanito Unit 51R	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	36	027N	09W		Hilcorp Energy Company
3004529728	Huerfanito Unit 19R	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	3	026N	09W		Hilcorp Energy Company
3004529731	Huerfanito Unit 065R	Ballard Pictured Cliffs	Flowing	NM	San Juan	12	026N	009W	SWSW	Hilcorp Energy Company
3004529885	Huerfanito Unit Com 174	Basin Fruitland Coal	Flowing	NM	San Juan	24	027N	009W	SESE	Hilcorp Energy Company
3004529901	Huerfanito Unit 066R	Ballard Pictured Cliffs	Flowing	NM	San Juan	12	026N	009W	SENE	Hilcorp Energy Company
3004530480	Huerfanito Unit 045R	Blanco P. C. South	Flowing	NM	San Juan	24	027N	009W	SWSW	Hilcorp Energy Company
3004530503	Huerfanito Unit 169	Basin Fruitland Coal	Perm Abandoned	NM	San Juan	34	027N	09W		Hilcorp Energy Company
3004530510	Huerfanito Unit 093R	Blanco P. C. South	Flowing	NM	San Juan	25	027N	009W	NWNW	Hilcorp Energy Company
3004530512	Huerfanito Unit 52R	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	36	027N	09W		Hilcorp Energy Company
3004530537	Huerfanito Unit 046R	Blanco P. C. South	Flowing	NM	San Juan	25	027N	009W	SWSW	Hilcorp Energy Company
3004530793	Huerfanito Unit 22R	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	4	026N	09W		Hilcorp Energy Company
3004530845	Huerfanito Unit 94R	Blanco S. Pictured Cliffs	Shut-In	NM	San Juan	26	027N	09W		Hilcorp Energy Company
3004530863	Huerfanito Unit 040R	Ballard Pictured Cliffs	Flowing	NM	San Juan	27	027N	009W	NESE	Hilcorp Energy Company
3004530864	Huerfanito Unit 34R	Ballard Pictured Cliffs	Temp Abandoned	NM	San Juan	34	027N	09W		Hilcorp Energy Company
3004530865	Huerfanito Unit 26R	Ballard Pictured Cliffs	Perm Abandoned	NM	San Juan	33	027N	09W		Hilcorp Energy Company
3004530940	Huerfanito Unit Com 552	Basin Fruitland Coal	Flowing	NM	San Juan	24	027N	009W	SENE	Hilcorp Energy Company
3004531048	Huerfanito Unit 015J	Ballard Pictured Cliffs	Flowing	NM	San Juan	2	026N	009W	SWNE	Hilcorp Energy Company
3004531840	Huerfanito Unit 087M	Basin Dakota	Flowing	NM	San Juan	1	026N	009W	NWSE	Hilcorp Energy Company
3004531840	Huerfanito Unit 087M	Blanco-Mesaverde	Flowing	NM	San Juan	1	026N	009W	NWSE	Hilcorp Energy Company
3004532226	Huerfanito Unit 023R	Ballard Pictured Cliffs	Flowing	NM	San Juan	4	026N	009W	SENE	Hilcorp Energy Company
3004532978	Huerfanito Unit 076E	Basin Dakota	Flowing	NM	San Juan	2	026N	009W	SENE	Hilcorp Energy Company
3004532978	Huerfanito Unit 076E	Blanco-Mesaverde	Flowing	NM	San Juan	2	026N	009W	SENE	Hilcorp Energy Company
3004533063	Huerfanito Unit 175	Blanco P. C. South	Flowing	NM	San Juan	26	027N	009W	SWSE	Hilcorp Energy Company
3004533063	Huerfanito Unit 175	Basin Fruitland Coal	Flowing	NM	San Juan	26	027N	009W	SWSE	Hilcorp Energy Company
3004533565	Huerfanito Unit 080E	Basin Dakota	Flowing	NM	San Juan	10	026N	009W	NENE	Hilcorp Energy Company
3004533567	Huerfanito Unit 081F	Basin Dakota	Flowing	NM	San Juan	11	026N	009W	NWNE	Hilcorp Energy Company
3004533600	Huerfanito Unit 092F	Basin Dakota	Flowing	NM	San Juan	12	026N	009W	SESE	Hilcorp Energy Company
3004533605	Huerfanito Unit 176	Basin Fruitland Coal	Flowing	NM	San Juan	26	027N	009W	SESE	Hilcorp Energy Company
3004533627	Huerfanito Unit 047R	Ballard Pictured Cliffs	Flowing	NM	San Juan	27	027N	009W	NENE	Hilcorp Energy Company
3004533627	Huerfanito Unit 047R	Basin Fruitland Coal	Flowing	NM	San Juan	27	027N	009W	NENE	Hilcorp Energy Company
3004533628	Huerfanito Unit 039R	Ballard Pictured Cliffs	Flowing	NM	San Juan	27	027N	009W	SWSW	Hilcorp Energy Company
3004533628	Huerfanito Unit 039R	Basin Fruitland Coal	Flowing	NM	San Juan	27	027N	009W	SWSW	Hilcorp Energy Company
3004533739	Huerfanito Unit 074R	Basin Dakota	Flowing	NM	San Juan	34	027N	009W	NENE	Hilcorp Energy Company
3004533741	Huerfanito Unit 091E	Basin Dakota	Flowing	NM	San Juan	12	026N	009W	SENE	Hilcorp Energy Company
3004533770	Huerfanito Unit 091F	Basin Dakota	Flowing	NM	San Juan	12	026N	009W	NWNW	Hilcorp Energy Company
3004533780	Huerfanito Unit 081E	Basin Dakota	Flowing	NM	San Juan	11	026N	009W	NWNW	Hilcorp Energy Company
3004533896	Huerfanito Unit 103E	Basin Dakota	Flowing	NM	San Juan	3	026N	009W	SWNW	Hilcorp Energy Company
3004534199	Huerfanito Unit 088R	Basin Dakota	Flowing	NM	San Juan	23	027N	009W	SENE	Hilcorp Energy Company
3004534199	Huerfanito Unit 088R	Blanco-Mesaverde	Flowing	NM	San Juan	23	027N	009W	SENE	Hilcorp Energy Company
3004534254	Huerfanito Unit 090M	Basin Dakota	Flowing	NM	San Juan	1	026N	009W	SENE	Hilcorp Energy Company
3004534254	Huerfanito Unit 090M	Blanco-Mesaverde	Flowing	NM	San Juan	1	026N	009W	SENE	Hilcorp Energy Company
3004534342	Huerfanito Unit 078N	Basin Dakota	Flowing	NM	San Juan	36	027N	009W	SENE	Hilcorp Energy Company
3004534342	Huerfanito Unit 078N	Blanco-Mesaverde	Flowing	NM	San Juan	36	027N	009W	SENE	Hilcorp Energy Company
3004534393	Huerfanito Unit 080F	Basin Dakota	Flowing	NM	San Juan	10	026N	009W	NWNW	Hilcorp Energy Company

3004534399	Huerfanito Unit 090E	Basin Dakota	Flowing	NM	San Juan	1	026N	009W	SWNW	Hilcorp Energy Company
3004534410	Huerfanito Unit 081G	Basin Dakota	Flowing	NM	San Juan	11	026N	009W	SENE	Hilcorp Energy Company
3004534411	Huerfanito Unit 061E	Basin Dakota	Flowing	NM	San Juan	4	026N	009W	NENE	Hilcorp Energy Company
3004534413	Huerfanito Unit 103F	Basin Dakota	Flowing	NM	San Juan	3	026N	009W	NWSW	Hilcorp Energy Company
3004534439	Huerfanito Unit 060E	Basin Dakota	Flowing	NM	San Juan	4	026N	009W	NWSW	Hilcorp Energy Company
3004534559	Huerfanito Unit 47S Ftc	Basin Fruitland Coal	Perm Abandoned	NM	San Juan	27	027N	09W		Hilcorp Energy Company
3004534572	Huerfanito Unit 98S	Basin Fruitland Coal	Perm Abandoned	NM	San Juan	35	027N	09W		Hilcorp Energy Company
3004534590	Huerfanito Unit 029S	Basin Fruitland Coal	Flowing	NM	San Juan	35	027N	009W	SENE	Hilcorp Energy Company
3004534592	Huerfanito Unit 039S	Basin Fruitland Coal	Flowing	NM	San Juan	27	027N	009W	NWNW	Hilcorp Energy Company
3004534604	Huerfanito Unit 075E	Basin Dakota	Flowing	NM	San Juan	22	027N	009W	NENE	Hilcorp Energy Company
3004534651	Huerfanito Unit 177	Basin Fruitland Coal	Flowing	NM	San Juan	28	027N	009W	SENE	Hilcorp Energy Company
3004534662	Huerfanito Unit 087E	Basin Dakota	Flowing	NM	San Juan	1	026N	009W	SWSE	Hilcorp Energy Company
3004534690	Huerfanito Unit 096E	Basin Dakota	Flowing	NM	San Juan	22	027N	009W	SWNE	Hilcorp Energy Company
3004534695	Huerfanito Unit 083E	Basin Dakota	Flowing	NM	San Juan	28	027N	009W	NWNE	Hilcorp Energy Company
3004534705	Huerfanito Unit 050E	Basin Dakota	Flowing	NM	San Juan	36	027N	009W	SWNW	Hilcorp Energy Company
3004534705	Huerfanito Unit 050E	Blanco-Mesaverde	Flowing	NM	San Juan	36	027N	009W	SWNW	Hilcorp Energy Company
3004534780	Huerfanito Unit 93S	Basin Fruitland Coal	Perm Abandoned	NM	San Juan	25	027N	09W		Hilcorp Energy Company
3004534809	Huerfanito Unit 106M	Basin Dakota	Flowing	NM	San Juan	2	026N	009W	NESW	Hilcorp Energy Company
3004534809	Huerfanito Unit 106M	Blanco-Mesaverde	Flowing	NM	San Juan	2	026N	009W	NESW	Hilcorp Energy Company
3004534838	Huerfanito Unit 076M	Basin Dakota	Flowing	NM	San Juan	2	026N	009W	NWNW	Hilcorp Energy Company
3004534838	Huerfanito Unit 076M	Blanco-Mesaverde	Flowing	NM	San Juan	2	026N	009W	NWNW	Hilcorp Energy Company
3004534872	Huerfanito Unit 087N	Basin Dakota	Flowing	NM	San Juan	1	026N	009W	NWSW	Hilcorp Energy Company
3004534872	Huerfanito Unit 087N	Blanco-Mesaverde	Flowing	NM	San Juan	1	026N	009W	NWSW	Hilcorp Energy Company
3004534950	Huerfanito Unit 079N	Basin Dakota	Flowing	NM	San Juan	26	027N	009W	SESE	Hilcorp Energy Company
3004534950	Huerfanito Unit 079N	Basin Mancos	Flowing	NM	San Juan	26	027N	009W	SESE	Hilcorp Energy Company
3004534950	Huerfanito Unit 079N	Blanco-Mesaverde	Flowing	NM	San Juan	26	027N	009W	SESE	Hilcorp Energy Company
3004535257	Huerfanito Unit 099E	Basin Dakota	Flowing	NM	San Juan	35	027N	009W	SENE	Hilcorp Energy Company
3004535257	Huerfanito Unit 099E	Basin Mancos	Flowing	NM	San Juan	35	027N	009W	SENE	Hilcorp Energy Company
3004535257	Huerfanito Unit 099E	Blanco-Mesaverde	Flowing	NM	San Juan	35	027N	009W	SENE	Hilcorp Energy Company
3004535262	Huerfanito Unit 098N	Basin Dakota	Flowing	NM	San Juan	35	027N	009W	NESE	Hilcorp Energy Company
3004535262	Huerfanito Unit 098N	Blanco-Mesaverde	Flowing	NM	San Juan	35	027N	009W	NESE	Hilcorp Energy Company
3004535267	Huerfanito Unit 088N	Basin Dakota	Flowing	NM	San Juan	23	027N	009W	NWSE	Hilcorp Energy Company
3004535267	Huerfanito Unit 088N	Basin Mancos	Flowing	NM	San Juan	23	027N	009W	NWSE	Hilcorp Energy Company
3004535267	Huerfanito Unit 088N	Blanco-Mesaverde	Flowing	NM	San Juan	23	027N	009W	NWSE	Hilcorp Energy Company
3004535287	Huerfanito Unit 085M	Basin Dakota	Flowing	NM	San Juan	26	027N	009W	NENW	Hilcorp Energy Company
3004535287	Huerfanito Unit 085M	Basin Mancos	Flowing	NM	San Juan	26	027N	009W	NENW	Hilcorp Energy Company
3004535287	Huerfanito Unit 085M	Blanco-Mesaverde	Flowing	NM	San Juan	26	027N	009W	NENW	Hilcorp Energy Company
3004535310	Huerfanito Unit 082N	Basin Dakota	Flowing	NM	San Juan	25	027N	009W	SWSW	Hilcorp Energy Company
3004535310	Huerfanito Unit 082N	Basin Mancos	Flowing	NM	San Juan	25	027N	009W	SWSW	Hilcorp Energy Company
3004535310	Huerfanito Unit 082N	Blanco-Mesaverde	Flowing	NM	San Juan	25	027N	009W	SWSW	Hilcorp Energy Company
3004535329	Huerfanito Unit 082P	Basin Dakota	Flowing	NM	San Juan	25	027N	009W	SWNW	Hilcorp Energy Company
3004535329	Huerfanito Unit 082P	Basin Mancos	Flowing	NM	San Juan	25	027N	009W	SWNW	Hilcorp Energy Company
3004535329	Huerfanito Unit 082P	Blanco-Mesaverde	Flowing	NM	San Juan	25	027N	009W	SWNW	Hilcorp Energy Company
3004560296	Huerfanito Unit 090	Basin Dakota	Flowing	NM	San Juan	1	026N	009W	NWNE	Hilcorp Energy Company
3004560296	Huerfanito Unit 090	Blanco-Mesaverde	Flowing	NM	San Juan	1	026N	009W	NWNE	Hilcorp Energy Company