

HALLIBURTON SERVICES

JOB SUMMARY

IN 1011

HALLIBURTON LOCATION

LEACH CO.

BILLED ON TICKET NO. 152642

WELL DATA

SEC.	TWP.	RNG.	COUNTY	STATE
INFORMATION NAME _____ TYPE _____ INFORMATION THICKNESS _____ FROM _____ TO _____ AL PROD: OIL _____ BPD: GAS _____ MCFD _____ ENT PROD: OIL _____ MCFD _____ PLEATION DATE _____ ER TYPE _____ TOM HOLE TEMP. _____ PRESSURE _____ DATA _____ TOTAL DEPTH _____				
CASING	NEW USED	WEIGHT	SIZE	FROM TO MAXIMUM PSI ALLOWABLE
LINER				
TUBING				
OPEN HOLE				SHOTS/FT.
PERFORATIONS				
PERFORATIONS				
PERFORATIONS				

ILLEGIBLE

JOB DATA

5/11- TOOLS AND ACCESSORIES 11046

TYPE AND SIZE	QTY.	MAKE
AT COLLAR		
AT SHOE		
IE SHOE	1	
TRALIZERS	1	
TCM PLUG		
PLUG	1	
D		
KEB		
ER		

CALLER OUT	ON LOCATION	JOB STARTED	JOB COMPLETED
DATE 5/11/85 TIME 20:00	DATE 5/12/85 TIME 09:00	DATE 5/12/85 TIME 20:45	DATE 5/12/85 TIME 22:00

PERSONNEL AND SERVICE UNITS

NAME	UNIT NO. & TYPE	LOCATION
G. HELSEL	4124	LAMARCO
P. FILMER	0471	
C. ASLEY	32669	

MATERIALS

AT. FLUID	DENSITY	LB/GAL. API
L. FLUID	DENSITY	LB/GAL. API
P. TYPE	SIZE	LB.
P. TYPE	SIZE	LB.
P. TYPE	GAL.	%
P. TYPE	GAL.	%
P. TYPE	GAL.	%
FACTANT TYPE	GAL.	IN
AGENT TYPE	GAL.	IN
ID LOSS ADD. TYPE	GAL.-LB.	IN
LINS AGENT TYPE	GAL.-LB.	IN
D. RED. AGENT TYPE	GAL.-LB.	IN
AKER TYPE	GAL.-LB.	IN
CKING AGENT TYPE	GAL.-LB.	
PPAC BAG TYPE	QTY.	

ER 17046 SUD

DEPARTMENT Int

DESCRIPTION OF JOB 542

JOB DONE THRU: TUBING ☐ CASING ☐ ANNULUS ☐ TBO./ANN. ☐

CUSTOMER REPRESENTATIVE X Billy Williams

HALLIBURTON OPERATOR _____ CCPIES REQUESTED _____

CEMENT DATA

AGE	NUMBER OF SACKS	TYPE	API CLASS	BRAND	BULK SACKED	ADDITIVES	YIELD CU.FT./BK.	MIXED LBS./GAL.
1	242	C		S.G.		570, 150, 6, 270, C, 1, 2, 1/2, 1/4	1.51	141.1

PRESSURES IN PSI

SUMMARY

VOLUMES

CULATING	DISPLACEMENT	FRESH: BBL-GAL.	TYPE
AKDOWN	MAXIMUM	LOAD & BKDN: BBL-GAL.	PAD: BBL-GAL.
CRAGE	RACTURE GRADIENT	TREATMENT: BBL-GAL.	DISPL: BBL-GAL. 52
THIN: INSTANT	5-MIN.	CEMENT SLURRY: BBL-GAL.	
15-MIN.		TOTAL VOLUME: BBL-GAL.	
ERRED	AVAILABLE	USED	REMARKS
AVERAGE RATES IN GPM			
ATING	DISPL	OVERALL	
CEMENT LEFT IN PIPE			
REASON			