

OIL CONSERVATION COMMISSION

P. O. BOX 871

SANTA FE, NEW MEXICO

March 11, 1954

Mrs. Libby Connor  
Iceco, Incorporated  
115 West Center St.  
Tucumcari, New Mexico

Re: Libby #1 SWNE Sec. 31-T 20 N, R 31 E  
Libby #2 SWNW Sec. 32-T 20 N, R 31 E  
DeBaca #2SWNE Sec. 31-T 20 N, R 31 E  
HARDING COUNTY

Dear Mrs. Connor:

We have your letter of March 4 wherein you request information and logs on the above captioned wells. Although our files on these wells are somewhat lacking in such pertinent data I shall endeavor to comply.

Please find enclosed a copy of the log on the Libby #1 well and also some data on the record. This was all submitted to this office on Nov. 19, 1951 by Mr. Frank C. Holden on Form C-105. Also enclosed is a copy of the log on the American Producers Corp. No. 1 well which we assume to be the Libby #2 as it has the same quarter-quarter and section as the latter. This is on file as the State Bureau of Mines & Mineral Resources well log #1259.

The DeBaca #2 well was originally drilled by the Colo-Mex Gas Company, thence transferred to Iceco, Inc. on Dec. 3, 1949. Iceco, finding the 6" casing in this well deteriorated and the hole full of water, in turn ran a string of 5 3/16" casing to a depth of 1989' and cemented some with 294 sacks. This work was done during the interim 11-28-49 to 1-18-50 and the cementing was by Halliburton. Following this the well came in making CO<sub>2</sub> gas at its usual pressure, dry of water and without any surface leaks.

A report on repairs made to the Libby #2 well submitted by Mr. Frank C. Holden and dated Jan. 7, 1952 reflects the following:—"The dates of this work were as follows: 2-5-52. Notice of intention to do the work was not submitted on Form C-102 and approval of the proposed plan was not obtained. DETAILED ACCOUNT OF WORK DONE AND RESULTS OBTAINED: A leak of low pressure gas between 5 1/2" production string and 13 3/4" surface casing was noticed. Halliburton Cementing Company truck #2174 in charge of G. R. Roach was sent for and 180' of 1" tubing inserted between these pipes and 242 sacks of cement were pumped in, completely closing off this gas. Tubing left in hole and cleared in case similar trouble noticed, work can be done from outside again. Suggested by Halliburton."

CONSERVATION COMMISSION

P. O. BOX 871

CHICAGO, ILL. 60601

Dear Sirs:  
Enclosed for you are two copies of a report  
on the work of the Commission during the year  
1960. The report is in two parts, one for the  
public and one for the Commission itself.

The report for the public is a summary of the work of the Commission during the year 1960. It is written in a simple, straightforward manner so that it can be understood by anyone interested in the work of the Commission.

The report for the Commission itself is a more detailed account of the work of the Commission during the year 1960. It is written in a more technical manner and is intended for the use of the Commission in its planning and decision-making.

I am sure that you will find the report for the public very interesting and informative. I am also sure that the report for the Commission itself will be of great value to the Commission in its planning and decision-making.

I am sure that you will find the report for the public very interesting and informative. I am also sure that the report for the Commission itself will be of great value to the Commission in its planning and decision-making.