ubmit 3 Copies		State of New Mexico		Form C-103	
Appropriate	Energy, Minerals, and	Energy, Minerals, and Natural Resources Department		Revised 1-1-89	
strict Office	OH CONCE	NATION DIVIGION			
<u>ISTRICT I</u>	OIL CONSERVATION DIVISION		WELL API NO.		
O. Box 1980, Hobbs, NM 88240 P.O. Box 2088		30-021-200			
O. Drawer DD, Artesia, NM 88210  Santa Fe, New Mexico 87504-2088			5. Indicate Type of Lease STATE FEE		
ISTRICT III			6. State Oil & Gas Lo	ease No.	
000 Rio Brazos Rd., Aztec, NM	87410				
SI	UNDRY NOTICES AND REPOR	RTS ON WELLS			
	FORM FOR PROPOSALS TO DRILL OR TO				
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"			7. Lease Name or Unit Agreement Name		
	(FORM C-101) FOR SUCH PROPOSA	BRAVO DOME CO2 GAS UNIT			
Type of Well OIL GAS GAS			BRAVO DOME CI	UZ GAS UNIT	
WELL		THER CO2			
Name of Operator	8. Well No			-	
AMOCO PRODU	JCTION COMPANY	1932-241G			
Address of Operator 9.			9. Pool name or Wildcat		
P.O. Box 303, AMISTAD, NEW MEXICO 88410			BRAVO DOME CO	BRAVO DOME CO2 GAS UNIT	
Well Location					
Unit Letter G	: 1980 Feet From The	North Line and 1980	Feet From The	East Line	
Section 24	Township 19	N Range 32E NMI	PM Harding	County	
	10. Elevation	(Show whether DF, RKB, RT, GR, etc.) 4690.9 GR		1 L	
Ol al America Denta Indicate Nation of Nation Dental and Other Details					
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data					
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				OF:	
ERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK			ALTE	ERING CASING	
EMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS.			. PLUC	G AND ABANDONMENT	
JLL OR ALTER CASING CASING TEST AND CEMENT JOB					
		¬			
THER:		OTHER:			
Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)  SEE RULE 1103.					
MIRUSU, kill well as necessary, NUBOP, release packer, lay down production tubing and packer, run cast iron bridge plug					
with wireline, set CIBP at 2,266 feet, run workstring, displace casing with mud laden fluid, pressure test casing to 500 psi,					
cap CIBP with 3 sacks of cement, pull workstring to 1,870 feet, spot 7 sacks of cement, pull workstring to 30 feet, fill casing					
with cement, NDBOP, cut off wellhead, install PXA marker, RDMOSU, cut off well anchors and clean location.					
nereby certify that the information above is true and complete to the best of my knowledge and belief.					
SNATURE ()	1 Holioml	TITLE Field Foreman	DATE	8-18-99	
PE OR PRINT NAME	ny J. Holcomb		TELEPHONE	E NO. (505) 374-3010	
his space for State Use)	Jall	grang to park the transport of principalities and		=	
PROVED BY	Ty Cottum	DISTRICT SUPERV	DATE_	8/23/99	
ANDITIONS OF APPROVAL, ** AN	T. 1				