

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals, and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I

P.O. Box 1980, Hobbs, NM 88240

DISTRICT II

P.O. Drawer DD, Artesia, NM 88210

DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

**WELL API NO.**

30-021-20073

**5. Indicate Type of Lease**

STATE ☐

FEE ☐

**6. State Oil & Gas Lease No.**

**7. Lease Name or Unit Agreement Name**

BRAVO DOME CO2 GAS UNIT

**8. Well No.**

1831-221G

**9. Pool name or Wildcat**

BRAVO DOME CO2 GAS UNIT

**SUNDRY NOTICES AND REPORTS ON WELLS**

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A

DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"

(FORM C-101) FOR SUCH PROPOSALS.)

**1. Type of Well**

OIL WELL ☐

GAS  
WELL ☐

OTHER

CO2

**2. Name of Operator**

AMOCO EXPLORATION AND PRODUCTION COMPANY

**3. Address of Operator**

P.O. Box 806, CLAYTON, NEW MEXICO 88415

**4. Well Location**

Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line

Section 22 Township 18N Range 31E NMPM Harding County

**10. Elevation (Show whether DF, RKB, RT, GR, etc.)**

4475 GR

**11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data**

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

**12. Describe Proposed or Completed Operations**  
SEE RULE 1103.

(Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

MIRUSU, Kill well as necessary, NUBOP, Rel pkr, LD production tbg and pkr, Run Cast iron BP with wireline, Set CIBP @ 2049 ft., Run tbg, Disp csg with mud laden fluid, Prs tst csg to 500psi, Cap CIBP with 5 sx cmt, Pull tbg to 1640 ft, Spot 10 sx cmt, Pull tbg to 30ft, Fill csg with cmt, NDBOP, Cut off wellhead, Install PXA marker, RDMOSU, Cut off SU anchors, Clean location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Billy E. Prichard TITLE Operations Specialist

DATE 1/20/98

TYPE OR PRINT NAME B. E. Prichard

TELEPHONE NO. (505) 374-3053

(This space for State Use)

APPROVED BY B. E. Prichard TITLE DISTRICT SUPERVISOR

DATE 2-5-98

CONDITIONS OF APPROVAL, IF ANY: