Submit 3 Copies State of New Mexico	Form C-103
to Appropriate Energy, Minerals, and Natural Resources Department	Revised 1-1-89
District Office	
DISTRICT 1 OIL CONSERVATION DIVISION	WELL API NO.
P.O. Box 1980, Hobbs, NM 88240 P.O. Box 2088	30-021-20104
DISTRICT II Santa Fe, New Mexico 87504-2088	5. Indicate Type of Lease
P.O. Drawer DD, Artesia, NM 88210	STATE FEE
1.O. Dianti DD, Hatolig 141 00210	
<u>DISTRICT III</u>	6. State Oil & Gas Lease No.
1000 Rio Brazos Rd., Aztec, NM 87410	
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well	BRAVO DOME CO2 GAS UNIT
GAS TO	
OIL WELL OTHER CO2	
2. Name of Operator	8. Well No.
AMOCO EXPLORATION AND PRODUCTION COMPANY	1831-161F
3. Address of Operator	9. Pool name or Wildcat
P.O. Box 606, CLAYTON, NEW MEXICO B8415	BRAVO DOME CO2 GAS UNIT
4. Well Location	1090
	1980 Feet From The East Line
Section 16 Township 18N Range 31E	NMPM Harding County
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
4340 GR	
Check Appropriate Box to Indicate Nature of Notic	e Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
It for our remember should be a second by the second state of the	. I ALTERNIO CASINO I II
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP	
	NS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING CASING TEST AND CEMEI	NS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING CASING TEST AND CEMEI OTHER: OTHER:	NS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING CASING TEST AND CEMEN OTHER: 12. Describe Proposed or Completed Operations (Clearly state all partinent details, and give partinent dates, including estimates)	NS. PLUG AND ABANDONMENT
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING CASING TEST AND CEME! OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. CHANGE PLANS COMMENCE DRILLING OP CASING TEST AND CEME! OTHER:	NS. PLUG AND ABANDONMENT NT JOB ated date of starting any proposed work)
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. MIRUSU,Kill well as nessecary,NUBOP,Rel pkr,LD production tbg and pkr,Ru	NS. PLUG AND ABANDONMENT Int JOB Intended date of starting any proposed work) In Cast iron BP with
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. MIRUSU, Kill well as nessecary, NUBOP, Rel pkr, LD production tbg and pkr, Ru wireline, Set CIBP @ 2084ft., Run tbg, Disp csg with mud laden fluid, Prs tst cs	ns. PLUG AND ABANDONMENT Int JOB Interest date of starting any proposed work) In Cast iron BP with g to 500psi,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. MIRUSU, Kill well as nessecary, NUBOP, Rel pkr, LD production tbg and pkr, Ru wireline, Set CIBP @ 2084ft., Run tbg, Disp csg with mud laden fluid, Prs tst cs	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPOULL OR ALTER CASING OTHER: OT	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP CASING TEST AND CEME! OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. MIRUSU, Kill well as nessecary, NUBOP, Rel pkr, LD production tbg and pkr, Ru wireline, Set CIBP @ 2084ft., Run tbg, Disp csg with mud laden fluid, Prs tst cs Cap CIBP with 5 sx cmt, Pull tbg to 1668 ft, Spot 10 sx cmt, Pull tbg to 30ft, Fill NDBOP, Cut off wellhead, Install PXA marker, RDMOSU, Cut off SU anchors, Company of the company	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. MIRUSU, Kill well as nessecary, NUBOP, Rel pkr, LD production tbg and pkr, Ru wireline, Set CIBP @ 2084ft., Run tbg, Disp csg with mud laden fluid, Prs tst cs Cap CIBP with 5 sx cmt, Pull tbg to 1668 ft, Spot 10 sx cmt, Pull tbg to 30ft, Fill NDBOP, Cut off wellhead, Install PXA marker, RDMOSU, Cut off SU anchors, Complete to 15g best of my knowledge and belief.	nt JOB Int
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP CASING TEST AND CEME! OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. MIRUSU, Kill well as nessecary, NUBOP, Rel pkr, LD production tbg and pkr, Ru wireline, Set CIBP @ 2084ft., Run tbg, Disp csg with mud laden fluid, Prs tst cs Cap CIBP with 5 sx cmt, Pull tbg to 1668 ft, Spot 10 sx cmt, Pull tbg to 30ft, Fill NDBOP, Cut off wellhead, Install PXA marker, RDMOSU, Cut off SU anchors, Company of the company	PLUG AND ABANDONMENT Introd date of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt,
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. MIRUSU, Kill well as nessecary, NUBOP, Rel pkr, LD production tbg and pkr, Ru wireline, Set CIBP @ 2084ft., Run tbg, Disp csg with mud laden fluid, Prs tst cs Cap CIBP with 5 sx cmt, Pull tbg to 1668 ft, Spot 10 sx cmt, Pull tbg to 30ft, Fill NDBOP, Cut off wellhead, Install PXA marker, RDMOSU, Cut off SU anchors, Complete to 15g best of my knowledge and belief.	nt JOB Int
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPPULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. MIRUSU, Kill well as nessecary, NUBOP, Rel pkr, LD production tbg and pkr, Ru wireline, Set CIBP @ 2084ft., Run tbg, Disp csg with mud laden fluid, Prs tst cs Cap CIBP with 5 sx cmt, Pull tbg to 1668 ft, Spot 10 sx cmt, Pull tbg to 30ft, Fill NDBOP, Cut off wellhead, Install PXA marker, RDMOSU, Cut off SU anchors, Compared to the state of the second point of the second plant to	PLUG AND ABANDONMENT Introde Introde
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP CASING TEST AND CEME OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. MIRUSU, Kill well as nessecary, NUBOP, Rel pkr, LD production tbg and pkr, Ru wireline, Set CIBP @ 2084ft., Run tbg, Disp csg with mud laden fluid, Prs tst cs Cap CIBP with 5 sx cmt, Pull tbg to 1668 ft, Spot 10 sx cmt, Pull tbg to 30ft, Fill NDBOP, Cut off wellhead, Install PXA marker, RDMOSU, Cut off SU anchors, C Thereby certify that the information above judrue and complete to the best of my knowledge and belief. SIGNATURE TYPE OR PRINTI NAME B. E. Prichard This space for State Use CHANGE PLANS COMMENCE DRILLING OP CASING TEST AND CEME OTHER: OT	PLUG AND ABANDONMENT Interperse of starting any proposed work) In Cast iron BP with g to 500psi, csg with cmt, Clean location DATE 1/20/98 TELEPHONE NO. (505) 374-3053
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OP PULL OR ALTER CASING OTHER: 12. Describe Proposed or Completed Operations SEE RULE 1103. MIRUSU, Kill well as nessecary, NUBOP, Rel pkr, LD production tbg and pkr, Ru wireline, Set CIBP @ 2084ft., Run tbg, Disp csg with mud laden fluid, Prs tst cs Cap CIBP with 5 sx cmt, Pull tbg to 1668 ft, Spot 10 sx cmt, Pull tbg to 30ft, Fill NDBOP, Cut off wellhead, Install PXA marker, RDMOSU, Cut off SU anchors, C This space for State Use Type on Print name B. E. Prichary This space for State Use	PLUG AND ABANDONMENT Introde Introde