Submit 3 Copies to Appropriate

State of New Mexico Energy, Minerais and Natural Resources Department

Form C-103

District Office	
DISTRICT! OIL CONSERVATION DIV	ISION WELL API NO.
P.O. Box 2088	20 021 20112
DISTRICT II P.O. Drawer DD. Artesia, NM 88210 Santa Fe, New Mexico 87504-20	5. Indicate Type of Lease
DISTRICT III	STATE FEE
1000 Rio Brazos Rd., Azzec, NM 87410	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG 6	MARK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"	7. Lease Name or Unit Agreement Name
(FORM C-101) FOR SUCH PROPOSALS.)	Bravo Dome Carbon Dioxide
1. Type of Weil:	Gas Unit
WELL X CO2 OTHER	
2. Name of Operator Amoco Production Company	8. Well No. 1933-111G
3. Address of Operator	9. Pool name or Wildcat
P. O. Box 3092; Houston, Texas 77253 Rm: 20.1	
4. Well Location	
Unit Letter G : 1980 Feet From The North Line	and 1980 Feet From The East Line
11	
Section 11 Township 19N Range	33E NMPM Harding County
4965GL	. GK, etc.)
	Notice Process Of Process
11. Check Appropriate Box to Indicate Nature of NOTICE OF INTENTION TO:	
NOTICE OF INTENTION TO.	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIA	L WORK ALTERING CASING
TEMPORARILY ABANDON CHANGE PLANS COMMEN	
COMMEN	CE DRILLING OPNS. PLUG AND ABANDONMENT
PULL OR ALTER CASING CASING	TEST AND CEMENT JOB
OTHER: Re-perf and repair high casing X OTHER:	TEST AND CEMENT JOB
OTHER: Re-perf and repair high casing X OTHER:	
OTHER: Re-perf and repair high casing X OTHER:	
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103.	ent dates, including estimated date of starting any proposed
OTHER: Re-perf and repair high casing X OTHER: 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2%	ent dates, including estimated date of starting any proposed KCL and additives. Nipple
OTHER: Re-perf and repair high casing X OTHER: pressure. 12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub	KCL and additives. Nipple ing. If necessary, clean out
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374,
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf.
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf.
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhi	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf.
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhi	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf.
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhi	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf.
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhi	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf.
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhi	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf.
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhi	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf.
OTHER: Re-perf and repair high casing The pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tube fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhit 500 psi for 30 minutes. Return well to production.	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf.
OTHER: Re-perf and repair high casing X OTHER: pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhi 500 psi for 30 minutes. Return well to production.	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf. bited fluid and test packer to
OTHER: Re-perf and repair high casing The pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tube fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhit 500 psi for 30 minutes. Return well to production.	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf. bited fluid and test packer to
OTHER: Re-perf and repair high casing pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give portion work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhit 500 psi for 30 minutes. Return well to production. Thereby certify that the information above is true and complete to the best of my knowledge and belief. Man b Re add of A. Admi	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf. bited fluid and test packer to
OTHER: Re-perf and repair high casing pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertine work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tube fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhit 500 psi for 30 minutes. Return well to production. Thereby certify that the information above is true and complete to the boot of my knowledge and belief. Signature Mark Randoff. Title Admit Title Mark D. Randolph	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf. bited fluid and test packer to nistrative Analyst DATE 11/12/91 713/
OTHER: Re-perf and repair high casing pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhi 500 psi for 30 minutes. Return well to production. I hereby certify that the information above a true and complete to the best of my knowledge and belief. Signature Mark Randoff Title Admit Type on FRINTNAME Mark D. Randolph (This space for State Use)	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf. bited fluid and test packer to mistrative Analyst DATE 11/12/91 713/ TELEPHONE NO. 556-3216
OTHER: Re-perf and repair high casing pressure. 12 Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent work) SEE RULE 1103. Move in and rig up service unit. Kill well with 2% up blow out preventor. Release packer and pull tub fill to 2560'. Perforate the following intervals 2 2377-2382, 2387-2394, 2410-2431, 2438-2476, 2482-25 Rerun production equipment. Load annulus with inhi 500 psi for 30 minutes. Return well to production. I hereby certify that the information above is true and complete to the best of my knowledge and belief. Signature Mark Randoff Title Admit Type on FRINTNAME Mark D. Randolph (This space for State Use)	KCL and additives. Nipple ing. If necessary, clean out 342-2346, 2348-2350, 2355-2374, 06, 2523-2534 with 4 jspf. bited fluid and test packer to