Submit 3 Copies to Appropriate	State of New Mexico Energy, Minerals, and Natural Resources Department					Form C-103 Revised 1-1-89				
District Office							Hoalogn I.I.	UJ		
DISTRICT I	OIL CONSERVATION DIVISION				WELI	API NO.	7			
P.O. Box 1980, Hobbs, NM 88240	P.O. Box 2088				30-021-20170					
DISTRICT II P.O. Drawer DD, Artesia, NM 88210	Santa Fe, New Mexico 87504-2088			5. Indic	ate Type of I		EE [
DISTRICT III 1000 Rio Brazos Rd., Aztec, NM 87410					6. State	Oil & Gas I				
SUNDRY NOTICES AND REPORTS ON WELLS (30 NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"					7 Leas	Name or U	-ie A	-4 NI		
l .	(FORM C-101) FOR SUCH PROPOSALS.)				7. Licase	rivallie of O	iii Agreeme	nt Name		
	GAS WELL OT		000		BRA	VO DOME CO2 GA	AS UNIT			
2. Name of Operator	WELL OT-		C02	-	0. XV. 11					
AMOCO PROCUCTION COMPANY						8. Well No. 1933-161G				
3. Address of Operator F.O. Box 303, AMISTAD, NEW MEXICO 88410						9. Pool name or Wildcat BRAVO DOME CO2 GAS UNIT				
4. Well Location Unit Letter G :	1650 Feet From The	NORTH	Line and	1656		D . F				
Section 15	Township 19			1650		Feet From The	EAST	Lin	ie :	
	10 Elevation		Range 33E her DF, RKB, RT, GR, etc.,	NMP:	M	HARDING	<u> </u>	County	**********	
	TO ISICVATION	494:	GL)						
11 Che	eck Appropriate Box to	Indicate	Nature of Notice	ce Reno		Other Date		<u> </u>		
NOTICE OF INT		1	1 millio of 110th							
PERFORM REMEDIAL WORK	PLUG AND ABANDON	n İ		SUBSEQU	ENT KEP	URI UF:				
	<u> </u>	-	REMEDIAL WORK			ALTE	RING CASING			
TEMPORARILY ABANDON	CHANGE PLANS	_	COMMENCE DRILLING O	PNS.		PLUG	AND ABANDONM	ENT		
PULL OR ALTER CASING			CASING TEST AND CEM	ENT JOB						
OTHER:			OTHER:							
12. Describe Proposed or Completed Operati	ons (Clearly state all pertinen	t details, and give	pertinent dates, including estin	mated date of sta	rtina any ora	pased work)	·		느ᆜ	
SEE RULE 1103.						7 0 1 1 1				
MIRUSU,Kill well as necessary, NUBOP,Rel pkr,LD production tbg and packer,Run										
tbg to 2450 ft, Spot 35 sx cmt, Pull tbg, WOC,Run tbg tag cmt. Cmt. should be above										
2416 ft, Prs tst csg to 500psi, disp well with mud laiden fluid. Pull that to 2031 ft Snot 20sy cmt Pull										
tbg to 30 ft and fill csg with cement, NDBOP, Cut off wellhead, Install PXA marker, RD MOSU, Cut off SU anchors and clean location										
mood, out on oo ancho	13 and clean location									
	7 _									
hereby certify that the information above is true an	d complete to the best of my knowledna and t	elief.								
IGNATURE BULL	, E. Truban		erations Specialist			0.175	1 (00.00			
YPE OR PRINT NAME B. E. Prich d			- Loons opecialist	· · · · · · · · · · · · · · · · · · ·			1/20/98			
This space for State Use)	A //					TELEPHONE NO.	(505) 3	174-3053		
PPROVED BY	Wok men	TITLE	SKILT as	ritist Viz	Star of the	DATE 2	-5-98	>		
ONDITIONS OF APPROVAL, IF ANY:		-				DATE	2 10			