ubmit 3 Copies	State of New Mexico Energy, Minerals, and Natural Resources Department			Form C-103
Appropriate strict Office	Ellergy, Millerais, a	iliu Naturai N	esources Department	Revised 1-1-89
ISTRICT I	OIL CONS	ERVATIO	N DIVISION	WELL API NO.
O. Box 1980, Hobbs, NM 88240	M 88240 P.O. Box 2088			30-021-20239
ISTRICT II O. Drawer DD, Artesia. NM 88210	Santa Fe, N	ew Mexico 8	7504-2088	5. Indicate Type of Lease STATE FEE
ISTRICT III 100 Rio Brazos Rd., Aztec, NM 87410				6. State Oil & Gas Lease No.
	RY NOTICES AND REP			
•	NT RESERVOIR. USE "APPLICATI	ION FOR PERMIT		7. Lease Name or Unit Agreement Name
Type of Well	(FORM O TOTAL OCCUPANCE)	007.20.7		BRAVO DOME CO2 GAS UNIT
OIL WELL	GAS WELL	OTHER	CO2	
Name of Operator				8. Well No.
AMOCO PRODUCTIO	ON COMPANY			2033-171G
Address of Operator				9. Pool name or Wildcat
P.O. Box 303, AMIS	STAD, NEW MEXICO	88410		BRAVO DOME CO2 GAS UNIT
Well Location Unit Letter G :	1980 Feet From The	North	Line and 1980	Feet From The East Line
Section 17	Township	20N	Range 33E NMI	PM Harding County
	10. Elevat	ion (Show when 5036	ther DF, RKB, RT, GR, etc.) GR	
Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data				
Type of Well OIL GAS WELL OTHER CO2 Name of Operator AMOCO PRODUCTION COMPANY Address of Operator P.O. Box 303. AMISTAD. NEW MEXICO 88410 Well Location Unit Letter G 1980 Feet From The North Line and 1980 Feet From The East Line Section 17 Township 20N Range 33E NMPM Harding County 10. Elevation (Show whether DF, RRB, RT, GR, etc.) 5036 GR Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: RFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK ALTERING CASING MPORARILY ABANDON CHANGE PLANS COMMENCE DRILLING OPNS. PLUG AND ABANDONMENT ALTER CASING CASING TEST AND CEMENT JOB HER: OTHER CO2				
ERFORM REMEDIAL WORK	PLUG AND ABANDON	X	REMEDIAL WORK	ALTERING CASING
EMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILLING OPNS	S. PLUG AND ABANDONMENT
JLL OR ALTER CASING	j	<u></u>	CASING TEST AND CEMENT	JOB
THER:	1		OTHER:	
WOC, run workstring, ta corrosion inhibited fluid,	g cement, cement shou pull workstring to 2,056	ld be above feet, spot 6	2,441 feet, pressure test of sacks of cement, pull wor	casing to 500 psi, displace casing with rkstring to 30 feet and fill casing with
ereby certify that the information about SNATURE	client		ge and belief. Field Foreman	DATE 2-29-00 TELEPHONE NO. (505) 374-3010
PE OR PRINT NAME Danny	doicomp			TELEPHONE NO (505) 374-3010
PROVED BY NOTIONS OF APPROVAL, IF ANY,	Elokum	TITLE D	ISTRICT SUPERV	150k DATE 3/9/00