

5/21/57

Delay in approval of the C-103, Report on Plugging, resulted from an extended effort to establish for certain who the actual owner of the surface is, and whether any further waivers of surface restoration are necessary.

Communication with various members of the Tripier family has failed to shed any light on the subject and I therefore feel that the Commission should accept the C-103 and Mr. Trimmings' waiver as sufficient to close the file on the well and cancel the bond.

Samuel H. Miller, Petr. Engr.

HOME OFFICE
CLAYTON, NEW MEXICO
PHONE 41W

DENVER OFFICE
1845 WYNKOOP STREET
PHONE ALPINE 1242

TIMMONS CARBONIC COMPANY

DENVER, COLORADO

November 28, 1955.

Oil Conservation Commission
P. O. Box 871
Santa Fe, New Mexico.

Dear Sirs:

Enclosed are forms covering the plugging of well on Tixier lease and owned by myself. I have repeatedly asked Mr. Smith to submit the forms to you, as the work was done in the early part of July. He did send me what he had used, and I feel that the well is plugged according to your specifications, as he was careful to find out just what had to be done to conform with your requirements.

I hope that the forms are filled out correctly, for I have no knowledge as to just how it should be done, and have listed what was used in my own way.

note: (As for the clearing of the junk, as was stated, I can assure you that there was no junk, and as well was drilled years ago, the pits are all covered, and offers no hazard to the landowner, and as the landowner, I hereby waive anything that would be classified as junk or restoring surface in any way.)

Hoping that this may clear up any misunderstanding and any reports that should be made, and that this will clear me of any further liability on the part of the Bonding Company, I am

Yours very truly

Roy E. Timmons
Roy E. Timmons

NEW MEXICO OIL CONSERVATION COMMISSION
MISCELLANEOUS REPORTS ON WELLS

(Submit to appropriate District Office as per Commission Rule 1106)

COMPANY ROY E. TIMMONS 1686 East 46th Denver, Colorado.
(Address)

LEASE Tixier WELL NO. 1 SW NE UNIT S 2 T 20N R 30E
Harding County

DATE WORK PERFORMED July 12 - 15 POOL _____

This is a Report of: (Check appropriate block) ☐ Results of Test of Casing Shut-off

☐ Beginning Drilling Operations

☐ Remedial Work

☒ Plugging

☐ Other _____

Detailed account of work done, nature and quantity of materials used and results obtained.

Twelve sacks cement at bottom
135 sacks of mud
15 sacks of cement
16 sacks mud
10 sacks cement on top
4" pipe on top to mark location.

In order used.

*see attached letter for waiver of
back filling pits and clearing
location*

FILL IN BELOW FOR REMEDIAL WORK REPORTS ONLY

Original Well Data:

DF Elev. _____ TD _____ PBD _____ Prod. Int. _____ Compl Date _____

Tbng. Dia _____ Tbng Depth _____ Oil String Dia _____ Oil String Depth _____

Perf Interval (s) _____

Open Hole Interval _____ Producing Formation (s) _____

RESULTS OF WORKOVER:

BEFORE

AFTER

Date of Test _____

Oil Production, bbls. per day _____

Gas Production, Mcf per day _____

Water Production, bbls. per day _____

Gas-Oil Ratio, cu. ft. per bbl. _____

Gas Well Potential, Mcf per day _____

Witnessed by _____

(Company)

OIL CONSERVATION COMMISSION

I hereby certify that the information given
above is true and complete to the best of
my knowledge.

Name Karl M. Miller

Title Petroleum Engineer

Date 5/21/57

Name Ray E. Timmons

Position Manager

Company _____