

Kelly Moore and Rader (b) Gambrel 2 1 23-20N-26E

Last report August 30, 1955, beginning drilling operations.

Inspection reveals that there is 13 to 16 inch surface casing set in the hole. This casing has no plug set in the top or bottom and only a loose steel plate covers the hole. It is the opinion of the inspector that this well open, as it is, constitutes an extreme hazard and deserves immediate attention. Further, the pits have not been filled.