

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

Accepted as Initial ONLY

OPERATOR

Initial Report Final Report

Name of Company: Chevron N.A. Exploration Production Co.	Contact: Edem F Sededji	
Address: P.O. Drawer 29 Andrews TX 79714	Telephone No. 432-234-4437	
Facility Name: WDDU 42	Facility Type: Injection Well	

Surface Owner: New Mexico	Mineral Owner: New Mexico	API No. 3002512321
---------------------------	---------------------------	--------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	32	24-S	38-E	660	North	660	East	Lea

Latitude 32°10'44.36"N Longitude 103° 4'32.23"W

NATURE OF RELEASE

Type of Release: Spill to Land	Volume of Release: 9 barrels of Produced Water	Volume Recovered: 5 bbls
Source of Release: Crack in nipple on B1 Hanger	Date and Hour of Occurrence: 02/11/2015 11:30 AM	Date and Hour of Discovery: 02/11/2015 11:30 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*


Describe Cause of Problem and Remedial Action Taken.*

Spill was due to crack in nipple on B1 Hanger.

Describe Area Affected and Cleanup Action Taken.*

Spill area was around the well head and then 600 FT down the road. Vacuum Truck was called out to vacuum up standing fluids, recovered 5 bbls of fluids and cleaned up the area. Backhoe will be excavating top layer of soil approx. 12-18". Next step is to take samples to determine effectiveness of local remediation and possibly turn remediation over to the Chevron Environmental Management Company if TPH and Chlorides levels are above required threshold.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Edem F. Sededji	Approved by <u>Environmental Specialist</u> : 	
Title: Health and Environmental Specialist	Approval Date: 02/13/2015	Expiration Date: 04/13/2015
E-mail Address: etpo@chevron.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 02/12/2015 Phone: 432-234-4437	Site samples required. Delineate and remediate are as per NMOCD guides.	IRP-3535

* Attach Additional Sheets If Necessary

nTO1504427248⁴³²³
pTO1504429181