

GW - 169

**INSPECTIONS &
DATA**



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

April 5, 2005

Mark E. Fesmire, P.E.

Director

Oil Conservation Division

Ms. Clara Garcia
Williams Field Services Company
188 CR 4900
Bloomfield, New Mexico 87413

RE: Field Inspections

Dear Ms. Garcia:

Attached are copies of the field inspections performed on various William Field Services Company's facilities. These inspections were performed on March 21, 22, and 23, 2005 by New Mexico Oil Conservation Division personnel, Mr. Jack Ford, Mr. Darrel Davis, and Mr. Ed Martin. No photographs were taken during the inspections.

Please review each of the facilities on the attached report and address the comments of items observed during the inspections. No Notice of Violation will be issued as a result of these inspections, however, a number of corrections at the facilities need immediate attention. Kindly inform me as these corrections are made. An e-mail note will be sufficient at this time. My e-mail address is: jwford@state.nm.us

If you have any questions please contact me at (505) 476-3489.

Sincerely,

W. Jack Ford, C.P.G.
Environmental Bureau
Oil Conservation Division

Attachment

Cc: OCD Aztec District Office

3/23/2005 eWJF0509043220 WFS MANZANARES CS
Operator: WILLIAMS FIELD SERVICES CO.

Compressor Station

Field Inspection
Permit(s) Authorizing Facility GW-62

Jack Ford

Samples
Photos / Etc.
Docs Reviewed

Violation Detail (If applicable) Contamination observed on ground surface

Other (Describe below)

Violation Description

Comments / Action Required Oil staining on gravel and soil along the base of compressor pad (removed compressor) requires remediation. Battery not stored properly, correctly store or dispose of properly. Erosion (in one area) along fence line should be corrected for storm water run-off. Tank and tank bermed area appears to have experienced some overflow with bermed area stained and area immediately outside bermed area oil stained. Vent piping is open on top of tank and appears to have been the source of blow-by or overflow. Correct vent piping to flow back into tank. Remediation of soils is required.

Addition Concerns as Checked:

Unauth. Release Drums Process Area Pad / Berm / Liner BG Tanks/Sumps Labeling WD Practice UG Lines Housekeeping Remediations Storm Water

3/23/2005 eWJF0509537782 WFS LA MAQUINA GP
Operator: WILLIAMS FIELD SERVICES CO.

Gas Plant

Field Inspection
Permit(s) Authorizing Facility GW-169

Jack Ford

Samples
Photos / Etc.
Docs Reviewed

Violation Detail (If applicable) No Violations Identified - All O.K.

Violation Description

Comments / Action Required Facility inactive at time of inspection.

Addition Concerns as Checked:

Unauth. Release Drums Process Area Pad / Berm / Liner BG Tanks/Sumps Labeling WD Practice UG Lines Housekeeping Remediations Storm Water