



Khody Land & Minerals Co. NMSLO Lease #X006470405

Section 32, T18S-R28E. Eddy County, NM

Description: On Thursday, June 17th I received a report of a poly line leak on the south side of Hagerman Cutoff road, Eddy County. A site inspection on Friday, July 18th revealed a 2 ¾" poly line had leaked a relatively small amount of crude onto State Trust Land. The line had been repaired, but no reports were made by the owner of the line. While following the line to its source, I found several other spill sites and a poorly maintained pump jack. Please see the attached map and photos. I suspect there are more spills to be found here; however, I didn't want to drive over a fiber glass line that crossed the two-track access road.

New Mexico State Land Office Carlsbad District: Ian Dolly District Resource Specialist
6/18/2015

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (1/8)



Photo Point 1: View of Spill Site #1 Lat: 32.710757° Lon: -104.201069°

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (2/8)



Photo Point 2: View of Spill Site #1

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (3/8)



Photo Point 3: View of Spill Site #2 Lat: 32.709307° Lon: -104.199400°

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (4/8)



Photo Point 4: View of spill site #3 Lat: 32.708042° Lon: -104.198542°

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (5/8)




Photo point 5: View of Pump Jack

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (6/8)



Photo point 6: View of Spill site #3

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (7/8)



Photo point 7: View of Spill site #3

**New Mexico State Land Office Carlsbad District
Ian Dolly District Resource Specialist**

Photographs (8/8)



Photo point 8: View of Spill site #5 and Fiber Glass Line Crossing Two-Track Road

New Mexico State Land Office Carlsbad District
 Ian Dolly District Resource Specialist

Map (1/1)

