

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nMLB1403537703

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Kaiser-Francis Oil Company	12361	Contact	Charles Lock
Address	P.O. Box 21468, Tulsa, OK 74121-1468		Telephone No.	918-491-4337
Facility Name	Malaga 1 Federal Comm 1		Facility Type	Oil and Gas Production Facility
Surface Owner	Mineral Owner		API No. 30015264150000	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
	1	24S	28E					Eddy

Latitude N 32.25214 Longitude W 104.04380

NATURE OF RELEASE

Type of Release	2% KCL Water	Volume of Release	230 bbl	Volume Recovered	0
Source of Release	Flowback Tank	Date and Hour of Occurrence	Date and Hour of Discovery 1/30/14 2:00 pm		
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	NMOCD, BLM and the NRC, Case # 2072554		
By Whom?	Production Foreman and EH&S Department	Date and Hour	approximately 2:00 pm on January 30, 2014		
Was a Watercourse Reached?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	unknown volume		

If a Watercourse was Impacted, Describe Fully.*

Spill left location and entered a deep draw and traveled approximately 1/4 mile with most of the water soaking into the ground but an unknown quantity reaching the Pecos river.


Describe Cause of Problem and Remedial Action Taken.*

Plate on the back of the flowback tank was not completely secure allowing the 2% KCL water to escape from the back of the tank. The 2 % KCL water soaked into the ground no immediate actions were taken.

Describe Area Affected and Cleanup Action Taken.*

The 2 % KCL water traveled down a deep draw with the majority of it soaking into the ground. Cleanup actions will be determined with the help of the BLM and NMOCD.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Charles Lock	Approved by Environmental Specialist: MBratcher		
Title: EH&S Manager	Processed 2/4/2014	Expiration Date:	
E-mail Address: charlesl@kfoc.net	Approval Date:	Attached <input type="checkbox"/>	
Date:	Conditions of Approval:	Phone:	

* Attach Additional Sheets If Necessary

2RP-2175