

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Received 8/23/2016
NMOCD Artesia

Form C-141
Revised October 10, 2003

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

nAB1624526757

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Brian Wall	
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739	
Facility Name: Skelly Unit 156	Facility Type: Oil Producer	
Surface Owner: Federal	Mineral Owner:	API No.: 30-015-25038

LOCATION OF RELEASE

Unit Letter J	Section 22	Township 17S	Range 31E	Feet from the 2560	North/South Line South	Feet from the 2630	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.8198803529214 Longitude: -103.857521338797

NATURE OF RELEASE


Type of Release: Produced Water / Oil	Volume of Release: 2 bbls / 1 bbl	Volume Recovered: 0 / 0
Source of Release: 3" polyline	Date and Hour of Occurrence: 06/17/2014	Date and Hour of Discovery: 06/17/2014 3:30pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jennifer Van Curen - BLM	
By Whom? Brian Wall	Date and Hour 06/18/2014 1:30pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: COG pumper noticed spray coming from cracked fusion in 3" poly line, well feeding the break was isolated and a vac truck was used to drain the line and gang used fusion machine to repair the crack.

Describe Area Affected and Cleanup Action Taken.* : Overspray landed in 15 ft radius circle around crack in line. Will delineate site and remove contaminated soils. Haul to approved site and return clean soils to spill void

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Brian Wall	Approved by District Supervisor:		
Title: Construction Foreman II	Approval Date: 9/1/2016	Expiration Date: N/A	
E-mail Address: bwall@linenergy.com	Conditions of Approval: N/A		Attached <input type="checkbox"/>
Date: 06/19/2014	Phone: 806-367-0645		

* Attach Additional Sheets If Necessary

2RP-3860