

**Photo No:**  
1.

**Direction Taken:**  
South

**Description:**  
Lease Sign



**Photo No:**  
2.

**Direction Taken:**  
Southwest

**Description:**  
View from NE corner of containment showing spill area confined inside of containment.



**Photo No:**  
3.

**Direction Taken:**  
West

**Description:**  
View from NE corner showing overspray area located on pad area. Area is ~ 90' x 50'.



**Photo No:**  
4.

**Direction Taken:**  
West

**Description:**  
View from east side of containment showing where spill sprayed over containment and area where pressure relief valve discharged product onto the pasture area outside of the containment.



**Photo No:**  
5.

**Direction Taken:**  
West

**Description:**  
View from the SE corner of the containment showing the spill area outside of the south side of the containment. Staining is largely due to the pressure relief valve located outside of the containment opening and product being discharged onto the ground. Impacted are is ~ 180' x 10'.



**Photo No:**  
6.

**Direction Taken:**  
East

**Description:**  
View from the end of the release looking east back towards the release point.

