

# Site Diagram

Linn, Turner B South 108  
 UL/K, Sec. 30 T17S R31E  
 Eddy County, NM  
 Drafted By: Lance Crenshaw, 5-19-14

0 0.00325 0.0065 0.013 Miles

## Legend

### Misc\_points

#### Types

-  Electrical Box
-  Power Pole
-  Headers
-  Injection
-  Pumpjacks
-  Tanks
-  Valves
-  Other
-  Soil Bores
-  sample\_pts
-  Source

### Pipeline

#### Type

-  Above Ground Line
-  Buried Line


### Spill

-  <all other values>

### Spill\_Media

-  Oil and Produced H2O
-  Oil
-  Other
-  Produced Water

Spill Area:  
5,072 sq. ft.



Lance Crenshaw  
GIS Technician

Soil Remediation and Ground Water Remediation  
Environmental Assessments  
Regulatory Compliance



Environmental **DFSI** Services

Office: 575-964-8394  
 Fax: 575-964-8396

Cell: 575-441-2359  
 Email: lcrenshaw@diversifiedfsi.com

Source: Esri, DigitalGlobe, GeoEye, IGN, swisstopo, and the GIS User Community