

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
811 South First, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd, Aztec, NM 87410

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, New Mexico 87505

WELL API NO. 30-015-26110
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1565
7. Lease Name or Unit Agreement Name Texaco BE
8. Well No. 3
9. Pool name or Wildcat Grayburg Jackson, SR, QN, GB, SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3678.2' GR

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS).	
1. Type Of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	RECEIVED APR 15 2004 OCD-ARTESIA
2. Name of Operator Mack Energy Corporation	
3. Address of Operator P.O. Box 960, Artesia, NM 88211-0960	
4. Well Location Unit Letter <u>B</u> : <u>330</u> Feet From The <u>North</u> Line and <u>1650</u> Feet From The <u>East</u> Line Section <u>16</u> Township <u>17S</u> Range <u>30E</u> NMPM <u>Eddy</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3678.2' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>
NOTIFY O.C.D. PRIOR TO CONSTRUCTION OF PIT(S).	

Pit(s) must meet all requirements of Rule 19.15.2.50.

Mack Energy Corporation proposes to plug and abandon well as follows:

1. Notify OCD 24 hours prior to starting plugging operations.
2. Set CIBP 100' above perforations @ 3146' w/35' cement cap.
3. Circulate hole with mud. - 100' cement 1100' - 1000'
4. Set 100' cement plug from 478-378', 50' above and below 8 5/8 casing. - WOC TAG
5. Set 60' surface plug. - WOC 24 Hr TAG.
6. Install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jerry W. Sherrell TITLE Production Clerk DATE 4/14/2004
TYPE OR PRINT NAME Jerry W. Sherrell TELEPHONE NO.

(This space for State Use)

APPROVED BY [Signature] TITLE ARI DATE 5/4/04
CONDITIONS OF APPROVAL, IF ANY:

STATE

MACK ENERGY CORPORATION
TEXACO BE STATE 3
SEC 16S T17S R30E 330FNL 1650FEL

1. Notify OCD 24 hrs. prior to any work done.
2. Set CIBP 100' above perfs @ 3146' w/35'cmt cap.
3. Circ hole with mud gel.
4. Set 100' cmt plug 478'-378' 50' above & below 8 5/8" shoe
5. 60' circ cmt to surface
6. Install Dry Hole Marker

60'
Surface 24 1/2" shoe

8 5/8" 24#&32# @ 428' circ cmt. 478'-378' w/24" TAC.

100' CMT 1100' - 1000'

CIBP @ 3146' w/35' CMT.
Perfs 3246'-5380'

5 1/2" @ 5513' circ cmt.