Submit 3 Copies To Appropriate District	State of N	lew Mexico		()\e Form C-103	
Office District I	Energy, Minerals and Natural Resources		S	Revised March 25, 1999	
1625 N. French Dr., Hobbs, NM 88240	N. French Dr., Hobbs, NM 88240		WELL API	NO.	
<u>District II</u> 811 South First, Artesia, NM 88210	OH CONSERVATION DIVISION			-005-63104	
District III	District III 1220 South St. Francis 1220 South St.		J. molcate	Type of Lease	
District IV	Rio Brazos Rd., Aztec, NM 87410 Santa Fe, NM 87505		6 State Oi	E FEE X 1 & Gas Lease No.	
1220 S. St. Francis Dr., Santa Fe, NM 87505	/	\(\text{\gamma}^{\gamma} \) \(\text{\gamma} \text{\gamma} \text{\gamma} \)	6) G. Simile Of	t de Cas Loase 110.	
SUNDRY NOTIC	CES AND REPORTS ON	WELDS PECE 2002	4 3/1	ne or Unit Agreement Name:	
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC	ALS TO DRILL OR TO DEEPER		56		
PROPOSALS.)	ATION FOR FERMIT (FORWI)	S/A	0		
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCCESSION OF PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other Plug & Abandon,			\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	mos Fee	
2. Name of Operator			8. Well No.	mos ree	
Marbob Energy Corporation				1	
3. Address of Operator			l l	9. Pool name or Wildcat	
P. O. Box 227 - Artesia, NM 88211-0227 4. Well Location			Long Arro	yo Devonian, NE	
4. Well Location					
Unit Letter G:	330 feet from the N	orth line and		from the East line	
S 22	T	D 20E	NA/DM (1)	Country	
Section 33 Township 12S Range 28E NMPM Chaves County 10. Elevation (Show whether DR, RKB, RT, GR, etc.)					
3607' GR					
	opropriate Box to Indic				
NOTICE OF INT			UBSEQUENT		
PERFORM REMEDIAL WORK	PLUG AND ABANDON L	I REMEDIAL W	ORK L	☐ ALTERING CASING ☐	
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE	DRILLING OPNS. [
PULL OR ALTER CASING	MULTIPLE [CASING TES	TAND [ABANDONMENT	
1 OLE ON AETEN CAOING	COMPLETION	CEMENT JOE		!	
OTHER:	٦	OTHER:			
12. Describe proposed or complete	d operations. (Clearly state	<u> </u>	nd give pertinent da	tes, including estimated date	
of starting any proposed work).					
or recompilation.	and referred up null4	no unit and niv	raina aguinman	t lingat numn	
12-12-2002 - Moved in and rigged up pulling unit and plugging equipment. Unset pump. TOOH with 160 rods. Shut well in for night.					
12-13-2002 - Finished TOOH with rods and pump. Opened casing - well flowed for 2 hours.					
Nippled down wellhead and nippled up BOP. Unset tubing anchor. TOOH with 72 joints of					
2-7/8" tubing. Shut BOP. Shut well in for night. 12-14-16-2002 - Finished POOH with tubing and tubing anchor. Shut well in for weekend.					
12-17-2002 - Finish	12-17-2002 - Bled well down. POOH with kill string. RIH with CIBP and set CIBP at 8100'.				
Nippled down wellhead and nippled up BOP. Unset tubing anchor. TOOH with 72 joints of 2-7/8" tubing. Shut BOP. Shut well in for night. 12-14-16-2002 - Finished POOH with tubing and tubing anchor. Shut well in for weekend. 12-17-2002 - Bled well down. POOH with kill string. RIH with CIBP and set CIBP at 8100'. Circulated hole with plugging mud. Shut well in for night. 12-18-2002 - Spotted 15 sacks Class C cement on top of CIBP at 8100'. Pulled up hole.					
12-18-2002 - Spotted 15 sacks Class C cement on top of CIBP at 8100'. Pulled up hole.					
Spotted 25 sacks Class C cement at 7266'. POOH to 6091'. Spotted 25 sacks Class C cement. POOH to 5155'. Spotted 25 sacks Class C cement. Pulled up hole. Shut well in for night.					
12-19-2002 - Spotted 2					
Class C cement at 1680	Class C cement at 1680'. Pulled up hole. WOC 4 hours. RIH with tubing and tagged cement at 1477'. Pulled up hole with tubing. Shut well in for night.				
at 1477'. Pulled up he	ole with tubing. S	hut well in for	night.	udaaad daam admaldma	
12-20-2002 - Rigged up I hereby certify that the information a					
The copy certify that the information a	Vove is due and complete t	o the best of my know	ledge and belief. (ONTINUED ON NEXT FAGE.	
SIGNATURE Tylesly	(0, 1)	TLE Agent for	BCM & Associat	es DATE Dec. 27, 2002	
Type or print name Rusty Klein					
Type or print name Rusty Rieth			œ.	Jamb one No. 748-2150	
(This space for State use)		A A 11	Te	elephone No. 748-2159	
(This space for State use)		A -01		FEB 2 5 2003	
(This space for State use) APPPROVED BY		LE Suld			

MARBOB ENERGY CORPORATION Ramos Fee #1 Section 33-T12S-R28E Chaves County, New Mexico

SUNDRY NOTICE CONTINUED:

RIH with packer and tubing and set packer at 30'. Pressured up to 1500 psi. Did not pump through. POOH with packer. RIH with tubing and spotted 25 sacks Class C cement. WOC 4 hours. RIH with tubing and tagged cement at 238'. POOH with tubing. Rigged up wireline. RIH and perforated at 60'. POOH & rigged down wireline. Pressured up. Did not pump through. RIH with 2 joints and spotted a 60' plug from 60' to surface. Nippled down BOP. Rigged down pulling unit and plugging equipment. Installed regulation abandonment marker. PLUGGED AND ABANDONED - FINAL REPORT. Plugging completed 12-19-2002.

Agent for BCM & Associates

December 27, 2002



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

GARY E. JOHNSON

Governor
Betty Rivera
Cabinet Secretary

alaulo3 OK for Release

JAN 08 2003

Lori Wrotenbery
Director
Oil Conservation Division

6 January 2003

Marbob Energy P.O. Box 227

Artesia, New Mexico 88211-0227

Form C-103 Report of Plugging for your Ramos Fee # 1 B-33-12-28 API 30-005-63104 67 87 Los Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.

- 1. All pits have been filled and leveled.
- 2. Rat hole and cellar have been filled and leveled.
- 3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)
- 4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.
- 3. The dead men and tie downs have been cut and removed.
- 🗵 6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.
- 3. All environmental concerns have been addressed as per OCD guidelines.

The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.

When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location.

I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection and approval.

Vame

Van Barton Field Rep. II

PRODUCTION ANALYST

Title

2/10/03