



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON

Governor

Joanna Prukop

Cabinet Secretary

Lori Wrotenbery

Director

Oil Conservation Division

Underground Injection Control Program

"Protecting Our Underground Sources of Drinking Water"

17-Apr-03

SAGA PETROLEUM LIMITED LIABILITY CO.

415 W WALL

STE 1900

MIDLAND TX 79701-0000

Dear Operator:

The following test(s) were performed on the listed dates on the following well(s) shown below in the test detail section.

The test(s) indicates that the well or wells failed to meet mechanical integrity standards of the New Mexico Oil Conservation Division. To comply with guidelines established by the U.S. Environmental Protection Agency, the well must be shut-in immediately until it is successfully repaired. The test detail section which follows indicates preliminary findings and/or probable causes of the failure. This determination is based on a test of your well or facility by an inspector employed by the Oil Conservation Division. Additional testing during the repair operation may be necessary to properly identify the nature of the well failure.

Please notify the proper district office of the Division at least 48 hours prior to the date and time that repairs will be attempted so that such operations may be witnessed by a field representative.

MECHANICAL INTEGRITY TEST DETAIL SECTION

WEST HENSHAW PREM UNIT 001

Temporarily Abandoned Injection - (All Types)

30-015-03840-00-00

M-3-16S-30E

Test Date: 4/14/2003 11:05:53 AM

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 7/18/2003

Test Type: Bradenhead Test

FAIL TYPE: Tubing

FAIL CAUSE:

Comments on MIT: Well has a continuous flow from casing.

WEST HENSHAW PREM UNIT 002

Temporarily Abandoned Injection - (All Types)

30-015-03864-00-00

I-5-16S-30E

Test Date: 4/14/2003 9:07:31 AM

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 7/18/2003

Test Type: Bradenhead Test

FAIL TYPE: Tubing

FAIL CAUSE:

Comments on MIT: Well has continuous blow from casing. Possible hole in tubing.

WEST HENSHAW PREM UNIT 004P

Active Injection - (All Types)

30-015-03876-00-00

A-8-16S-30E

Test Date: 4/14/2003 11:33:36 AM

Permitted Injection PSI:

Actual PSI:

Test Reason: Annual IMIT

Test Result: F

Repair Due: 7/18/2003

Test Type: Bradenhead Test


FAIL TYPE: Tubing

FAIL CAUSE:

Comments on MIT: Well has not been repaired since failed MIT in 2000.

Thank you for your prompt attention to this matter and your efforts in helping to protect our ground water resources.

Sincerely,



Artesia OCD District Office

Note: Pressure Tests are performed prior to initial injection, after repairs and otherwise, every 5 years; Bradenhead Tests are performed annually. Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. "Failure Type" and "Failure Cause" and any Comments are not to be interpreted as a diagnosis of the condition of the wellbore. Additional testing should be conducted by the operator to accurately determine the nature of the actual failure. * Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.