State of New Mexico Encryy, Minerals and Natural Resources Department



Form C-103 Revised 1-1-6

to Approxime District Office	Energy, wines are my wantan	tanonia - i	Revised 1-1-69
DISTRICT! P.O. Box 1940, Hobbe, NM 41240	OIL CONSERVATI		WELL ANNO.
P.O. Box 2066		30-015-01630	
DISTRICT II P.O. Drewer DD. Arrosie, PM \$1210	Santa Fc, New Mexico	o 87504-2088	S. Indiana Type of Lane
DISTRICT III			STATE FEE
1000 Rio Brition Rd., Amer. NOV. 17410			6. State OI & Gar Lorice No.
SUNDRY NOT	TICES AND REPORTS ON WI	RLS &	
(DO NOT USE THIS FORM FOR PA	IOPOSALS TO DRILL OR TO DEEPE	EN OR PUIG BACK TO A	7. Lead Nume or Unit Agrocomon Name
	RVOIR, USE "APPLICATION FOR P >101) FOR SUCH PROPOSALS,)	ERUT	
1. Type of Well:	21017 FOR SOCRETAGE CONTRACTOR		Red Lake Sand Unit
Aur X	отнех	RECEIVED	1
2. Nune of Openuor			L Well Na
Mack Energy Corp	oration	JAN 0 4 2005	2
1. Address of Operator		PH: NOTERIA	9. Pool aume or Waldent
P.O. Box 960, Ar	tesia, NM 88211	<u></u>	Red Lake, Queen-Grayburg-SA
Well Location		000	_
Unit Leace: 16!	50 Feet From The North	Linc and990	Food From TheEast
Sertion 30	170	ንያፑ .	NMPM Eddy Grant
Section 30	Township 175 R		MMPM Eddy Count
	/////		<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>
Charles Charles	Appropriate Box to Indicate	Name of Name D	more or Other Data
	* * *		•
NOTICE OF IM	IENTION TO:	SOB	SEQUENT REPORT OF:
ERFORM REMEDIAL WORK	PUIG AND ABANDON 🔲	RELIEDUL WORK	ALTERING CASING
	PLUG AND ABANDON CHANGE PLANS		
ERFORM REMEDIAL WORK		COMMENCE DESILLING	ория. Прис лю лелиоониелт
EMPORARILY ABANDON			ория. Прис лю лелиоониелт
EMPORARILY ABANDON		CASING TEST AND CE	ория. Прис лю лелиоониелт
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER:	DENT DB TO BURG AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING UTHER: 12 Decardo: Proposed or Completed Opera	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER:	DENT DB TO BURG AND ABANDONMENT
EMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER:	DENT DB TO BURG AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING THER: 12 Describe Proposed of Completed Operation SEE RULE 1103.	CHANGE PLANS	COMMENCE DRILLING CASING TEST AND CE OTHER: and line portions data, included	DENT DB TO BURG AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operation SEE RULE 1103. 1-23-04 Spot 25 sx c	ciox (Clerty state all portions details, a	COMMENCE DRILLING CASING TEST AND CE OTHER: and line portions data, included	DENT DB TO BURG AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operatory SEE RULE 1101 1-23-04 Spot 25 sx ct 1-23-04 Circ. hole w	ciox (Clerty state all portions details, at met. @ 1720', tag plug	COMMENCE DRILLING CASING TEST AND CE OTHER: and fine portions data, include (**1587**,	DENT DB TO BURG AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING THER: 12 Describe Proposed or Completed Operation SEE RULE 1101. 1-23-04 Spot 25 sx ct 1-23-04 Circ. hole will 1-23-04 Perf. 4 hole	change Plans	COMMENCE DRILLING CASING TEST AND CE OTHER: and fine portions data, include (**1587**,	DENT DB TO BURG AND ABANDONMENT
EMPORARLY ABANDON ULL OR ALTER CASING THER: 12 Decribe Proposed of Completed Operatory SEE RULE 1101 1-23-04 Spot 25 sx cc 1-23-04 Circ. hole w 1-23-04 Perf. 4 hole 1-26-04 Tag plug @ 4	change Plans	COMMENCE DRILLING CASING TEST AND CE OTHER: and five portions data, include (** 1587**, 376**.	SOPHS. PUIG AND ABANDONMENT THENT JOB STATE STATE OF PRINCE AND PROPOSED THE CRITICAL STATE OF PROPOSED AND PROPOSED A
THER: 1-23-04 Spot 25 sx con 1-23-04 Circ. hole will 1-26-04 Tag plug @ 4 1-26-04 Perf. 4 hole	ciox (Clerty state all partirers decade, as met. @ 1720', tag plug of mud. es @ 612', set pkr. @ 35'. es @ 400', set pkr. @	COMMENCE DRILLING CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx	CMT. Displaced cmt. to 300'.
EMPORARILY ABANDON ULL OR ALTER CASING THER: 12 Decribe Proposed or Completed Operatory SEE RULE 1103. 1-23-04 Spot 25 sx con 1-23-04 Circ. hole with 1-23-04 Perf. 4 hole 1-26-04 Tag plug @ 41-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole	change plans int. @ 1720', tag plug mud. es @ 612', set pkr. @ es @ 400', set pkr. @ es @ 60' pump 20 sx cm	COMMENCE DRILLING CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx	SOPHS. PUIG AND ABANDONMENT THENT JOB STATE STATE OF PRINCE AND PROPOSED THE CRITICAL STATE OF PROPOSED AND PROPOSED A
THER: 12 Dearbe Proposed or Completed Operatory SEE RULE 1101. 1-23-04 Spot 25 sx continued Circ. hole with 1-23-04 Perf. 4 hole 1-26-04 Tag plug @ 41-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole Leave 7" full	change Plans	COMMENCE DRILLING CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx	CMT. Displaced cmt. to 300'.
THER: 1-23-04 Spot 25 sx c 1-23-04 Circ. hole w 1-23-04 Tag plug @ 4 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Tag plug @ 5	change Plans	COMMENCE DRILLING CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx t. down 7" & out	CMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS AND ABANDONMENT
THER: 1-23-04 Spot 25 sx c 1-23-04 Circ. hole w 1-23-04 Tag plug @ 4 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Tag plug @ 5	change Plans	COMMENCE DRILLING CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx t. down 7" & out	CMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING THER: 12 Decribe Proposed or Completed Operators SEE RULE 1101. 1-23-04 Spot 25 sx cc 1-23-04 Circ. hole w 1-23-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-27-04 Tag plug @ 5	change Plans	COMMENCE DRILLING CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx t. down 7" & out	CMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS AND ABANDONMENT
ULL OR ALTER CASING OTHER: 12 Dearby Proposed or Completed Operatory SEE RULE 1101 1-23-04 Spot 25 sx cc 1-23-04 Circ. hole w 1-23-04 Perf. 4 hole 1-26-04 Tag plug @ 4 1-26-04 Perf. 4 hole 1-26-04 Tag plug @ 5	change Plans	COMMENCE DRILLING CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx t. down 7" & out	CMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING ULL OR SEE RULE 1101. 1-23-04 Spot 25 sx cc 1-23-04 Circ. hole will 1-23-04 Perf. 4 hole ull 1-26-04 Tag plug @ 41-26-04 Perf. 4 hole ull 1-26-04 Perf. 4 hole ull 1-26-04 Perf. 4 hole ull 1-27-04 Tag plug @ 51-27-04 RDMO. Cut of	change Plans [] ciox (Clerty state of portions decode, and	CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx t. down 7" & out	CMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS AND ABANDONMENT
ULL OR ALTER CASING OTHER: 12 Dearby Proposed or Completed Operatory SEE RULE 1101 1-23-04 Spot 25 sx cc 1-23-04 Circ. hole w 1-23-04 Perf. 4 hole 1-26-04 Tag plug @ 4 1-26-04 Perf. 4 hole 1-26-04 Tag plug @ 5	change Plans [] ciox (Clerty state of portions decode, and	CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx t. down 7" & out Try hole marker,	CMT. Displaced cmt. to 300'. 8-5/8" csg. to surface.
EMPORARILY ABANDON OTHER: 12 Despite Proposed or Completed Operatory SEE RULE 1101 1-23-04 Spot 25 sx cc 1-23-04 Circ. hole w 1-23-04 Perf. 4 hole 1-26-04 Tag plug @ 41-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole Leave 7" ful 1-27-04 Tag plug @ 51-27-04 RDMO. Cut of	change Plans mt. @ 1720', tag plug mt. @ 612', set pkr. @ a55'. es @ 400', set pkr. @ es @ 60' pump 20 sx cm of cmt. f wellhead, install di	CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx t. down 7" & out	CMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS. PRUG AND ABANDONMENT JOB COPHS AND ABANDONMENT
EMPORARILY ABANDON ULL OR ALTER CASING UTHER: 12 Decribe Proposed or Completed Operatory SEE RULE 1101 1-23-04 Spot 25 sx cc 1-23-04 Circ. hole will 1-23-04 Perf. 4 hole 1-26-04 Tag plug @ 41-26-04 Perf. 4 hole 1-26-04 Perf. 4 hole Leave 7" full 1-27-04 Tag plug @ 51-27-04 RDMO. Cut of	change Plans mt. @ 1720', tag plug mt. @ 612', set pkr. @ a55'. es @ 400', set pkr. @ es @ 60' pump 20 sx cm of cmt. f wellhead, install di	COMMENCE DRILLING CASING TEST AND CE OTHER: 1587'. 376'. 62', sqz. 35 sx t. down 7" & out ry hole marker,	CMT. Displaced cmt. to 300'. 8-5/8" csg. to surface.



NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

BILL RICHARDSON Governor Joanna Prukop Cabinet Secretary

RECEIVED

Lori Wrotenbery Director **Oil Conservation Division**

JAN 0 4 2005	
998:ARTESIA	
16 February 2004	
Mack Energy Corp. P. O. Box 960 Artesia, New Mexico 88221-0960	
Form C-103 Report of Plugging for your Red Lake Sand Unit # 2 30-17-28 API 30-015-01630 Cannot be approved until an NMOCD representative has made an inspection of the location and found it to be cleared to comply with OCD rules and regulations. Please check each item in the space provided to indicate that the work has been accomplished and the location is ready for final inspection.)
☐ 1. All pits have been filled and leveled.	
2. Rat hole and cellar have been filled and leveled.	
3. A steel marker 4" in diameter and approximately 4' above mean ground level has been set in concrete to mark the exact location of the plugged well. (Marker must have operator name, lease name, well number and location including quarter/quarter section or unit letter, section, township, range and API well ID number permanently welded, stamped or otherwise engraved into the metal marker.)	are,
4. The location has been leveled as nearly as possible to original top ground contour and has been cleared of all junk and equipment.	
5. The dead men and tie downs have been cut and removed.	
6. If a one well lease or last remaining well on lease, the battery and burn pit locations have been leveled and cleared of all junk & equipment.	
7. All environmental concerns have been addressed as per OCD guidelines.	
The above are minimum requirements and no plugging bond will be cancelled until all locations for plugged and abandoned wells have been inspected and Form C-103 approved.	
When all of the work outlined above has been done, please notify this office by completing, signing and returning this letter to us so that our representative will not have to make more than one trip to the location	l.
I certify that the above work has been done and the above-mentioned lease is ready for OCD inspection an approval.	<u>d</u>
Park at a Clark	