Energy, Minerals and Natura	THE T L DINIO	
District II RECEIVED	WELL API NO. 30-015-30113	
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION I	JIVISION 5 Indicate Type of I	I ease
District III MAR 2 5 2005 220 South St. France 1000 Rio Brazos Rd., Aztec, NM 87410	is Dr. STATE	FEE
District IV OUD AND AND AND AND AND AND AND AND AND AN	6. State Oil & Gas I	
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or U	nit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUC	G BACK TO A Cochiti 28 Federal	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR PROPOSALS.)		
1. Type of Well: Oil Well Gas Well Other Salt Water D	isposal 8. Well Number 1	
2. Name of Operator	9. OGRID Number	
Devon Energy Production Company, L.P.	6137	
3. Address of Operator 20 North Broadway, Suite 1500, Oklahoma City, Oklahoma 73102	10. Pool name or W	ildcat
4. Well Location	(403) 332-4013	
	line and 660 feet from	theWestline
	Range 29E NMPM Edd	
Section 28 Township 23S Range 29E NMPM Eddy County  11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
2995' GR		
Pit or Below-grade Tank Application ☐ or Closure ☐		
Pit typeDepth to GroundwaterDistance from nearest fresh water well Distance from nearest surface water		
Pit Liner Thickness: mil Below-Grade Tank: Volume	bbls; Construction Material	
12. Check Appropriate Box to Indicate Na	ture of Notice, Report or Other Da	ata
NOTICE OF INTENTION TO	OUDOFOLIENT DEDO	
NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐	SUBSEQUENT REPORT REPORTS SUBSEQUENT REPORTS ALL SUBSEQUENT REPORTS ALL SUBSECTION SUBSE	JR FOF: LTERING CASING □
Y		AND A
	OCIMINE HOL BINIELING OF NO.	7.11071
PULL OR ALTER CASING   MULTIPLE COMPL	CASING/CEMENT JOB	
		_
OTHER: Convert to SWD. Admin Order SWD-972	CASING/CEMENT JOB   OTHER:	
OTHER: Convert to SWD. Admin Order <u>SWD-972</u> ⊠	OTHER:	
OTHER: Convert to SWD. Admin Order SWD-972	OTHER: rtinent details, and give pertinent dates,	including estimated date
OTHER: Convert to SWD. Admin Order SWD-972    3. Describe proposed or completed operations. (Clearly state all persons)	OTHER: rtinent details, and give pertinent dates,	including estimated date
OTHER: Convert to SWD. Admin Order SWD-972    3. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.	OTHER: rtinent details, and give pertinent dates,	including estimated date
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.	OTHER: rtinent details, and give pertinent dates, Completions: Attach wellbore diagram	including estimated date of proposed completion
OTHER: Convert to SWD. Admin Order SWD-972    3. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.	OTHER: rtinent details, and give pertinent dates, Completions: Attach wellbore diagram	including estimated date of proposed completion
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all perof starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the case.	OTHER:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and	including estimated date of proposed completion date. (Note: parted
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all perof starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)	OTHER:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and	including estimated date of proposed completion date. (Note: parted
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all perof starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p	including estimated date of proposed completion of tag. (Note: parted possible hole in casing
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all perof starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p	including estimated date of proposed completion of tag. (Note: parted possible hole in casing
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 3	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p	including estimated date of proposed completion at tag. (Note: parted possible hole in casing
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 3 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p	including estimated date of proposed completion date. (Note: parted possible hole in casing el & surface pressure of perform MIT test on
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 3 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to 7. Wellhead injection pressure shall be limited to no more than 685 psi (p	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p	including estimated date of proposed completion date. (Note: parted possible hole in casing el & surface pressure of perform MIT test on
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 3 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p	including estimated date of proposed completion date. (Note: parted possible hole in casing el & surface pressure of perform MIT test on
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 3 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to 7. Wellhead injection pressure shall be limited to no more than 685 psi (pthat max allowed injection pressure is not exceeded. Commence water in	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p	including estimated date of proposed completion of tag. (Note: parted possible hole in casing el & surface pressure of perform MIT test on essure limiting device so
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 3 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to 7. Wellhead injection pressure shall be limited to no more than 685 psi (pthat max allowed injection pressure is not exceeded. Commence water in	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p  628' to 3658'. Note stabilized fluid leve  6378'. Load hole with packer fluid and p  7 performing MIT test)  1 per approved C108). Equip well with pre-  1 piction. Note date of injection.  1 tof my knowledge and belief. I further c	including estimated date of proposed completion of proposed completion of tag. (Note: parted possible hole in casing the surface pressure of perform MIT test on the essure limiting device so the estimate of the case of the estimate of the essure limiting device so the estimate of the e
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 3 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to 7. Wellhead injection pressure shall be limited to no more than 685 psi (pthat max allowed injection pressure is not exceeded. Commence water in I hereby certify that the information above is true and complete to the best grade tank has been/will be constructed or closed according to NMOCD guidelines.	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p  628' to 3658'. Note stabilized fluid leve  6378'. Load hole with packer fluid and p  7 performing MIT test)  1 per approved C108). Equip well with pre-  1 piction. Note date of injection.  1 tof my knowledge and belief. I further c	including estimated date of proposed completion of proposed completion of tag. (Note: parted possible hole in casing the surface pressure of perform MIT test on the essure limiting device so the estimate of the case of the estimate of the essure limiting device so the estimate of the e
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 32 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to 7. Wellhead injection pressure shall be limited to no more than 685 psi (pthat max allowed injection pressure is not exceeded. Commence water in I hereby certify that the information above is true and complete to the best grade tank has been/will be constructed or closed according to NMOCD guidelines.	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note percentage)  378'. Load hole with packer fluid and performing MIT test) per approved C108). Equip well with prejection. Note date of injection.  t of my knowledge and belief. I further can general permit or an (attached) alternative.	including estimated date of proposed completion of proposed completion of tag. (Note: parted possible hole in casing the surface pressure of perform MIT test on the essure limiting device so the estimate of the essure limiting device so the estimate of t
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 3 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to 7. Wellhead injection pressure shall be limited to no more than 685 psi (pthat max allowed injection pressure is not exceeded. Commence water in I hereby certify that the information above is true and complete to the best grade tank has been/will be constructed or closed according to NMOCD guidelines   SIGNATURE   Representation   Rep	rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note per second performing MIT test) ber approved C108). Equip well with prejection. Note date of injection.  t of my knowledge and belief. I further can general permit or an (attached) alternation.	including estimated date of proposed completion of proposed completion of tag. (Note: parted possible hole in casing the surface pressure of perform MIT test on the essure limiting device so the estimate of the occupance of the occupance occupanc
13. Describe proposed or completed operations. (Clearly state all perof starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 36 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to 7. Wellhead injection pressure shall be limited to no more than 685 psi (pthat max allowed injection pressure is not exceeded. Commence water in the standard property of the standard propert	rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note per second performing MIT test) ber approved C108). Equip well with prejection. Note date of injection.  t of my knowledge and belief. I further can general permit or an (attached) alternation.	including estimated date of proposed completion of proposed completion of tag. (Note: parted possible hole in casing the surface pressure of perform MIT test on the essure limiting device so the estimate of the occupance of the occupance occupanc
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 36 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to 7. Wellhead injection pressure shall be limited to no more than 685 psi (pthat max allowed injection pressure is not exceeded. Commence water in the standard processor of the sta	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p  628' to 3658'. Note stabilized fluid leve  6378'. Load hole with packer fluid and p  performing MIT test) Der approved C108). Equip well with pre- piection. Note date of injection.  t of my knowledge and belief. I further c  a general permit or an (attached) alternative  Engineering Technician DA  llack@dvn.com  Telephone No. 40	including estimated date of proposed completion of proposed completion of tag. (Note: parted possible hole in casing the surface pressure of perform MIT test on the essure limiting device so the estimate of the essure of the e
OTHER: Convert to SWD. Admin Order SWD-972  13. Describe proposed or completed operations. (Clearly state all per of starting any proposed work). SEE RULE 1103. For Multiple or recompletion.  1. Retrieve existing production tubing, rods, and pump from wellbore.  2. Spot a 100' balanced cement plug from 6350' to 6450' to abandon the casing indicated at 6402-6404'.)  3. Set a CIBP @ 6100' and dump bail 35' cement on top to abandon the indicated at 6118', but tested Ok to 1000 psi on 5/29/99.)  4. Set CIBP @ 3858' and dump bail 35' cement on top.  5. Perforate the Delaware Bell Canyon from 3428' to 3467' and from 36 casing.  6. Run 2-7/8" internally plastic coated tubing and packer. Set packer at 3 casing. Chart results. (Note: Notify OCD 24 hours in advance prior to 7. Wellhead injection pressure shall be limited to no more than 685 psi (pthat max allowed injection pressure is not exceeded. Commence water in the standard property of t	other:  rtinent details, and give pertinent dates, Completions: Attach wellbore diagram  Bone Spring at 7816'-7875'. WOC and Brushy Canyon at 6210'-6230'. (Note p  628' to 3658'. Note stabilized fluid leve  6378'. Load hole with packer fluid and p  performing MIT test) Der approved C108). Equip well with pre- piection. Note date of injection.  t of my knowledge and belief. I further c  a general permit or an (attached) alternative  Engineering Technician DA  llack@dvn.com  Telephone No. 40	including estimated date of proposed completion of proposed completion of tag. (Note: parted possible hole in casing the surface pressure of perform MIT test on the essure limiting device so the estimate of the occupance of the occupance occupanc



