Form 3160-5 (February 2005)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT


OCD Artesia

FORM APPROVED OMB No 1004-0137 Expires: March 31, 2007


5 Lease Serial No. NM 0418220-A

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.			6. If Indian, Allottee or Tribe Name	
SUBMIT IN TRIPLICATE – Other instructions on page 2.			7. If Unit of CA/Agreement, Name and/or No	
1. Type of Well Gas Well Other		8. Well Name and N Todd 27 Federal !	8. Well Name and No. Todd 27 Federal 5	
2. Name of Operator Devon Energy Production Company, L.P.		9. API Well No 30-015-35517		
3a. Address 20 North Broadway, Oklahoma City, OK 73102 3b. Prione No. (include area code) 405-235-3611				
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL. 1850 FNL & 500 FWL SEC 27 T23S R31E		11. Country or Paris	11. Country or Parish, State Eddy County, NM	
12. CHECK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE	OF NOTICE, REPORT OR OT	THER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			
Notice of Intent Acidize Alter Casing Casing Repair Change Plans	Deepen Fracture Treat New Construction Plug and Abandon	Production (Start/Resume) Reclamation Recomplete Temporarily Abandon	Water Shut-Off Well Integrity Other Recomplete Uphole	
Final Abandonment Notice Convert to Injection	_	Water Disposal	Pérfs	
following completion of the involved operations. If the opera testing has been completed. Final Abandonment Notices mus determined that the site is ready for final inspection.) 1. MIRU PU. POOH w/ rods. ND WH. NU 5K BOP. 2. RU WL & RIH w/ GR & JB_Set CBP @ ~7300'. 3. Perf M. Brushy Canyon 7142-7197': 66 total shots. 4. Perf U. Brushy Canyon 7050-7064': 28 total shots. 5. RIH w/ pkr & RBP w/ ball catcher. Hydro test tbg to ~70826. MIRU BJ & acidize M. Brushy w/ 7 1/2% Pentol acid dropp. 7. RIse pkr & knock balls to btm. Latch on to RBP & PU to 7 recommendation. RD BJ. 8. RIse pkr & knock balls to btm. Unset RBP & set @ 7250'. 9. Prep for frac. 10. Set RBP @ 7100' & pkr @ 6990'. Swab dry. 11. Depending upon swab testing two zones; doesn't give up	t be filed only after all requirements 2'. Set RBP @ ~ 7250'. PT RBP bing balls as per BJ Recommend 100'. Set pkr @ 6990'. Acidize I PU & set pkr @ 7100'. Swab di	to 500#. Set pkr @ 7100'. ation. J. Brushy w/ 7 1/2% Pentol atry. SEE ATTACH	RECEIVED JUL 15 2011 NMOCD ARTESIA acid dropping balls per BJ on @ 6933-37'; 6943-46'.	
14. I hereby certify that the foregoing is true and correct Name (Printed/Typed) Judy A. Barnett	Title Regulator	y Specialist	-	
Signature Jud Sannet	Date 04/26/201			
THIS SPACE FOR FEDERAL OR STATE OF FICE USEV EU				
Approved by Conditions of peroval, if any, are attached. Approval of this notice do that the applicant holds legal or equitable title to those rights in the subjectite the applicant to conduct operations thereon. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make in	ect lease which would Office	JUL 1 4 2011 BUREAU OF LAND MANAGE	Date EMENT Out or agency of the United States any false,	


fictitious or fraudulent statements or representations as to any matter within its jurisdiction.



devon



devon



Todd 27M Federal 5 30-015-35517 Devon Energy Production Company July 14, 2011 Conditions of Approval

- 1. Surface disturbance beyond the originally approved pad must have prior approval.
- 2. Closed loop system required.
- 3. Subsequent sundry with completion record and wellbore schematic required.

TAM 071411