	State of New Mexico	Form C-103
District I 1625 N French Dr., Hobbs, NM 88240	Energy, Minerals and Natural Resources	October 13, 2009 WELL API NO.
District II	OIL CONSERVATION DIVISION	30-015-3937
1301 W. Grand Ave , Artesia, NM 88210 District III	1220 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd , Aztec, NM 87410 District IV	Santa Fe, NM 87505	STATE FEE 6. State Oil & Gas Lease No.
1220 S St. Francis Dr., Santa Fe, NM	2 111011 2 0, 2 1111 0 / 2 02	30-1969
87505 SUNDRY NOTIC	ES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSA	LLS TO DRILL OR TO DEEPEN OR PLUG BACK TO A TION FOR PERMIT" (FORM C-101) FOR SUCH	Pigled 21 State
PROPOSALS)	,	8. Well Number
1. Type of Well: Oil Well 2. Name of Operator	as Well U Other	9. OGRID Number
OXY USA W	TP LP	192463
3. Address of Operator P.O. Box 5025	50 Midland, TX 79710	10. Pool name or Wildcat
4. Well Location	77 17 17 17 17 17 17 17 17 17 17 17 17 1	Antesia Glorieta Yeso
	1627 feet from the South line and	345 feet from the east line
Section 71	Township 175 Range 28E	NMPM County
	11. Elevation (Show whether DR, RKB, RT, GR, etc. 3653 GR	.)
	7635 GK	
12. Check Ap	ppropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INT	FNTION TO:	SSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON ☐ REMEDIAL WOF	
TEMPORARILY ABANDON		ILLING OPNS. P AND A
PULL OR ALTER CASING DOWNHOLE COMMINGLE	MULTIPLE COMPL CASING/CEMEN	IT JOB 🎺 🔀
_	_	_
OTHER: 13 Describe proposed or comple	☐ OTHER: ted operations. (Clearly state all pertinent details, an	ad give pertinent dates, including estimated date
	k). SEE RULE 19.15.7.14 NMAC. For Multiple Co	ompletions: Attach wellbore diagram of
of starting any proposed work proposed completion or record		empletions: Attach wellbore diagram of
proposed completion or recor	mpletion.	
proposed completion or records. Spud 12-1/4" hole 1/15/12, drill to 4	npletion. 116. RIH & set 9-5/8'36# J55 STC csg @ 416, 0	cmt w/ 400sx (102bbl) PPC w/ additives,
proposed completion or records Spud 12-1/4" hole 1/15/12, drill to 4 no cmt to surf, just spacer gel. RII	mpletion.	cmt w/ 400sx (102bbl) PPC w/ additives,
proposed completion or records. Spud 12-1/4' hole 1/15/12, drill to 4 no cmt to surf, just spacer gel. RII BOP's @ 250# low 3000# high.	npletion. I16. RIH & set 9-5/8'36# J55 STC csg @ 416', o H temp svy, RIH w/ 1" & cmt w/ 84sx (20bbl), circ	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test
proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion and the surf, just spacer gel. RII BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4' production hole	npletion. 116'. RIH & set 9-5/8' 36# J55 STC csg @ 416', o H temp svy, RIH w/ 1" & cmt w/ 84sx (20bbl), circ to 4950' 1/29/12. Log well w/ Triple Express. F	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @
proposed completion or recompletion of recompletion of recompletion of recompletion of the surf, just spacer gel. RII BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4" production hole 4950". Cmt w/ 940sx (315bbl) PPO	npletion. I16. RIH & set 9-5/8'36# J55 STC csg @ 416', o H temp svy, RIH w/ 1" & cmt w/ 84sx (20bbl), circ	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @
proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion and the surf, just spacer gel. RII BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4' production hole	npletion. 116'. RIH & set 9-5/8' 36# J55 STC csg @ 416', o H temp svy, RIH w/ 1" & cmt w/ 84sx (20bbl), circ to 4950' 1/29/12. Log well w/ Triple Express. F	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ yes, circ 588sx (197bbl) cmt to surf. Rel
proposed completion or recompletion of recompletion of recompletion of recompletion of the surf, just spacer gel. RII BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4" production hole 4950". Cmt w/ 940sx (315bbl) PPO	npletion. 116'. RIH & set 9-5/8' 36# J55 STC csg @ 416', o H temp svy, RIH w/ 1" & cmt w/ 84sx (20bbl), circ to 4950' 1/29/12. Log well w/ Triple Express. F	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ yes, circ 588sx (197bbl) cmt to surf. Rel
proposed completion or recompletion of recompletion of recompletion of recompletion of the surf, just spacer gel. RII BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4" production hole 4950". Cmt w/ 940sx (315bbl) PPO	npletion. 116. RIH & set 9-5/8' 36# J55 STC csg @ 416, orgonerated the set 9-5/8' 36# J55 STC csg @ 416, orgonerated the set of the	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ ves, circ 588sx (197bbl) cmt to surf. Rel RECEIVED FEB 0.6 2012
proposed completion or recompletion of recompletion of recompletion of the surf, just spacer gel. RII BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4" production hole 4950". Cmt w/ 940sx (315bbl) PPORig 2/1/12.	npletion. 116. RIH & set 9-5/8' 36# J55 STC csg @ 416, orgonerated the set 9-5/8' 36# J55 STC csg @ 416, orgonerated the set of the	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ ves, circ 588sx (197bbl) cmt to surf. Rel RECEIVED FEB 0.6 2012
proposed completion or recompletion of recompletion of recompletion of the surf, just spacer gel. RII BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4" production hole 4950". Cmt w/ 940sx (315bbl) PPORig 2/1/12.	npletion. 116. RIH & set 9-5/8' 36# J55 STC csg @ 416, orgonerated the set 9-5/8' 36# J55 STC csg @ 416, orgonerated the set of the	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ yes, circ 588sx (197bbl) cmt to surf. Rel RECEIVED FEB 0.6 2012
proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion and the surf, just spacer gel. RII BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4" production hole 4950". Cmt w/ 940sx (315bbl) PPORig 2/1/12.	Rig Release Date:	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ yes, circ 588sx (197bbl) cmt to surf. Rel RECEIVED FEB 0.6 2012 NNIOCD ARTESIA
proposed completion or recompletion or recompletion or recompletion or recompletion or recompletion and the surf, just spacer gel. RII BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4" production hole 4950". Cmt w/ 940sx (315bbl) PPORig 2/1/12.	npletion. 116. RIH & set 9-5/8' 36# J55 STC csg @ 416, orgonerated the set 9-5/8' 36# J55 STC csg @ 416, orgonerated the set of the	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ yes, circ 588sx (197bbl) cmt to surf. Rel RECEIVED FEB 0.6 2012 NNIOCD ARTESIA
Spud 12-1/4' hole 1/15/12, drill to 4 no cmt to surf, just spacer gel. RII BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4' production hole 4950'. Cmt w/ 940sx (315bbl) PPORig 2/1/12. Spud Date:	Rig Release Date: RIH & set 9-5/8' 36# J55 STC csg @ 416', or temp svy, RIH w/ 1" & cmt w/ 84sx (20bbl), circle to 4950' 1/29/12. Log well w/ Triple Express. For followed by 1140sx (248bbl) PPC all w/ additions and complete to the best of my knowledge.	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ yes, circ 588sx (197bbl) cmt to surf. Rel RECEIVED FEB 0.6 2012 NNIOCD ARTESIA ge and belief.
Spud 12-1/4' hole 1/15/12, drill to 4 no cmt to surf, just spacer gel. Rll BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4' production hole 4950'. Cmt w/ 940sx (315bbl) PPORig 2/1/12. Spud Date:	Rig Release Date: Rig Regulatory Advisor_ TITLERegulatory Advisor_	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ yes, circ 588sx (197bbl) cmt to surf. Rel RECEIVED FEB 0.6 2012 NNIOCD ARTESIA ge and belief. DATE 2(3(12)
Spud 12-1/4" hole 1/15/12, drill to 4 no cmt to surf, just spacer gel. Rll BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4" production hole 4950. Cmt w/ 940sx (315bbl) PPORig 2/1/12. Spud Date: I hereby certify that the information at SIGNATURE Type or print nameDavid Stewart	Rig Release Date: RIH & set 9-5/8' 36# J55 STC csg @ 416', or temp svy, RIH w/ 1" & cmt w/ 84sx (20bbl), circle to 4950' 1/29/12. Log well w/ Triple Express. For followed by 1140sx (248bbl) PPC all w/ additions and complete to the best of my knowledge.	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ yes, circ 588sx (197bbl) cmt to surf. Rel RECEIVED FEB 0.6 2012 NNIOCD ARTESIA ge and belief. DATE 2(3(12)
Spud 12-1/4' hole 1/15/12, drill to 4 no cmt to surf, just spacer gel. Rll BOP's @ 250# low 3000# high. 1/20/12, drill 8-3/4' production hole 4950'. Cmt w/ 940sx (315bbl) PPORig 2/1/12. Spud Date:	Rig Release Date: Rig Regulatory Advisor_ TITLERegulatory Advisor_	cmt w/ 400sx (102bbl) PPC w/ additives, c 29sx (7bbl) cmt to surf. WOC. Test RIH w/ 5-1/2" 17# J55 LTC csg & set @ yes, circ 588sx (197bbl) cmt to surf. Rel RECEIVED FEB 0.6 2012 NNIOCD ARTESIA ge and belief. DATE 2(3(12) POXY.com PHONE: _432-685-5717

-

Office District I – (575) 393-6161	State of New Mexico	Form C-103
	Energy, Minerals and Natural Resources	Revised August 1, 2011
1625 N French Dr., Hobbs, NM 88240		WELL API NO.
<u>District II</u> – (575) 748-1283	OIL CONSERVATION DIVISION	30-015-22212
811 S First St , Artesia, NM 88210		5. Indicate Type of Lease
<u>District III</u> – (505) 334-6178 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis Dr.	STATE FEE
<u>District IV</u> – (505) 476-3460	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr, Santa Fe, NM		
87505	NODG AND DEDODES ON HELLS	7 7 27 27 424
	TICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
	DSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A ICATION FOR PERMIT" (FORM C-101) FOR SUCH	Anadarko Pardue Farms ANQ Com
PROPOSALS)	CATION TORTERIMIT (FORWIC-101) FOR SOCIT	8. Well Number
1. Type of Well: Oil Well	Gas Well Other	1
2. Name of Operator		9. OGRID Number
Yates Petroleum Corporation	•	025575
3. Address of Operator		10. Pool name or Wildcat
105 South Fourth Street, Artesia,	NM 88210	Indian Basin Upper Penn, Assoc.
		matan basin oppor rom, rissoc.
4. Well Location		1000
Unit Letter F :	2130 feet from the North line and	1980 feet from the West line
Section 27	Township 21S Range 24E	NMPM Eddy County
	11. Elevation (Show whether DR, RKB, RT, GR, etc.	
	3680'GR	
	3000 (1)	
12. Check A	appropriate Box to Indicate Nature of Notice,	Report or Other Data
		BSEQUENT REPORT OF:
PERFORM REMEDIAL WORK] PLUG AND ABANDON □ REMEDIAL WO	RK ☐ ALTERING CASING ☐
TEMPORARILY ABANDON	CHANGE PLANS COMMENCE DI	RILLING OPNS. 🗌 P AND A . 💮 🗌
PULL OR ALTER CASING] MULTIPLE COMPL CASING/CEMEI	NT JOB ·
DOWNHOLE COMMINGLE	_	
DOWN TOLE COMMINGEE		•
OTHER:		
13 Describe proposed or com	nleted operations. (Clearly state all pertinent details, a	and give pertinent dates, including estimated
		and give pertinent dates, including estimated
date of starting any propos	sed work). SEE RULE 19.15.7.14 NMAC. For Multip	
	sed work). SEE RULE 19.15.7.14 NMAC. For Multip	
date of starting any proposed completion or re	sed work): SEE RULE 19.15.7.14 NMAC. For Multipecompletion.	ole Completions: Attach wellbore diagram of
date of starting any proposed completion or re 1/19/12 – Tagged at 5428'. Worke	sed work): SEE RULE 19.15.7.14 NMAC. For Multipecompletion. End tubing down to 5439'. Tagged at 5436'. Milled down	ole Completions: Attach wellbore diagram of
date of starting any proposed completion or results. 1/19/12 – Tagged at 5428'. Worker RC and CT with piece of collar class.	sed work): SEE RULE 19.15.7.14 NMAC. For Multipecompletion. End tubing down to 5439'. Tagged at 5436'. Milled down many inside shoe.	ole Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of
date of starting any proposed completion or responsed completion or resulting the starting and the starting any proposed completion or resulting the starting any proposed completion or resulting any proposed complete the starting any proposed completion or resulting any proposed completion and any	sed work). SEE RULE 19.15.7.14 NMAC. For Multipecompletion. ed tubing down to 5439'. Tagged at 5436'. Milled down inside shoe. ske circulation. Milled down to 5444'. Mill shoe plugg	ole Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of
date of starting any proposed completion or responsed completion or responsed to the starting and the starting any proposed completion or response to the starting and the starting and the starting any proposed to the starting and starting any proposed to the starting and starting any proposed to the starting and	sed work): SEE RULE 19.15.7.14 NMAC. For Multipercompletion. Ed tubing down to 5439'. Tagged at 5436'. Milled down mp inside shoe. Solve circulation. Milled down to 5444'. Mill shoe plugget to 5448'.	ole Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe.
date of starting any proposed completion or responsed completion or responsed to the starting and the starting any proposed completion or response to the starting and the starting and the starting any proposed to the starting and starting any proposed to the starting and starting any proposed to the starting and	sed work). SEE RULE 19.15.7.14 NMAC. For Multipecompletion. ed tubing down to 5439'. Tagged at 5436'. Milled down inside shoe. ske circulation. Milled down to 5444'. Mill shoe plugg	ole Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of
date of starting any proposed completion or responsed completion or responsed to the starting and the starting any proposed completion or response to the starting and the starting and the starting any proposed to the starting and starting any proposed to the starting and starting any proposed to the starting and	sed work): SEE RULE 19.15.7.14 NMAC. For Multipercompletion. Ed tubing down to 5439'. Tagged at 5436'. Milled down mp inside shoe. Solve circulation. Milled down to 5444'. Mill shoe plugget to 5448'.	onle Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe.
date of starting any proposed completion or responsed completion or responsed to the starting and the starting any proposed completion or response to the starting and the starting and the starting any proposed to the starting and starting any proposed to the starting and starting any proposed to the starting and	sed work): SEE RULE 19.15.7.14 NMAC. For Multipercompletion. Ed tubing down to 5439'. Tagged at 5436'. Milled down mp inside shoe. Solve circulation. Milled down to 5444'. Mill shoe plugget to 5448'.	ole Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe.
date of starting any proposed completion or responsed completion or responsed to the starting and the starting any proposed completion or response to the starting and the starting and the starting any proposed to the starting and starting any proposed to the starting and starting any proposed to the starting and	sed work): SEE RULE 19.15.7.14 NMAC. For Multipercompletion. Ed tubing down to 5439'. Tagged at 5436'. Milled down mp inside shoe. Solve circulation. Milled down to 5444'. Mill shoe plugget to 5448'.	ole Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012
date of starting any proposed completion or responsed completion or responsed to the starting and the starting any proposed completion or response to the starting and the starting and the starting any proposed to the starting and starting any proposed to the starting and starting any proposed to the starting and	sed work): SEE RULE 19.15.7.14 NMAC. For Multipercompletion. Ed tubing down to 5439'. Tagged at 5436'. Milled down mp inside shoe. Solve circulation. Milled down to 5444'. Mill shoe plugget to 5448'.	ole Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012
date of starting any proposed completion or responsed completion or responsed completion or responsed at 5428'. Worker RC and CT with piece of collar classification of the starting and the starting and the starting and the starting any proposed complete at 5428'. Worker RC and CT with piece of collar classification at 5440'. Brown 1/23/12 – Continued milling down 1/24/12 – Set 2-7/8" L-80 tubing with the starting any proposed completion or response at 5428'. Worker RC and CT with piece of collar classification and the starting any proposed completion or response at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5440'. Brown 1/23/12 – Continued milling down 1/24/12 – Set 2-7/8" L-80 tubing with piece of collar classification at 5440'. The starting at 5440'. Brown 1/24/12 – Set 2-7/8" L-80 tubing with piece of collar classification at 5440'.	sed work): SEE RULE 19.15.7.14 NMAC. For Multiple completion. Ed tubing down to 5439'. Tagged at 5436'. Milled down inside shoe. Sie circulation. Milled down to 5444'. Mill shoe plugg to 5448'. With SN on bottom at 5265'. ND BOP.	onle Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe.
date of starting any proposed completion or responsed completion or responsed to the starting and the starting any proposed completion or response to the starting and the starting and the starting any proposed to the starting and starting any proposed to the starting and starting any proposed to the starting and	sed work): SEE RULE 19.15.7.14 NMAC. For Multipercompletion. Ed tubing down to 5439'. Tagged at 5436'. Milled down mp inside shoe. Solve circulation. Milled down to 5444'. Mill shoe plugget to 5448'.	ole Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012
date of starting any proposed completion or responsed completion or responsed completion or responsed at 5428'. Worker RC and CT with piece of collar classification of the starting and the starting and the starting and the starting any proposed complete at 5428'. Worker RC and CT with piece of collar classification at 5440'. Brown 1/23/12 – Continued milling down 1/24/12 – Set 2-7/8" L-80 tubing with the starting any proposed completion or response at 5428'. Worker RC and CT with piece of collar classification and the starting any proposed completion or response at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5440'. Brown 1/23/12 – Continued milling down 1/24/12 – Set 2-7/8" L-80 tubing with piece of collar classification at 5440'. The starting at 5440'. Brown 1/24/12 – Set 2-7/8" L-80 tubing with piece of collar classification at 5440'.	sed work): SEE RULE 19.15.7.14 NMAC. For Multiple completion. Ed tubing down to 5439'. Tagged at 5436'. Milled down inside shoe. Sie circulation. Milled down to 5444'. Mill shoe plugg to 5448'. With SN on bottom at 5265'. ND BOP.	ole Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012
date of starting any proposed completion or responsed completion or responsed completion or responsed at 5428'. Worker RC and CT with piece of collar classification of the starting and the starting and the starting and the starting any proposed complete at 5428'. Worker RC and CT with piece of collar classification at 5440'. Brown 1/23/12 – Continued milling down 1/24/12 – Set 2-7/8" L-80 tubing with the starting any proposed completion or response at 5428'. Worker RC and CT with piece of collar classification and the starting any proposed completion or response at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5428'. Worker RC and CT with piece of collar classification at 5440'. Brown 1/23/12 – Continued milling down 1/24/12 – Set 2-7/8" L-80 tubing with piece of collar classification at 5440'. The starting at 5440'. Brown 1/24/12 – Set 2-7/8" L-80 tubing with piece of collar classification at 5440'.	sed work): SEE RULE 19.15.7.14 NMAC. For Multiple completion. Ed tubing down to 5439'. Tagged at 5436'. Milled down inside shoe. Sie circulation. Milled down to 5444'. Mill shoe plugg to 5448'. With SN on bottom at 5265'. ND BOP.	ole Completions: Attach wellbore diagram of wn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012
date of starting any proposed completion or responsed completion or responsed completion or response to the starting and proposed the starting and start	sed work): SEE RULE 19.15.7.14 NMAC. For Multipercompletion. Ed tubing down to 5439'. Tagged at 5436'. Milled down principle shoe. Since circulation. Milled down to 5444'. Mill shoe plugge to 5448'. With SN on bottom at 5265'. ND BOP. Rig Release Date:	one Completions: Attach wellbore diagram of two to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESIA
date of starting any proposed proposed completion or results. 1/19/12 – Tagged at 5428'. Worker RC and CT with piece of collar classification of the start of th	sed work): SEE RULE 19.15.7.14 NMAC. For Multiple completion. Ed tubing down to 5439'. Tagged at 5436'. Milled down inside shoe. Sie circulation. Milled down to 5444'. Mill shoe plugg to 5448'. With SN on bottom at 5265'. ND BOP.	one Completions: Attach wellbore diagram of two to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESIA
date of starting any proposed completion or responsed completion or responsed completion or response to the starting and proposed the starting and start	sed work): SEE RULE 19.15.7.14 NMAC. For Multipercompletion. Ed tubing down to 5439'. Tagged at 5436'. Milled down principle shoe. Since circulation. Milled down to 5444'. Mill shoe plugge to 5448'. With SN on bottom at 5265'. ND BOP. Rig Release Date:	one Completions: Attach wellbore diagram of two to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESIA
date of starting any proposed proposed completion or results. 1/19/12 – Tagged at 5428'. Worker RC and CT with piece of collar classification of the start of th	sed work): SEE RULE 19.15.7.14 NMAC. For Multipercompletion. Ed tubing down to 5439'. Tagged at 5436'. Milled down amp inside shoe. See circulation. Milled down to 5444'. Mill shoe plugg to 5448'. Fifth SN on bottom at 5265'. ND BOP. Rig Release Date:	onle Completions: Attach wellbore diagram of what to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESIA
date of starting any proposed proposed completion or results. 1/19/12 – Tagged at 5428'. Worker RC and CT with piece of collar classification of the start of th	sed work): SEE RULE 19.15.7.14 NMAC. For Multipercompletion. Ed tubing down to 5439'. Tagged at 5436'. Milled down amp inside shoe. See circulation. Milled down to 5444'. Mill shoe plugg to 5448'. Fifth SN on bottom at 5265'. ND BOP. Rig Release Date:	one Completions: Attach wellbore diagram of two to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESIA
date of starting any proposed proposed completion or results. 1/19/12 – Tagged at 5428'. Worker RC and CT with piece of collar classification of the start of th	Rig Release Date: Rig Regulatory Compliance TITLE Regulatory Compliance Rown work): SEE RULE 19.15.7.14 NMAC. For Multiper Second Proceedings of the Second Proceedings of	ole Completions: Attach wellbore diagram of vn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESIA
date of starting any proposed proposed completion or results. 1/19/12 – Tagged at 5428'. Worker RC and CT with piece of collar classification of the start of th	Rig Release Date: Rig Release Date: TITLE Regulatory Compliance of Multiple Complex	ole Completions: Attach wellbore diagram of vn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESIA
date of starting any proposed proposed completion or results. 1/19/12 – Tagged at 5428'. Worker RC and CT with piece of collar classification of the start of th	Rig Release Date: Rig Regulatory Compliance TITLE Regulatory Compliance Rown work): SEE RULE 19.15.7.14 NMAC. For Multiper Second Proceedings of the Second Proceedings of	ole Completions: Attach wellbore diagram of vn to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESIA
date of starting any propose proposed completion or results. The state Use Only	Rig Release Date: Rig Release Date: TITLE Regulatory Compliance and address: tinah@yatespetrole	role Completions: Attach wellbore diagram of two to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESI dige and belief. ce-Supervisor DATE February 3, 2012 im.com PHONE: 575-748-4168
date of starting any proposed proposed completion or results. 1/19/12 – Tagged at 5428'. Worker RC and CT with piece of collar classification of the start of th	Rig Release Date: Rig Release Date: TITLE Regulatory Compliance and address: tinah@yatespetrole	role Completions: Attach wellbore diagram of two to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESI dige and belief. ce-Supervisor DATE February 3, 2012 im.com PHONE: 575-748-4168
date of starting any propose proposed completion or results. The state Use Only	Rig Release Date: Rig Regulatory Compliance TITLE Regulatory Compliance Rown work): SEE RULE 19.15.7.14 NMAC. For Multiper Second Proceedings of the Second Proceedings of	role Completions: Attach wellbore diagram of two to 5440', shoe plugged. Hade 3' plug of ged off. Cleaned out shoe. RECEIVED FEB 0.6 2012 NMOCD ARTESI dige and belief. ce-Supervisor DATE February 3, 2012 im.com PHONE: 575-748-4168