Form 3160-5 (August 2307)

## **UNITED STATES** DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

O<sub>CD</sub><sub>Artesia</sub>

FORM APPROVED OMB NO. 1004-0135 10

	Expires:		
ease S	erial No.		

-	SUNDRY N	OTICES AN	D REPORT	rs on w	ELLS
	Do not use this:				
â	bandoned well.	Use form 31	60-3 (APD)	for such	proposals.

NMNM104661				
7	If Indian	Allottee or Tribe Name		


Do not uso thi	e form for proposale to	drill or to ro-	ontor an		1			
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRI	PLICATE - Other instruc	tions on rev	erse side.		7. If Unit or CA/Agr NMNM120212		Name and/or No.	
1. Type of Well				8. Well Name and N TRINITY 20 FEI	o. DERAL (	COM 2		
Oil Well Gas Well Oth  Name of Operator		TERRI STATI	JEM		9. API Well No.			
CIMAREX ENERGY COMPAN	NY OF C@-Mail: tstathem@	cimarex.com			30-015-34500	-00-S1		
3a. Address 600 NORTH MARIENFELD STREET SUITE 600 Ph: 432 MIDLAND, TX 79701			(include area co 0-1936	ode)		10. Field and Pool, or Exploratory COTTONWOOD DRAW		
Sec 20 T25S R26E NWSW 1980FSL 660FWL		RE	CEIVE	EDI	11. County or Parisl	n, and Sta	nte	
			NOV 1 9 2012		EDDY COUNT	EDDY COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICAME	DEAD LARE D	<b>ESIGN</b>	CE, REPORT, OR OTH	ER DA	TA	
TYPE OF SUBMISSION			ТҮРЕ	OF ACTI	ION			
- Natice of Intent	Acidize	□ Deep	en	□Р	roduction (Start/Resume)		Water Shut-Off	
Notice of Intent	☐ Alter Casing	□ Frac	ture Treat		Leclamation	'	Well Integrity	
☐ Subsequent Report	Casing Repair	□ New	Construction	_ ⊠ R	Lecomplete		Other	
Final Abandonment Notice	☐ Change Plans	□ Plug	and Abandon		emporarily Abandon			
	Convert to Injection	□ Plug	Back	□ <sup>v</sup>	Vater Disposal			
Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for formarex Energy respectfully r Wolfcamp/Cisco (DHC) per the The BLM approved October 3 attempt was made to complet history attached for daily active Due to the fish in the hole @ Wolfcamp/Cisco as follows:	l operations. If the operation re- bandonment Notices shall be fil inal inspection.)  request approval to comple ie procedure below.  7, 2011 a NOI to abandon e the well in the Wolfcam rity of Wolfcamp completion	sults in a multipled only after all rete the Trinity the Morrow a p as approveon. (Sundry file	e completion or requirements, inc v 20 Federal ( and complete d by the BLM ed 9/13/12)	recompletic cluding rec Com #2 v in the Wo	on in a new interval, a Forth 3 lamation, have been complete well in the olfcamp. An	160-4 shed, and the	all be filed once e operator has	
Cisco is OH @ 10001-10950' 1. Perf Wolfcamp @ 9164-96	632' w/ 3 JSPF @ 120 deg	g phasing,114	holes.	A	Accepted for re-	-05	_	
14. I hereby certify that the foregoing is  Con  Name (Printed/Typed) TERRI ST	# Electronic Submission For CIMAREX ENE nmitted to AFMSS for proc	RGY COMPA	NY OF CO, se RT SIMMONS (	nt to the ( on 09/20/2	Carlsbad	11/24	ING.	
Signature (Electronic	Submission)		Date 09/1:	3/2012				
	THIS SPACE FO	OR FEDERA	L OR STAT	E OFFI	CE USE			
Approved By REJECT	ED		WESLE TitlePETRO	Y INGRA		•	Date 11/15/201	
Conditions of approval, if any, are attached the conditions of applicant holds legal or equivalent would entitle the applicant to conditions.	uitable title to those rights in the		Office Carls	bad				
			<u> </u>					


## Additional data for EC transaction #150041 that would not fit on the form

## 32. Additional remarks, continued

2. Acid & frac perfs down 7" csg per recommendation.
3. Drill out CBPs. CO.
4. RU WL. TIH w/ 10K pkr w/ on-off tool & pump out plug (pinned for 7500 psi BHP) in place & set @ +/- 9050'. RD.
5. Turn well to production.

Current & proposed WBD is attached. DHC permit pending approval.





## Trinity 20 Federal #2 WO History

Attachment to 3160-5 Subsequent Recomplete to Wolfcamp 3001534500

- 9/30/2011 MIRU Pulling Unit. Killed well, Tried to release pkr for 3 hours w/o success.
- 10/1/2011 Worked pkr for 2 hours and release. TOOH w/ pkr & tbg
- 10/5/2011 Set CIBP @ 11400'. TIH w/ tbg and spot 25 sx cmt plug on top of CIBP Abandoning Morrow.
- 10/6/2011 Ran GR to 10880'. Ran Chem cutter and cut 4-1/2" csg @ 10800'. RD WL. Ran spear and could not latch on to liner. TOOH w/ tools
- 10/7/2011 TIH w/ spear and caught liner. Pulled 80K and did not move liner. Pulled 90K and jarred for 2 hours still no movement. Pulled 100K and jarred for 2 hrs moving 8'. Pulled 105K and had a little more movement. Jarred and moved 17' before parting tbg at surface. Moved a total of 37'.
- 10/10/2011 RIH w/ OS and caught fish. Worked for 3 hrs w/ no progress. RU power swivel jarred and work for 3 hrs w/ no progress.
- 10/11/2011 Attempted to back off tbg at bumper sub. Pulled 56K and tbg parted. TOOH w/tbg. WO new grapple. Ran grapple and tagged at 47'. Latched on to fish and backed off tbg @ 9636'. TOOH to OS and LD OS. Started OOH w/tbg.
- 10/12/2011 Finished TOOH w. tbg. LD tbg. PU 2-7/8" tbg and start in hole w/ jars
- 10/13/2011 FIH w/ jars and tagged @ 9590'. Latched on to fish and worked to 110K max pull w/ no movement
- 10/14/2011 RU swivel and work 1700 psi RH torq into string while pulling 80K and bumping down on fish to release spear. Worked 2 hrs & can not set off jars w/ swivel.
- 10/15/2011 RU csg jacks and worked fish to 140K. Saw about 12" movement and stopped moving. Beat down on fish w/ rig from 100K to 70K. Pulled 150K w/ csg jacks w/ no movement. Pulled 160K and saw 12" movement and stopped. Continued to work jacks w/ 160K and additional movement. Pump down tbg to try to circ around fish. Took 4 bbls to load. Pumped 9.5 bbls and pressured up to 2000 psi. Let pressure bleed of to 1000 psi w/ no action on backside. Pumped down tbg while pulling 100K w/ rig and 140K & 160K w/ csg jacks w/ no movement. Pumped total of 20 bbls down tbg. Pumped 22.5 bbls down csg and loaded csg. Pressure backside to 3000 psi and pulled 160K w/ no movement and circ up tbg. Moved fish a total of 2'. Leaves 4-1/2" pkr @ 9640'. RD Pulling unit
- 10/18/2011 RU new Pulling unit and worked fish up to 167K and using bumper sub to beat down fish. Worked fish for 2 hrs and moved fish 2". Tie on to tbg and pumped down tbg at 0.5 BPM @ 2500 psi while working tbg from 167K to 90K. Gained 2" movement in fish. Bled off pressure and tied on to csg. Pressured csg to 3000 psi and saw no indication of circ on tbg. SDON
- 10/19/2011 RU wireline and backed off tbg at stop sub. TOOH w/ tbg and tools. Left stop sub, x-over, 3-1/8" DC, DC sub, x-over, and spear in hole. Start in hole w/ mill to drill up stop sub. TOF @ 9638'.
- 10/20/2011 SITP 80 psi. Blew dead in 20 secs. FIH w/ mill hitting tight spot @ 9627', but took less than a point to drop through. Set down @ 9630'. Worked tbg w/ swivel from 9615' to 9630' w/ swivel stalling each time @ 9627', but taking less than a point to drop through. Worked tight spot for 2 hrs w/ no show of metal in returns and blew hydraulic hose. SDON.

- 10/21/2011 SITP 175 psi. Blew dead in 15 secs. Worked through tight spot one time and then did not have any problems. Tagged fish @ 9638'. Milled on stop sub and made 3" in 30 min then slowed down. Returns showed good metal shavings.

  Made an additional 0.5" for a total of 3.5" for the day. TOOH w/ mill
- 10/22/2011 SITP 0 psi. RIH w/ new mill and tagged @ 9638'. Started milling, made 12" in 1st hour and 2" in 2nd hour. Made no hole in 3rd hour. TOOH w/ mill.
- 10/23/2011 SITP 0 psi. RIH w/ new mill and tagged @ 9639.5'. Started milling and didn't make much progress in 1st half hour. Pressure then went to 300 psi and started making hole. Returns showed good metal shavings and about 30% black scale. After 1 hr, scale slowed to an ocassional showing, but still getting good metal returns.. After 4 hrs, still getting metal returns, but much smaller pieces. Total cut today 3'. TOF @ 9642.5'. TOOH w/ mill. Found 2.55' piece of tie back sleeve jammed in shoe (explains increased pump pressure). Shoe was worn out and OD of face cracked. SDFWE.
- 10/25/2011 SITP 60 psi. Blew dead in 45 secs. Ran impression block which showed 1/2 of tie back sleeve looking up w/ 4-1/2" OD. TIH w/ 6-1/8" concave mill. SDON.
- 10/26/2011 SITP 100 psi. Blew dead in 45 secs. FIH and tag fish @ 9640'. Started milling Made 2.5' in 1st hour, after 1st hour rate slowed and quit making hole. Circ out gas. After 350 bbls gone, still had gas at surface. PU and shut down pump and still flowing. SIW and SITP increased to 250 psi in 15 min. Circ hole w/ prod wtr, SD pump and still bring gas to surface. Leave EOT @ 9615 & SDON
- 10/27/2011 SITP 1300 psi. Open tbg to tank and bled down to 900 psi before unloading fluid. Opened csg to tank and bled to 700 psi before unloading fluid. Pumped 60 bbls brine down tbg to kill tbg. RU flowback iron and opened tbg on 12/64" choke. Tbg still dead and csg @ 600 psi and climbing. SDON. Will monitor pressures and flow through the night. Well SI pending engineering evaluation and procedure approval from BLM.