Sub-mit I Way To Appropriate District		
Submit 1 Try To Appropriate District	State of New Mexico	Form C-103
Office District 1 – (575) 393-6161 Energy, N	Minerals and Natural Resources	Revised July 18, 2013
1625 N. French Dr., Hobbs, NM 88240	•	WELL API NO.
District II – (575) 748-1283 OIL CC	INSERVATION DIVISION	30-015-36029
611 3. 1 list St., Altesia, 1411 66210	20 South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE
District (cos) c	Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		·
SUNDRY NOTICES AND REP	ORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL C		Corsair State Com
DIFFERENT RESERVOIR. USE "APPLICATION FOR PER	MIT" (FORM C-101) FOR SUCH	Coronia State Com
PROPOSALS.)		8. Well Number 1
	Other	
2. Name of Operator		9. OGRID Number
COG Operating LLC		229137
3. Address of Operator		10. Pool name or Wildcat
One Concho Center, 600 W. Illinois Ave, Midland	, TX 79701	Wildcat; Wolfcamp (Gas) 97489
4. Well Location		
	from the North line and 66	feet from the East line
Section 2 Township		NMPM County: Eddy
	(Show whether DR, RKB, RT, GR, etc.	
3627' GR		
•		
12. Check Appropriate B	Sox to Indicate Nature of Notice,	Report or Other Data
		r
NOTICE OF INTENTION T	O: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐ PLUG AND A	BANDON 🗌 📗 REMEDIAL WOR	RK
TEMPORARILY ABANDON (CHANGE PLA	ANS 🗍 COMMENCE DR	ILLING OPNS. P AND A
PULL OR ALTER CASING MULTIPLE C	_	
DOWNHOLE COMMINGLE	ONNIE ONONINO/OLIVIEN	11 30B
	•	
CLOSED-LOOP SYSTEM CTUER	· Mark	
OTHER: Abandon Penn Shale, Recomplete		
13. Describe proposed or completed operations		
of starting any proposed work) SEE RIII		
	E 19.15./.14 NMAC. For Multiple Co	mpletions: Attach wellbore diagram of
proposed completion or recompletion.	E 19.15./.14 NMAC. For Multiple Co	mpletions: Attach wellbore diagram of
proposed completion or recompletion.		
proposed completion or recompletion. COG Operating respectfully request to abandon the		
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU		fcamp for the Corsair State Com #1.
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary.		
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU		fcamp for the Corsair State Com #1.
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary.		fcamp for the Corsair State Com #1.
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP.		fcamp for the Corsair State Com #1.
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement		RECEIVED SEP 0 4 2013
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run		fcamp for the Corsair State Com #1.
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi	Penn Shale and recomplete to the Wol	RECEIVED SEP 0 4 2013 NMOCD ARTESIA
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10	Penn Shale and recomplete to the Wol	RECEIVED SEP 0 4 2013
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 16 utilizing Halliburton openhole log dated 6/6	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09.	RECEIVED SEP 0 4 2013 NMOCD ARTESIA
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/6 9) TIH w/tubing & packer. Packer to include	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 09/09. on/off & profile nipple.	RECEIVED SEP 0 4 2013 NMOCD ARTESIA
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950'	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. on/off & profile nipple.	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. on/off & profile nipple.	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950'	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. on/off & profile nipple.	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 09/09. on/off & profile nipple. Cl at 3 – 5 BPM. Drop 50 balls throug	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing shout the job. Have 500 psi on backside during
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 09/09. on/off & profile nipple. Cl at 3 – 5 BPM. Drop 50 balls throug	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing shout the job. Have 500 psi on backside during
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. 209/09	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing whout the job. Have 500 psi on backside during
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. 209/09	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing whout the job. Have 500 psi on backside during
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. 209/09	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing whout the job. Have 500 psi on backside during
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. 209/09	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing whout the job. Have 500 psi on backside during
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 09/09. on/off & profile nipple. Cl at 3 – 5 BPM. Drop 50 balls through the based upon 24 hr. d complete to the best of my knowleds	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing thout the job. Have 500 psi on backside during test. ge and belief.
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job COA: Classification of well will I hereby certify that the information above is true and the set of the set	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. 209/09	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing thout the job. Have 500 psi on backside during test. ge and belief.
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job COA: Classification of well will I hereby certify that the information above is true and SIGNATURE	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. on/off & profile nipple. Cl at 3 – 5 BPM. Drop 50 balls through d complete to the best of my knowledge TITLERegulatory Analyst	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing shout the job. Have 500 psi on backside during test. ge and belief. DATE _9/3/13
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job COA: Classification of well will I hereby certify that the information above is true and SIGNATURE Type or print name Brian Maiorino	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 09/09. on/off & profile nipple. Cl at 3 – 5 BPM. Drop 50 balls through the based upon 24 hr. d complete to the best of my knowleds	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing thout the job. Have 500 psi on backside during test. ge and belief. DATE _9/3/13
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job COA: Classification of well will I hereby certify that the information above is true and SIGNATURE	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. on/off & profile nipple. Cl at 3 – 5 BPM. Drop 50 balls through d complete to the best of my knowledge TITLERegulatory Analyst E-mail address: _bmaiorino@com	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing whout the job. Have 500 psi on backside during test. Be and belief. DATE _9/3/13 cho.com PHONE: _432-221-0467
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job COA: Classification of well will I hereby certify that the information above is true and SIGNATURE Type or print name Brian Maiorino For State Use Only	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. on/off & profile nipple. Cl at 3 – 5 BPM. Drop 50 balls through d complete to the best of my knowledge TITLERegulatory Analyst E-mail address: _bmaiorino@con	SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing whout the job. Have 500 psi on backside during test. ge and belief. DATE 9/3/13 cho.com PHONE: 432-221-0467
proposed completion or recompletion. COG Operating respectfully request to abandon the 1) MIRU 2) Kill well if necessary. 3) Remove wellhead & install BOP. 4) Pull tubing and packer 5) Make a bit and scraper run 6) Set a CIBP @ 10280' w/35' of cement 7) Pressure test casing to 7500 psi 8) Perforate Wolfcamp @ 10147 (6 Holes), 10 utilizing Halliburton openhole log dated 6/0 9) TIH w/tubing & packer. Packer to include 10) Spot acid across perfs. Set packer at 9950' 11) Acidize zone with 3000 gallons 15% NE H job COA: Classification of well will I hereby certify that the information above is true and SIGNATURE Type or print name Brian Maiorino	Penn Shale and recomplete to the Wol 2090 (8 holes), 10066 (10 holes), 1004 209/09. on/off & profile nipple. Cl at 3 – 5 BPM. Drop 50 balls through d complete to the best of my knowledge TITLERegulatory Analyst E-mail address: _bmaiorino@com	RECEIVED SEP 0 4 2013 NMOCD ARTESIA 0 (8 holes), 10027 (8 holes), w/120° phasing whout the job. Have 500 psi on backside during test. Be and belief. DATE _9/3/13 cho.com PHONE: _432-221-0467

- 12) Shut-in 1 hour & flow back
- 13) Swab well to determine if well should be fraced.
- 14) If well warrants frac, pull tubing and packer.
- 15) Install frac valve and frac well.
- 16) Flow back until dead
- 17) TIH w/tubing and check for sand. TOH
- 18) TIH w/tubing and gas lift equipment
- 19) Tree up wellhead
- 20) Place well on test

^{*}Operations will be conducted using a closed loop system.

District 1
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720
District III
811 S. First St., Artesia, NM 88210
Phone: (575) 748-1283 Fax: (575) 748-9720
District III
1000 Rio Brazos Road, Aztec, NM 87410
Phone: (505) 334-6178 Fax: (505) 334-6170
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505
Phone: (505) 476-3460 Fax: (505) 476-3462

State of New Mexico Energy, Minerals & Natural Resources Department OIL CONSERVATION DIVISION 1220 South St. Francis Dr. Santa Fe, NM 87505

Form C-102 Revised August 1, 2011 Submit one copy to appropriate District Office

☐ AMENDED REPORT

Date

Brian Maiorino

Date of Survey

Certificate Number

bmaiorino@concho.com

Signature and Seal of Professional Surveyor:


**SURVEYOR CERTIFICATION
I hereby certify that the well location shown on this
plat was plotted from field notes of actual surveys
made by me or under my supervision, and that the
same is true and correct to the best of my belief.

WELL LOCATION AND ACREAGE DEDICATION PLAT

				CAII	ON AND AC			ATIONTE	7.1		
1,	API Numbe	er ² Pool Code ³ Pool Name					me				
30-015-30	97489 Wildcat; Wolfcamp (Gas)			97489			Wildcat; Wolfcamp (Gas)				
⁴ Property (4 Property Code		⁵ Property Name						6 W	ell Number	
36930		Corsair State Com					Corsair State Com		1		
7 OGRID	No.	8 Operator Name						8 Operator Name 9 Eleva		Elevation	
229137		COG Operating LLC						3627	, *		
					" Surface	Location			•	•	
UL or lot no.	Section	Township	Range	Lot I	dn Feet from th	e North/	South line	Feet from the	East/V	Vest line	County
1	2	19S	31E		660	North		660	East		Eddy
	·		" Bo	ttom H	lole Location	If Differer	nt From	1 Surface	<u> </u>		
UL or lot no.	Section	Township		Lot I	· , · · · · · · · · · · · · · · · · · ·		South line	Feet from the	East/V	Vest line	Count
² Dedicated Acres	s ¹³ Joint o	r Infill	14 Consolidation	Code 15	Order No.	1					
319.79											
No allowable v livision.	will be ass	signed to	this comple	tion unti	l all interests have	e been cons	olidated	or a non-standa	rd unit has	been app	roved by the
16	-					660'	\downarrow	-			FICATION herein is true and comp
							- 4	•		•	t this organization eithe
									_		terest in the land includ
							(560' II · · ·			ht to drill this well at this of such a mineral or wor
								li -			r a compulsory pooling
								lli i	ore entered by the d		
								 7	V).		
								5 _	'/\		8/28/13

Author:	Stroup		
Well Name	Corsair St Com	Well No.	#1
Field	Shugart: Morrow	API#:	30-015-36029
County	Eddy	Prop #:	
State	New Mexico	Zone:	Penn Shale
Date	8/23/2013		
GL	3627'		
кв	3644'		


Description	0	.D.	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	13	3/8	J55	54.4	828	700	Surface
Inter Csg	9	5/8	J55	36	2,988	875	Surface
Prod Csg	5	1/2	P110	17	12,168	1,750	1900'
Liner							



TD @ 12169

Author:	Stroup		
Well Name	Corsair St Com	Well No.	#1
Field	Shugart: Morrow	API#:	30-015-36029
County	Eddy	Prop #:	
State	New Mexico	Zone:	Wolfcamp
Date	8/23/2013		
GL	3627'		
кв	3644'		

Description	O.D.	Grade	Weight	Depth	Cmt Sx	тос
Surface Csg	13 3/8	J55	54.4	828	700	Surface
Inter Csg	9 5/8	J55	36	2,988	875	Surface
Prod Csg	5 1/2	P110	17	12,168	1,750	1900'
Liner						



TD @ 12169