

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED

JAN 16 2014

Form C-141
Revised October 10, 2003

NMOC DARTESIA
District Office in
accordance with 19.15.29 NMAC

Release Notification and Corrective Action

NM 1407029586

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: Linn Operating 269324	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No.: 575-738-1739
Facility Name: Turner A #39	Facility Type: Oil

Surface Owner: Federal	Mineral Owner:	API No.: 30-015-28770
------------------------	----------------	-----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	18	17S	31E	1310	South	2300	West	Eddy

Latitude: 32.8308687811363 Longitude: -103.909398556665

NATURE OF RELEASE

Type of Release: Produced Water / Oil	Volume of Release: 6 bbls / 15gal	Volume Recovered: 3 bbls / 10gal
Source of Release: Broken bridle. Well head tubing and casing flowline connections	Date and Hour of Occurrence: 11/06/2013 6:30am	Date and Hour of Discovery: 11/06/2013 6:30am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Burton- BLM Mike Bratcher-NM OCD	
By Whom? Brian Wall	Date and Hour 11/06/2013 1010	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*:

Describe Cause of Problem and Remedial Action Taken.*: received call at 6:30am that well had broken bridle and had cause flow lines to be separated from well head. Had gang put in valves to prevent any further spills. Spill was mostly water some oil present. Water spilled was approx 6 bbls. Oil spilled was approx 15 gallons.

Describe Area Affected and Cleanup Action Taken.*: spray to the north of well head and flowing leak to the south and east of well head. Approx 6 bbls fluid on ground. Had vacuum truck pick up what they were able. Recovered about 3 or 4 barrels of fluid.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Brian Wall</i>	OIL CONSERVATION DIVISION	
Printed Name: Brian Wall	Signed By: <i>Mike Bratcher</i> Approved by District Supervisor:	
Title: Construction Foreman II	Approval Date: MAR 10 2014	Expiration Date:
E-mail Address: bwall@linenergy.com	Conditions of Approval: Remediation	Attached <input type="checkbox"/>
Date: 11/12/2013 Phone: 806-367-0645		

* Attach Additional Sheets If Necessary

per NMOCD Rules & Guidelines 2RP-2148