

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

nHMP1408631594

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Devon Energy	<i>6137</i>	Contact Jaime Castillo
Address PO Box 250 Artesia, NM 88211		Telephone No. 575- 748-5502
Facility Name Antares 23 Federal 2H		Facility Type Oil Well

Surface Owner Federal	Mineral Owner Federal	API No. 3001541106
------------------------------	------------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter D	Section 23	Township 19S	Range 31E	Feet from the 180	North/South Line FNL	Feet from the 225	East/West Line FWL	County Eddy
-------------------------	----------------------	------------------------	---------------------	-----------------------------	--------------------------------	-----------------------------	------------------------------	-----------------------

Latitude: Longitude:

NATURE OF RELEASE

Type of Release Spill	Volume of Release 20bbls	Volume Recovered 15bbls
Source of Release flow line rupture	Date and Hour of Occurrence 3/18/14 5:45PM	Date and Hour of Discovery 3/18/14 5:45PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? John Barnett-Lease Operator	
By Whom? Eric Lopez- Night Lease Operator	Date and Hour 3/18/14 6:00PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*

Surge in pressure caused a rupture in the flow line resulting in a spill of 20bbls of produced fluid; oil and water. Flow line has been repaired and efforts will be made to ensure Murphy switches are set at correct pressure.

RECEIVED
MAR 20 2014
NMOCD ARTESIA

Describe Area Affected and Cleanup Action Taken.*

The area affected was approximately 70'x70' on the NE side of the facility near the pump jack. 15 bbls of spilled fluid were recovered by vac truck services the same day of the incident. After a representative from the Bureau of Land Management (BLM) analyzes the effects of the spill the affected soil will be removed and replaced. Talon LPE will complete soil sampling if deemed necessary by the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: *Sandra Farley*

Printed Name: **Sandra Farley**

Title: **Field Admin Support**

E-mail Address: **Sandy.Farley@dvn.com**

Date: **3.20.14**

Phone: **575.746.5587**

OIL CONSERVATION DIVISION

Approved by Environmental Specialist: *[Signature]*

Approval Date: **3/27/14**

Expiration Date: **NA**

Conditions of Approval:

Attached ☐

Remediation per OCD Rule &
Guidelines. **SUBMIT REMEDIATION**
PROPOSAL NO LATER THAN:
4/27/14

2RP- 2228

* Attach Additional Sheets If Necessary